

Page 1 of 2

EXECUTIVE SUMMARY - ENFORCEMENT MATTER
DOCKET NO.: 2010-1450-AIR-E TCEQ ID: RN100225945 CASE NO.: 40329
RESPONDENT NAME: The Dow Chemical Company

ORDER TYPE:		
<input checked="" type="checkbox"/> 1660 AGREED ORDER	<input type="checkbox"/> FINDINGS AGREED ORDER	<input type="checkbox"/> FINDINGS ORDER FOLLOWING SOAH HEARING
<input type="checkbox"/> FINDINGS DEFAULT ORDER	<input type="checkbox"/> SHUTDOWN ORDER	<input type="checkbox"/> IMMINENT AND SUBSTANTIAL ENDANGERMENT ORDER
<input type="checkbox"/> AMENDED ORDER	<input type="checkbox"/> EMERGENCY ORDER	
CASE TYPE:		
<input checked="" type="checkbox"/> AIR	<input type="checkbox"/> MULTI-MEDIA (check all that apply)	<input type="checkbox"/> INDUSTRIAL AND HAZARDOUS WASTE
<input type="checkbox"/> PUBLIC WATER SUPPLY	<input type="checkbox"/> PETROLEUM STORAGE TANKS	<input type="checkbox"/> OCCUPATIONAL CERTIFICATION
<input type="checkbox"/> WATER QUALITY	<input type="checkbox"/> SEWAGE SLUDGE	<input type="checkbox"/> UNDERGROUND INJECTION CONTROL
<input type="checkbox"/> MUNICIPAL SOLID WASTE	<input type="checkbox"/> RADIOACTIVE WASTE	<input type="checkbox"/> DRY CLEANER REGISTRATION
<p>SITE WHERE VIOLATION(S) OCCURRED: Dow Texas Operations Freeport, 2301 North Brazosport Boulevard, Freeport, Brazoria County</p> <p>TYPE OF OPERATION: Power generation plant</p> <p>SMALL BUSINESS: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p> <p>OTHER SIGNIFICANT MATTERS: There are no complaints. There are three additional pending enforcement actions regarding this facility location, Docket Nos. 2011-0051-AIR-E, 2010-1781-AIR-E, and 2010-1279-AIR-E.</p> <p>INTERESTED PARTIES: No one other than the ED and the Respondent has expressed an interest in this matter.</p> <p>COMMENTS RECEIVED: The <i>Texas Register</i> comment period expired on March 21, 2011. No comments were received.</p> <p>CONTACTS AND MAILING LIST: TCEQ Attorney/SEP Coordinator: Mr. Phillip Hampsten, SEP Coordinator, Enforcement Division, MC 219, (512) 239-6732 TCEQ Enforcement Coordinator: Ms. Heather Podlipny, Enforcement Division, Enforcement Team 4, MC 149, (512) 239-2603; Ms. Laurie Eaves, Enforcement Division, MC 219, (512) 239-4495 Respondent: Ms. Fran Falcon, EH&S Leveraged Delivery Leader, The Dow Chemical Company, 2301 North Brazosport Boulevard, Freeport, Texas 77541 Ms. Laura Ambrose, Responsible Care Leader, The Dow Chemical Company, 2301 North Brazosport Boulevard, Freeport, Texas 77541 Respondent's Attorney: Not represented by counsel on this enforcement matter</p>		

VIOLATION SUMMARY CHART:

VIOLATION INFORMATION	PENALTY CONSIDERATIONS	CORRECTIVE ACTIONS TAKEN/REQUIRED
<p>Type of Investigation: <input type="checkbox"/> Complaint <input checked="" type="checkbox"/> Routine <input type="checkbox"/> Enforcement Follow-up <input type="checkbox"/> Records Review</p> <p>Date(s) of Complaints Relating to this Case: None</p> <p>Date of Investigation Relating to this Case: September 1, 2010</p> <p>Date of NOV/NOE Relating to this Case: August 23, 2010 (NOE)</p> <p>Background Facts: This was a routine investigation.</p> <p>AIR</p> <p>1) Failed to submit an application for renewal prior to the expiration of a permit and continued to operate without authorization after the permit expired. Specifically, the Respondent failed to renew Standard Permit Registration No. 43417 for the wet compression equipment before the permit expiration date of February 16, 2010 [30 TEX. ADMIN. CODE § 116.110(a) and TEX. HEALTH & SAFETY CODE §§ 382.0518(a) and 382.085(b)].</p> <p>2) Failed to submit an application for renewal prior to expiration of a permit and continued to operate without authorization after the permit expired. Specifically, the Respondent failed to renew New Source Review ("NSR") Permit No. 9046 for the Power 6 Westinghouse Gas Turbines before the permit expiration date of July 21, 2010 [30 TEX. ADMIN. CODE § 116.110(a) and TEX. HEALTH & SAFETY CODE §§ 382.0518(a) and 382.085(b)].</p>	<p>Total Assessed: \$96,975</p> <p>Total Deferred: \$19,395 <input checked="" type="checkbox"/> Expedited Settlement <input type="checkbox"/> Financial Inability to Pay</p> <p>SEP Conditional Offset: \$38,790</p> <p>Total Paid to General Revenue: \$38,790</p> <p>Compliance History Classifications: Person/CN - Average Site/RN - Average</p> <p>Major Source: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>Applicable Penalty Policy: September 2002</p>	<p>Corrective Actions Taken:</p> <p>The Executive Director recognizes that, by September 30, 2010, the Respondent implemented an electronic system for environmental health and safety management to review upcoming permit renewal deadlines so permit renewals will not be overlooked in the future.</p> <p>Ordering Provisions:</p> <p>1) The Order will require the Respondent to implement and complete a Supplemental Environmental Project ("SEP"). (See SEP Attachment A)</p> <p>2) The Order will also require the Respondent to:</p> <p>a. Immediately upon the effective date of this Agreed Order, until such time authorization to operate is obtained, comply with the provisions in expired Standard Permit Registration No. 43417 and NSR Permit No. 9046;</p> <p>b. Within 15 days after the effective date of this Agreed Order, submit an administratively complete permit application for the wet compression equipment and the Power 6 Westinghouse Gas Turbines;</p> <p>c. Respond completely and adequately to all requests for information concerning the permit application within 30 days after the date of such requests, or by any other deadline specified in writing; and</p> <p>d. Within 180 days after the effective date of this Agreed Order, submit written certification that authorization to operate a source of air emissions has been obtained or that operation has ceased until such time that appropriate authorization is obtained.</p>

Additional ID No(s): Air Account BLo082R

Attachment A
Docket Number: 2010-1450-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent: The Dow Chemical Company

Penalty Amount: Seventy-Seven Thousand Five Hundred Eighty Dollars (\$77,580)

SEP Offset Amount: Thirty-Eight Thousand Seven Hundred Ninety Dollars (\$38,790)

Type of SEP: Pre-approved

Third-Party Recipient: Brazoria County – *Brazoria County Vehicle and Equipment Program*

Location of SEP: Brazoria County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative Penalty Amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Offset Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Recipient named above. The contribution will be used by **Brazoria County** for the *Brazoria County Vehicle and Equipment Program* as set forth in an agreement between the Third-Party Recipient and the TCEQ. The Third-Party Recipient shall use SEP Funds to: 1) retire current diesel powered or gasoline-powered vehicles and equipment and replace those vehicles and equipment with alternative-fueled or low-emission vehicles or equipment; 2) convert current vehicles and equipment to alternative-fueled vehicles or equipment; or 3) retrofit current gasoline-powered and diesel-powered vehicles and equipment to decrease emissions from those sources. *SEP Funds may only be used for: 1) the incremental costs of purchase of alternative-fueled or lower emission vehicles or equipment or retrofit of existing vehicles or equipment; 2) the incremental cost of purchase of alternative fuels versus regular gasoline or diesel fuels; or 3) other direct expenses authorized in advance and in writing by TCEQ.*

Retirement of Vehicles. The Third-Party Recipient shall submit proof that any purchase of new vehicles or equipment using SEP Funds meets current EPA low-emission standards. The Third-Party Recipient shall ensure that equipment and vehicles being retired are operational and that vehicles have current registration stickers. The retired vehicles and equipment must not be resold for any use except scrap value. The engine and exhaust system, including the catalytic

converter, must be destroyed. The Third-Party Recipient shall submit proof of registration, decommissioning, and scrapping by an authorized vehicle dismantler for all retired vehicles and equipment.

Retrofits and Conversions. The Third-Party Recipient shall submit proof that all conversions or retrofits meet current EPA low-emission standards. Retrofitting, in this context, means installing devices to reduce exhaust emissions that are verified or certified by the U.S. Environmental Protection Agency ("EPA") or the California Air Resources Board ("CARB") as proven retrofit technologies. All replacement engines must be certified or verified by the EPA or CARB.

When purchasing alternative-fueled vehicles or equipment, The Third-Party Recipient shall purchase only those types of equipment that use fuels that are available for purchase within 15 miles of its fleet operation area. Alternative-fueled technologies may include propane or electric-powered lawn mowers, propane-powered light duty vehicles and heavy equipment, propane-powered generators, and other technologies or alternative fuels as described below. The Third-Party Recipient may utilize any of the following fuel technologies if the fuel is available for purchase within 15 miles of its fleet operation area:

Alternative Fuels: Use of alternatives fuels is limited to this list of fuels which are defined as alternative fuels by the Energy Policy Act of 1992 and are currently, or have been, commercially available for vehicles: Biodiesel (if used in an area not designated as ozone non-attainment or near non-attainment), electricity, ethanol, hydrogen, methanol, natural gas and propane. Other fuels that are currently under development may be approved for use at the discretion of the TCEQ staff.

b. Environmental Benefit

Replacement of gasoline and diesel powered lawn mowers, heavy equipment, and vehicles with lower-emission items will reduce air pollution emissions of particulate matter (PM), volatile organic carbon (VOC) compounds, nitrogen oxides (NOx), and other pollutants associated with the combustion of fuel that would have been generated by the older replaced item. Use of alternative fuels combined with energy efficiency modifications results in a direct reduction in the amount of emissions that contribute to air pollution in this state.

The Respondent certifies that it has no prior commitment to make this contribution and that it is being done solely in an effort to settle this enforcement action.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Recipient and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Recipient. The Respondent shall mail a copy of the Agreed Order with the contribution to:

Brazoria County Parks Department
313 W. Mulberry
Angleton, Texas 77155

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the TCEQ SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount to the Third-Party Recipient. The Respondent shall mail a copy of the check and transmittal letter to:

Litigation Division
Attention: SEP Coordinator, MC 175
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this SEP in any way, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Section 3 above, the Executive Director may require immediate payment of all or part of the SEP Offset Amount.

In the event of incomplete performance, the Respondent shall include on the check the docket number of this Agreed Order and a note that it is for reimbursement of a SEP. The Respondent shall make the payment for the amount due to "Texas Commission on Environmental Quality" and mail it to:

Litigation Division
Attention: SEP Coordinator, MC 175
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent must include a clear statement that the project was performed as part of the settlement of an enforcement action brought by the TCEQ. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.



Penalty Calculation Worksheet (PCW)

Policy Revision 2 (September 2002)

PCW Revision October 30, 2008

TCEQ

DATES	Assigned	1-Sep-2010	Screening	1-Sep-2010	EPA Due	
	PCW	2-Sep-2010				

RESPONDENT/FACILITY INFORMATION

Respondent	The Dow Chemical Company		
Reg. Ent. Ref. No.	RN100225945		
Facility/Site Region	12-Houston	Major/Minor Source	Major

CASE INFORMATION

Enf./Case ID No.	40329	No. of Violations	1
Docket No.	2010-1450-AIR-E	Order Type	1660
Media Program(s)	Air	Government/Non-Profit	No
Multi-Media		Enf. Coordinator	Heather Podlipny
		EC's Team	Enforcement Team 4
Admin. Penalty \$ Limit Minimum	\$0	Maximum	\$10,000

Penalty Calculation Section

TOTAL BASE PENALTY (Sum of violation base penalties) **Subtotal 1** \$22,500**ADJUSTMENTS (+/-) TO SUBTOTAL 1**

Subtotals 2-7 are obtained by multiplying the Total Base Penalty (Subtotal 1) by the indicated percentage.

Compliance History 331.0% Enhancement **Subtotals 2, 3, & 7** \$74,475

Notes: Enhancement for six orders with denial of liability, eight orders without denial of liability, six same/similar NOV's, 95 dissimilar NOV's, and repeat violator status. Reduction for 130 NOIs and 52 DOVs.

Culpability No 0.0% Enhancement **Subtotal 4** \$0

Notes: The Respondent does not meet the culpability criteria.

Good Faith Effort to Comply Total Adjustments **Subtotal 5** \$0**Economic Benefit** 0.0% Enhancement* **Subtotal 6** \$0

Total EB Amounts \$572
Approx. Cost of Compliance \$11,150
*Capped at the Total EB \$ Amount

SUM OF SUBTOTALS 1-7 **Final Subtotal** \$96,975**OTHER FACTORS AS JUSTICE MAY REQUIRE** 0.0% **Adjustment** \$0

Reduces or enhances the Final Subtotal by the indicated percentage.

Notes

Final Penalty Amount \$96,975**STATUTORY LIMIT ADJUSTMENT** **Final Assessed Penalty** \$96,975**DEFERRAL** 20.0% Reduction **Adjustment** -\$19,395

Reduces the Final Assessed Penalty by the indicated percentage. (Enter number only; e.g. 20 for 20% reduction.)

Notes

Deferral offered for expedited settlement.

PAYABLE PENALTY \$77,580

Screening Date 1-Sep-2010

Docket No. 2010-1450-AIR-E

PCW

Respondent The Dow Chemical Company

Policy Revision 2 (September 2002)

Case ID No. 40329

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN100225945

Media [Statute] Air

Enf. Coordinator Heather Podlipny

Compliance History Worksheet

>> Compliance History Site Enhancement (Subtotal 2)

Component	Number of...	Enter Number Here	Adjust.
NOVs	Written notices of violation ("NOVs") with same or similar violations as those in the current enforcement action (<i>number of NOVs meeting criteria</i>)	6	30%
	Other written NOVs	95	190%
Orders	Any agreed final enforcement orders containing a denial of liability (<i>number of orders meeting criteria</i>)	6	120%
	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	8	200%
Judgments and Consent Decrees	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (<i>number of judgments or consent decrees meeting criteria</i>)	0	0%
	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government	0	0%
Convictions	Any criminal convictions of this state or the federal government (<i>number of counts</i>)	0	0%
Emissions	Chronic excessive emissions events (<i>number of events</i>)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which notices were submitted</i>)	130	-130%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (<i>number of audits for which violations were disclosed</i>)	52	-104%
Please Enter Yes or No			
Other	Environmental management systems in place for one year or more	No	0%
	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

Adjustment Percentage (Subtotal 2) 306%

>> Repeat Violator (Subtotal 3)

Yes

Adjustment Percentage (Subtotal 3) 25%

>> Compliance History Person Classification (Subtotal 7)

Average Performer

Adjustment Percentage (Subtotal 7) 0%

>> Compliance History Summary

Compliance History Notes

Enhancement for six orders with denial of liability, eight orders without denial of liability, six same/similar NOVs, 95 dissimilar NOVs, and repeat violator status. Reduction for 130 NOIs and 52 DOVs.

Total Adjustment Percentage (Subtotals 2, 3, & 7) 331%

Screening Date 1-Sep-2010

Docket No. 2010-1450-AIR-E

PCW

Respondent The Dow Chemical Company

Policy Revision 2 (September 2002)

Case ID No. 40329

PCW Revision October 30, 2008

Reg. Ent. Reference No. RN100225945

Media [Statute] Air

Enf. Coordinator Heather Podlipny

Violation Number 1

Rule Cite(s) 30 Tex. Admin. Code § 116.110(a) and Tex. Health & Safety Code §§ 382.0518(a) and 382.085(b)

Violation Description

Failed to submit applications for renewal prior to the expiration of two permits and continued to operate without authorization after the permits expired, as documented during an investigation conducted on September 1, 2010. Specifically, the Respondent failed to renew Standard Permit Registration No. 43417 for the wet compression equipment before the permit expiration date of February 16, 2010, and failed to renew New Source Review Permit No. 9046 for the Power 6 Westinghouse Gas Turbines before the permit expiration date of July 21, 2010.

Base Penalty \$10,000

>> Environmental, Property and Human Health Matrix

OR

Release	Harm		
	Major	Moderate	Minor
Actual			
Potential			

Percent 0%

>> Programmatic Matrix

Falsification	Major	Moderate	Minor
	X		

Percent 25%

Matrix Notes

100% of the rule requirement was not met.

Adjustment \$7,500

\$2,500

Violation Events

Number of Violation Events 9

197 Number of violation days

mark only one with an x

daily	
weekly	
monthly	X
quarterly	
semiannual	
annual	
single event	

Violation Base Penalty \$22,500

Nine monthly events are recommended from the date Standard Permit No. 43417 expired, on February 16, 2010, to the screening date, on September 1, 2010, and from the date New Source Review Permit No. 9046 expired, on July 21, 2010, to the screening date.

Good Faith Efforts to Comply

0.0% Reduction

\$0

Extraordinary

Before NOV NOV to EDRP/Settlement Offer

Ordinary

N/A

X

(mark with x)

Notes

The Respondent does not meet the good faith criteria for this violation.

Violation Subtotal \$22,500

Economic Benefit (EB) for this violation

Statutory Limit Test

Estimated EB Amount \$572

Violation Final Penalty Total \$96,975

This violation Final Assessed Penalty (adjusted for limits) \$96,975

Economic Benefit Worksheet

Respondent: The Dow Chemical Company
Case ID No: 40329
Reg. Ent. Reference No: RN100225945
Media: Air
Violation No: 1

Percent Interest	Years of Depreciation
5.0	15

Item Cost Date Required Final Date Yrs Interest Saved Onetime Costs EB Amount
Item Description No commas or \$

Delayed Costs

Equipment				0.00	\$0	\$0	\$0
Buildings				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0
Engineering/construction				0.00	\$0	\$0	\$0
Land				0.00	\$0	n/a	\$0
Record Keeping System	\$250	16-Feb-2010	30-Sep-2010	0.62	\$8	n/a	\$8
Training/Sampling				0.00	\$0	n/a	\$0
Remediation/Disposal				0.00	\$0	n/a	\$0
Permit Costs	\$10,900	16-Feb-2010	1-Mar-2011	1.04	\$564	n/a	\$564
Other (as needed)				0.00	\$0	n/a	\$0

Notes for DELAYED costs

Estimated costs for two new permit applications and for improving the recordkeeping/reporting system for timely permit renewal submittals. The Date Required is the date Standard Permit No. 43417 expired. The Record Keeping System Final Date is the date of implementation of an electronic recordkeeping system for environmental health and safety management. The Permit Costs Final Date is the estimated date of compliance.

Avoided Costs

ANNUALIZE [1] avoided costs before entering item (except for one-time avoided costs)

Disposal				0.00	\$0	\$0	\$0
Personnel				0.00	\$0	\$0	\$0
Inspection/Reporting/Sampling				0.00	\$0	\$0	\$0
Supplies/equipment				0.00	\$0	\$0	\$0
Financial Assurance [2]				0.00	\$0	\$0	\$0
ONE-TIME avoided costs [3]				0.00	\$0	\$0	\$0
Other (as needed)				0.00	\$0	\$0	\$0

Notes for AVOIDED costs

Approx. Cost of Compliance

\$11,150

TOTAL

\$572

Compliance History Report

Customer/Respondent/Owner-Operator:	CN600356976	The Dow Chemical Company	Classification: AVERAGE	Rating: 2.56
Regulated Entity:	RN100225945	DOW TEXAS OPERATIONS FREEPORT	Classification: AVERAGE	Site Rating: 8.93

ID Number(s):	AIR OPERATING PERMITS	ACCOUNT NUMBER	BL0082R
	AIR OPERATING PERMITS	PERMIT	1388
	AIR OPERATING PERMITS	PERMIT	2202
	AIR OPERATING PERMITS	PERMIT	2203
	AIR OPERATING PERMITS	PERMIT	2204
	AIR OPERATING PERMITS	PERMIT	2205
	AIR OPERATING PERMITS	PERMIT	2206
	AIR OPERATING PERMITS	PERMIT	2207
	AIR OPERATING PERMITS	PERMIT	2208
	AIR OPERATING PERMITS	PERMIT	2209
	AIR OPERATING PERMITS	PERMIT	2210
	AIR OPERATING PERMITS	PERMIT	2211
	AIR OPERATING PERMITS	PERMIT	2212
	AIR OPERATING PERMITS	PERMIT	2213
	AIR OPERATING PERMITS	PERMIT	2214
	AIR OPERATING PERMITS	PERMIT	2215
	AIR OPERATING PERMITS	PERMIT	2216
	AIR OPERATING PERMITS	PERMIT	2217
	AIR OPERATING PERMITS	PERMIT	2218
	AIR OPERATING PERMITS	PERMIT	2219
	AIR OPERATING PERMITS	PERMIT	2220
	AIR OPERATING PERMITS	PERMIT	2221
	AIR OPERATING PERMITS	PERMIT	2311
	AIR OPERATING PERMITS	PERMIT	2313
	AIR OPERATING PERMITS	PERMIT	2697
	AIR OPERATING PERMITS	PERMIT	3005
	INDUSTRIAL AND HAZARDOUS WASTE	EPA ID	TXD008092793
	INDUSTRIAL AND HAZARDOUS WASTE	SOLID WASTE REGISTRATION # (SWR)	30106
	INDUSTRIAL AND HAZARDOUS WASTE	PERMIT	50161
	PUBLIC WATER SYSTEM/SUPPLY	REGISTRATION	0200535
	PUBLIC WATER SYSTEM/SUPPLY	REGISTRATION	0200530
	PUBLIC WATER SYSTEM/SUPPLY	REGISTRATION	0200531
	PUBLIC WATER SYSTEM/SUPPLY	REGISTRATION	0200533
	PUBLIC WATER SYSTEM/SUPPLY	REGISTRATION	0200232

PUBLIC WATER SYSTEM/SUPPLY	REGISTRATION	0200534
PUBLIC WATER SYSTEM/SUPPLY	REGISTRATION	0200027
WASTEWATER	PERMIT	WQ0000007000
WASTEWATER	EPA ID	TX0006483
WASTEWATER	EPA ID	TX0006484
WASTEWATER	EPA ID	TX0059447
UNDERGROUND INJECTION CONTROL	PERMIT	WDW059
UNDERGROUND INJECTION CONTROL	PERMIT	WDW071
UNDERGROUND INJECTION CONTROL	PERMIT	WDW076
UNDERGROUND INJECTION CONTROL	PERMIT	WDW081
AIR NEW SOURCE PERMITS	REGISTRATION	91883
AIR NEW SOURCE PERMITS	REGISTRATION	91579
AIR NEW SOURCE PERMITS	REGISTRATION	92616
AIR NEW SOURCE PERMITS	REGISTRATION	92407
AIR NEW SOURCE PERMITS	REGISTRATION	92392
AIR NEW SOURCE PERMITS	REGISTRATION	92662
AIR NEW SOURCE PERMITS	REGISTRATION	92613
AIR NEW SOURCE PERMITS	REGISTRATION	92434
AIR NEW SOURCE PERMITS	REGISTRATION	91764
AIR NEW SOURCE PERMITS	REGISTRATION	92020
AIR NEW SOURCE PERMITS	REGISTRATION	92334
AIR NEW SOURCE PERMITS	PERMIT	941
AIR NEW SOURCE PERMITS	PERMIT	3941
AIR NEW SOURCE PERMITS	PERMIT	3947
AIR NEW SOURCE PERMITS	REGISTRATION	11832
AIR NEW SOURCE PERMITS	REGISTRATION	12173
AIR NEW SOURCE PERMITS	PERMIT	19041
AIR NEW SOURCE PERMITS	PERMIT	20195
AIR NEW SOURCE PERMITS	PERMIT	20285
AIR NEW SOURCE PERMITS	PERMIT	20432
AIR NEW SOURCE PERMITS	PERMIT	20525
AIR NEW SOURCE PERMITS	PERMIT	20607
AIR NEW SOURCE PERMITS	PERMIT	20687
AIR NEW SOURCE PERMITS	PERMIT	20774
AIR NEW SOURCE PERMITS	PERMIT	20775
AIR NEW SOURCE PERMITS	PERMIT	20776
AIR NEW SOURCE PERMITS	PERMIT	20777
AIR NEW SOURCE PERMITS	PERMIT	20909
AIR NEW SOURCE PERMITS	PERMIT	22070

AIR NEW SOURCE PERMITS	PERMIT	22071
AIR NEW SOURCE PERMITS	PERMIT	22072
AIR NEW SOURCE PERMITS	PERMIT	22078
AIR NEW SOURCE PERMITS	PERMIT	22743
AIR NEW SOURCE PERMITS	REGISTRATION	22759
AIR NEW SOURCE PERMITS	REGISTRATION	22853
AIR NEW SOURCE PERMITS	REGISTRATION	22809
AIR NEW SOURCE PERMITS	REGISTRATION	22810
AIR NEW SOURCE PERMITS	REGISTRATION	22851
AIR NEW SOURCE PERMITS	REGISTRATION	22862
AIR NEW SOURCE PERMITS	REGISTRATION	22945
AIR NEW SOURCE PERMITS	REGISTRATION	23075
AIR NEW SOURCE PERMITS	REGISTRATION	23076
AIR NEW SOURCE PERMITS	REGISTRATION	23519
AIR NEW SOURCE PERMITS	REGISTRATION	23387
AIR NEW SOURCE PERMITS	REGISTRATION	23388
AIR NEW SOURCE PERMITS	REGISTRATION	23389
AIR NEW SOURCE PERMITS	REGISTRATION	24053
AIR NEW SOURCE PERMITS	REGISTRATION	24101
AIR NEW SOURCE PERMITS	REGISTRATION	24030
AIR NEW SOURCE PERMITS	PERMIT	26692
AIR NEW SOURCE PERMITS	REGISTRATION	25702
AIR NEW SOURCE PERMITS	REGISTRATION	26035
AIR NEW SOURCE PERMITS	REGISTRATION	25124
AIR NEW SOURCE PERMITS	REGISTRATION	25536
AIR NEW SOURCE PERMITS	PERMIT	28363
AIR NEW SOURCE PERMITS	REGISTRATION	28220
AIR NEW SOURCE PERMITS	REGISTRATION	30018
AIR NEW SOURCE PERMITS	REGISTRATION	30622
AIR NEW SOURCE PERMITS	REGISTRATION	30503
AIR NEW SOURCE PERMITS	REGISTRATION	31753
AIR NEW SOURCE PERMITS	REGISTRATION	31992
AIR NEW SOURCE PERMITS	REGISTRATION	32546
AIR NEW SOURCE PERMITS	REGISTRATION	33328
AIR NEW SOURCE PERMITS	REGISTRATION	33609
AIR NEW SOURCE PERMITS	REGISTRATION	33593
AIR NEW SOURCE PERMITS	REGISTRATION	33885
AIR NEW SOURCE PERMITS	REGISTRATION	34111
AIR NEW SOURCE PERMITS	REGISTRATION	34116

AIR NEW SOURCE PERMITS	REGISTRATION	34368
AIR NEW SOURCE PERMITS	REGISTRATION	34545
AIR NEW SOURCE PERMITS	REGISTRATION	34541
AIR NEW SOURCE PERMITS	PERMIT	35022
AIR NEW SOURCE PERMITS	REGISTRATION	35012
AIR NEW SOURCE PERMITS	REGISTRATION	35204
AIR NEW SOURCE PERMITS	REGISTRATION	35203
AIR NEW SOURCE PERMITS	REGISTRATION	35364
AIR NEW SOURCE PERMITS	REGISTRATION	35413
AIR NEW SOURCE PERMITS	REGISTRATION	35658
AIR NEW SOURCE PERMITS	REGISTRATION	36002
AIR NEW SOURCE PERMITS	REGISTRATION	36397
AIR NEW SOURCE PERMITS	REGISTRATION	25205
AIR NEW SOURCE PERMITS	REGISTRATION	36554
AIR NEW SOURCE PERMITS	REGISTRATION	36523
AIR NEW SOURCE PERMITS	REGISTRATION	36569
AIR NEW SOURCE PERMITS	REGISTRATION	36634
AIR NEW SOURCE PERMITS	REGISTRATION	37000
AIR NEW SOURCE PERMITS	REGISTRATION	37122
AIR NEW SOURCE PERMITS	REGISTRATION	37569
AIR NEW SOURCE PERMITS	PERMIT	37884
AIR NEW SOURCE PERMITS	REGISTRATION	37667
AIR NEW SOURCE PERMITS	REGISTRATION	71888
AIR NEW SOURCE PERMITS	PERMIT	4020
AIR NEW SOURCE PERMITS	PERMIT	4021
AIR NEW SOURCE PERMITS	PERMIT	4031
AIR NEW SOURCE PERMITS	PERMIT	4085
AIR NEW SOURCE PERMITS	PERMIT	4310A
AIR NEW SOURCE PERMITS	PERMIT	5339
AIR NEW SOURCE PERMITS	PERMIT	5520
AIR NEW SOURCE PERMITS	PERMIT	5661
AIR NEW SOURCE PERMITS	PERMIT	6803
AIR NEW SOURCE PERMITS	PERMIT	7131
AIR NEW SOURCE PERMITS	PERMIT	7341
AIR NEW SOURCE PERMITS	PERMIT	7387
AIR NEW SOURCE PERMITS	REGISTRATION	7423
AIR NEW SOURCE PERMITS	PERMIT	7531
AIR NEW SOURCE PERMITS	PERMIT	7593

AIR NEW SOURCE PERMITS	PERMIT	8009
AIR NEW SOURCE PERMITS	PERMIT	8047
AIR NEW SOURCE PERMITS	PERMIT	8567
AIR NEW SOURCE PERMITS	PERMIT	9044
AIR NEW SOURCE PERMITS	REGISTRATION	10423
AIR NEW SOURCE PERMITS	REGISTRATION	10690
AIR NEW SOURCE PERMITS	REGISTRATION	10790
AIR NEW SOURCE PERMITS	REGISTRATION	10791
AIR NEW SOURCE PERMITS	REGISTRATION	10959
AIR NEW SOURCE PERMITS	REGISTRATION	11076
AIR NEW SOURCE PERMITS	REGISTRATION	11566
AIR NEW SOURCE PERMITS	REGISTRATION	11567
AIR NEW SOURCE PERMITS	REGISTRATION	11644
AIR NEW SOURCE PERMITS	REGISTRATION	12128
AIR NEW SOURCE PERMITS	REGISTRATION	12130
AIR NEW SOURCE PERMITS	REGISTRATION	12145
AIR NEW SOURCE PERMITS	REGISTRATION	12166
AIR NEW SOURCE PERMITS	REGISTRATION	12432
AIR NEW SOURCE PERMITS	REGISTRATION	12445
AIR NEW SOURCE PERMITS	REGISTRATION	12484
AIR NEW SOURCE PERMITS	REGISTRATION	12520
AIR NEW SOURCE PERMITS	REGISTRATION	13194
AIR NEW SOURCE PERMITS	REGISTRATION	13873
AIR NEW SOURCE PERMITS	REGISTRATION	15811
AIR NEW SOURCE PERMITS	REGISTRATION	16249
AIR NEW SOURCE PERMITS	PERMIT	16473
AIR NEW SOURCE PERMITS	PERMIT	7009
AIR NEW SOURCE PERMITS	REGISTRATION	13920
AIR NEW SOURCE PERMITS	REGISTRATION	14329
AIR NEW SOURCE PERMITS	PERMIT	17027
AIR NEW SOURCE PERMITS	PERMIT	17028
AIR NEW SOURCE PERMITS	PERMIT	20996
AIR NEW SOURCE PERMITS	PERMIT	20997
AIR NEW SOURCE PERMITS	PERMIT	18561
AIR NEW SOURCE PERMITS	PERMIT	18950
AIR NEW SOURCE PERMITS	PERMIT	19519
AIR NEW SOURCE PERMITS	REGISTRATION	37618
AIR NEW SOURCE PERMITS	REGISTRATION	38157
AIR NEW SOURCE PERMITS	REGISTRATION	38156

AIR NEW SOURCE PERMITS	REGISTRATION	38861
AIR NEW SOURCE PERMITS	REGISTRATION	38759
AIR NEW SOURCE PERMITS	REGISTRATION	39609
AIR NEW SOURCE PERMITS	REGISTRATION	39450
AIR NEW SOURCE PERMITS	REGISTRATION	40479
AIR NEW SOURCE PERMITS	REGISTRATION	40430
AIR NEW SOURCE PERMITS	REGISTRATION	40854
AIR NEW SOURCE PERMITS	REGISTRATION	41163
AIR NEW SOURCE PERMITS	REGISTRATION	41108
AIR NEW SOURCE PERMITS	REGISTRATION	41179
AIR NEW SOURCE PERMITS	REGISTRATION	41304
AIR NEW SOURCE PERMITS	REGISTRATION	41302
AIR NEW SOURCE PERMITS	REGISTRATION	41542
AIR NEW SOURCE PERMITS	REGISTRATION	41555
AIR NEW SOURCE PERMITS	REGISTRATION	42190
AIR NEW SOURCE PERMITS	REGISTRATION	42611
AIR NEW SOURCE PERMITS	REGISTRATION	42464
AIR NEW SOURCE PERMITS	REGISTRATION	42384
AIR NEW SOURCE PERMITS	REGISTRATION	42923
AIR NEW SOURCE PERMITS	REGISTRATION	43382
AIR NEW SOURCE PERMITS	REGISTRATION	43381
AIR NEW SOURCE PERMITS	REGISTRATION	42443
AIR NEW SOURCE PERMITS	REGISTRATION	43813
AIR NEW SOURCE PERMITS	REGISTRATION	43959
AIR NEW SOURCE PERMITS	REGISTRATION	43960
AIR NEW SOURCE PERMITS	REGISTRATION	44002
AIR NEW SOURCE PERMITS	REGISTRATION	44001
AIR NEW SOURCE PERMITS	REGISTRATION	44036
AIR NEW SOURCE PERMITS	REGISTRATION	44056
AIR NEW SOURCE PERMITS	REGISTRATION	44118
AIR NEW SOURCE PERMITS	REGISTRATION	44411
AIR NEW SOURCE PERMITS	REGISTRATION	44464
AIR NEW SOURCE PERMITS	REGISTRATION	44465
AIR NEW SOURCE PERMITS	REGISTRATION	44608
AIR NEW SOURCE PERMITS	REGISTRATION	44622
AIR NEW SOURCE PERMITS	REGISTRATION	44718
AIR NEW SOURCE PERMITS	REGISTRATION	44719
AIR NEW SOURCE PERMITS	PERMIT	44833
AIR NEW SOURCE PERMITS	REGISTRATION	44834

AIR NEW SOURCE PERMITS	REGISTRATION	45097
AIR NEW SOURCE PERMITS	REGISTRATION	45152
AIR NEW SOURCE PERMITS	REGISTRATION	45449
AIR NEW SOURCE PERMITS	REGISTRATION	46009
AIR NEW SOURCE PERMITS	REGISTRATION	46174
AIR NEW SOURCE PERMITS	REGISTRATION	46173
AIR NEW SOURCE PERMITS	PERMIT	46306
AIR NEW SOURCE PERMITS	REGISTRATION	46378
AIR NEW SOURCE PERMITS	PERMIT	46429
AIR NEW SOURCE PERMITS	PERMIT	46428
AIR NEW SOURCE PERMITS	PERMIT	46431
AIR NEW SOURCE PERMITS	REGISTRATION	46481
AIR NEW SOURCE PERMITS	REGISTRATION	46568
AIR NEW SOURCE PERMITS	REGISTRATION	46658
AIR NEW SOURCE PERMITS	REGISTRATION	46682
AIR NEW SOURCE PERMITS	REGISTRATION	46767
AIR NEW SOURCE PERMITS	REGISTRATION	46798
AIR NEW SOURCE PERMITS	REGISTRATION	46911
AIR NEW SOURCE PERMITS	REGISTRATION	46987
AIR NEW SOURCE PERMITS	REGISTRATION	47095
AIR NEW SOURCE PERMITS	REGISTRATION	47203
AIR NEW SOURCE PERMITS	REGISTRATION	47114
AIR NEW SOURCE PERMITS	REGISTRATION	47374
AIR NEW SOURCE PERMITS	REGISTRATION	47347
AIR NEW SOURCE PERMITS	REGISTRATION	47352
AIR NEW SOURCE PERMITS	REGISTRATION	47564
AIR NEW SOURCE PERMITS	REGISTRATION	47970
AIR NEW SOURCE PERMITS	REGISTRATION	48027
AIR NEW SOURCE PERMITS	REGISTRATION	48343
AIR NEW SOURCE PERMITS	REGISTRATION	48337
AIR NEW SOURCE PERMITS	REGISTRATION	48414
AIR NEW SOURCE PERMITS	PERMIT	48567
AIR NEW SOURCE PERMITS	PERMIT	48715
AIR NEW SOURCE PERMITS	PERMIT	48478
AIR NEW SOURCE PERMITS	PERMIT	48479
AIR NEW SOURCE PERMITS	PERMIT	48813
AIR NEW SOURCE PERMITS	REGISTRATION	49187
AIR NEW SOURCE PERMITS	REGISTRATION	49235

AIR NEW SOURCE PERMITS	REGISTRATION	49253
AIR NEW SOURCE PERMITS	REGISTRATION	47314
AIR NEW SOURCE PERMITS	PERMIT	49685
AIR NEW SOURCE PERMITS	REGISTRATION	37957
AIR NEW SOURCE PERMITS	PERMIT	9938
AIR NEW SOURCE PERMITS	PERMIT	3301
AIR NEW SOURCE PERMITS	PERMIT	834
AIR NEW SOURCE PERMITS	REGISTRATION	13682
AIR NEW SOURCE PERMITS	PERMIT	313
AIR NEW SOURCE PERMITS	PERMIT	1430
AIR NEW SOURCE PERMITS	PERMIT	1496
AIR NEW SOURCE PERMITS	PERMIT	1496B
AIR NEW SOURCE PERMITS	PERMIT	1496C
AIR NEW SOURCE PERMITS	PERMIT	2008
AIR NEW SOURCE PERMITS	REGISTRATION	49715
AIR NEW SOURCE PERMITS	REGISTRATION	85494
AIR NEW SOURCE PERMITS	REGISTRATION	49965
AIR NEW SOURCE PERMITS	REGISTRATION	50298
AIR NEW SOURCE PERMITS	REGISTRATION	72132
AIR NEW SOURCE PERMITS	PERMIT	5340
AIR NEW SOURCE PERMITS	PERMIT	5746
AIR NEW SOURCE PERMITS	PERMIT	6069A
AIR NEW SOURCE PERMITS	PERMIT	6383
AIR NEW SOURCE PERMITS	PERMIT	6744
AIR NEW SOURCE PERMITS	PERMIT	6932
AIR NEW SOURCE PERMITS	PERMIT	7093
AIR NEW SOURCE PERMITS	PERMIT	7094
AIR NEW SOURCE PERMITS	PERMIT	7385
AIR NEW SOURCE PERMITS	PERMIT	7447
AIR NEW SOURCE PERMITS	PERMIT	7942
AIR NEW SOURCE PERMITS	PERMIT	10469
AIR NEW SOURCE PERMITS	REGISTRATION	10534
AIR NEW SOURCE PERMITS	REGISTRATION	10613
AIR NEW SOURCE PERMITS	REGISTRATION	10674
AIR NEW SOURCE PERMITS	REGISTRATION	10677
AIR NEW SOURCE PERMITS	REGISTRATION	10689
AIR NEW SOURCE PERMITS	REGISTRATION	10731
AIR NEW SOURCE PERMITS	REGISTRATION	10766
AIR NEW SOURCE PERMITS	REGISTRATION	10792

AIR NEW SOURCE PERMITS	REGISTRATION	10794
AIR NEW SOURCE PERMITS	REGISTRATION	10845
AIR NEW SOURCE PERMITS	REGISTRATION	10955
AIR NEW SOURCE PERMITS	REGISTRATION	11092
AIR NEW SOURCE PERMITS	REGISTRATION	11691
AIR NEW SOURCE PERMITS	REGISTRATION	11691A
AIR NEW SOURCE PERMITS	REGISTRATION	11745
AIR NEW SOURCE PERMITS	REGISTRATION	11919
AIR NEW SOURCE PERMITS	REGISTRATION	12007
AIR NEW SOURCE PERMITS	REGISTRATION	12008
AIR NEW SOURCE PERMITS	REGISTRATION	12045
AIR NEW SOURCE PERMITS	REGISTRATION	12051
AIR NEW SOURCE PERMITS	REGISTRATION	12104
AIR NEW SOURCE PERMITS	REGISTRATION	12265
AIR NEW SOURCE PERMITS	REGISTRATION	12613
AIR NEW SOURCE PERMITS	REGISTRATION	13104
AIR NEW SOURCE PERMITS	REGISTRATION	13132
AIR NEW SOURCE PERMITS	REGISTRATION	13950
AIR NEW SOURCE PERMITS	REGISTRATION	14935
AIR NEW SOURCE PERMITS	REGISTRATION	15386
AIR NEW SOURCE PERMITS	PERMIT	4022
AIR NEW SOURCE PERMITS	REGISTRATION	12340
AIR NEW SOURCE PERMITS	PERMIT	6911
AIR NEW SOURCE PERMITS	PERMIT	18145
AIR NEW SOURCE PERMITS	PERMIT	19720
AIR NEW SOURCE PERMITS	PERMIT	19792
AIR NEW SOURCE PERMITS	PERMIT	21596
AIR NEW SOURCE PERMITS	PERMIT	770
AIR NEW SOURCE PERMITS	PERMIT	1258
AIR NEW SOURCE PERMITS	PERMIT	1472
AIR NEW SOURCE PERMITS	PERMIT	1558
AIR NEW SOURCE PERMITS	PERMIT	1559
AIR NEW SOURCE PERMITS	PERMIT	1655
AIR NEW SOURCE PERMITS	PERMIT	1658
AIR NEW SOURCE PERMITS	PERMIT	1715
AIR NEW SOURCE PERMITS	PERMIT	2008A
AIR NEW SOURCE PERMITS	PERMIT	2367
AIR NEW SOURCE PERMITS	PERMIT	2606
AIR NEW SOURCE PERMITS	PERMIT	2728

AIR NEW SOURCE PERMITS	PERMIT	2772
AIR NEW SOURCE PERMITS	PERMIT	3302
AIR NEW SOURCE PERMITS	PERMIT	3347
AIR NEW SOURCE PERMITS	PERMIT	3914
AIR NEW SOURCE PERMITS	REGISTRATION	52152
AIR NEW SOURCE PERMITS	REGISTRATION	52724
AIR NEW SOURCE PERMITS	REGISTRATION	52200
AIR NEW SOURCE PERMITS	REGISTRATION	52999
AIR NEW SOURCE PERMITS	REGISTRATION	52998
AIR NEW SOURCE PERMITS	REGISTRATION	53895
AIR NEW SOURCE PERMITS	REGISTRATION	54200
AIR NEW SOURCE PERMITS	REGISTRATION	55032
AIR NEW SOURCE PERMITS	REGISTRATION	55411
AIR NEW SOURCE PERMITS	PERMIT	83795
AIR NEW SOURCE PERMITS	PERMIT	83838
AIR NEW SOURCE PERMITS	REGISTRATION	55537
AIR NEW SOURCE PERMITS	REGISTRATION	75817
AIR NEW SOURCE PERMITS	REGISTRATION	76012
AIR NEW SOURCE PERMITS	REGISTRATION	75579
AIR NEW SOURCE PERMITS	PERMIT	75751
AIR NEW SOURCE PERMITS	REGISTRATION	76295
AIR NEW SOURCE PERMITS	REGISTRATION	76138
AIR NEW SOURCE PERMITS	REGISTRATION	76039
AIR NEW SOURCE PERMITS	REGISTRATION	75513
AIR NEW SOURCE PERMITS	REGISTRATION	56833
AIR NEW SOURCE PERMITS	REGISTRATION	56851
AIR NEW SOURCE PERMITS	REGISTRATION	70194
AIR NEW SOURCE PERMITS	REGISTRATION	70195
AIR NEW SOURCE PERMITS	PERMIT	48892
AIR NEW SOURCE PERMITS	REGISTRATION	70458
AIR NEW SOURCE PERMITS	REGISTRATION	70940
AIR NEW SOURCE PERMITS	REGISTRATION	70945
AIR NEW SOURCE PERMITS	REGISTRATION	70776
AIR NEW SOURCE PERMITS	REGISTRATION	71039
AIR NEW SOURCE PERMITS	REGISTRATION	71062
AIR NEW SOURCE PERMITS	ACCOUNT NUMBER	BL0082R
AIR NEW SOURCE PERMITS	REGISTRATION	70592
AIR NEW SOURCE PERMITS	REGISTRATION	71209

AIR NEW SOURCE PERMITS	PERMIT	N59
AIR NEW SOURCE PERMITS	REGISTRATION	71584
AIR NEW SOURCE PERMITS	REGISTRATION	71087
AIR NEW SOURCE PERMITS	REGISTRATION	71088
AIR NEW SOURCE PERMITS	REGISTRATION	71089
AIR NEW SOURCE PERMITS	REGISTRATION	71090
AIR NEW SOURCE PERMITS	REGISTRATION	71091
AIR NEW SOURCE PERMITS	REGISTRATION	54140
AIR NEW SOURCE PERMITS	REGISTRATION	53905
AIR NEW SOURCE PERMITS	REGISTRATION	50646
AIR NEW SOURCE PERMITS	REGISTRATION	52153
AIR NEW SOURCE PERMITS	REGISTRATION	52179
AIR NEW SOURCE PERMITS	REGISTRATION	53903
AIR NEW SOURCE PERMITS	REGISTRATION	52201
AIR NEW SOURCE PERMITS	REGISTRATION	53954
AIR NEW SOURCE PERMITS	REGISTRATION	50488
AIR NEW SOURCE PERMITS	REGISTRATION	71781
AIR NEW SOURCE PERMITS	REGISTRATION	52884
AIR NEW SOURCE PERMITS	REGISTRATION	53897
AIR NEW SOURCE PERMITS	REGISTRATION	54042
AIR NEW SOURCE PERMITS	REGISTRATION	71936
AIR NEW SOURCE PERMITS	REGISTRATION	50576
AIR NEW SOURCE PERMITS	REGISTRATION	72671
AIR NEW SOURCE PERMITS	REGISTRATION	53736
AIR NEW SOURCE PERMITS	REGISTRATION	53814
AIR NEW SOURCE PERMITS	REGISTRATION	72663
AIR NEW SOURCE PERMITS	REGISTRATION	72884
AIR NEW SOURCE PERMITS	REGISTRATION	72794
AIR NEW SOURCE PERMITS	REGISTRATION	72798
AIR NEW SOURCE PERMITS	PERMIT	3434
AIR NEW SOURCE PERMITS	REGISTRATION	53811
AIR NEW SOURCE PERMITS	REGISTRATION	52180
AIR NEW SOURCE PERMITS	REGISTRATION	74059
AIR NEW SOURCE PERMITS	REGISTRATION	73732
AIR NEW SOURCE PERMITS	REGISTRATION	73750
AIR NEW SOURCE PERMITS	REGISTRATION	73781
AIR NEW SOURCE PERMITS	REGISTRATION	74543
AIR NEW SOURCE PERMITS	REGISTRATION	74748
AIR NEW SOURCE PERMITS	REGISTRATION	74597

AIR NEW SOURCE PERMITS	REGISTRATION	75090
AIR NEW SOURCE PERMITS	REGISTRATION	74350
AIR NEW SOURCE PERMITS	REGISTRATION	74940
AIR NEW SOURCE PERMITS	REGISTRATION	75239
AIR NEW SOURCE PERMITS	REGISTRATION	74853
AIR NEW SOURCE PERMITS	REGISTRATION	76448
AIR NEW SOURCE PERMITS	EPA ID	PSDTX994
AIR NEW SOURCE PERMITS	EPA ID	PSDTX994M1
AIR NEW SOURCE PERMITS	EPA ID	PSDTX986M1
AIR NEW SOURCE PERMITS	REGISTRATION	76506
AIR NEW SOURCE PERMITS	REGISTRATION	76504
AIR NEW SOURCE PERMITS	REGISTRATION	76763
AIR NEW SOURCE PERMITS	REGISTRATION	76536
AIR NEW SOURCE PERMITS	REGISTRATION	77669
AIR NEW SOURCE PERMITS	REGISTRATION	77405
AIR NEW SOURCE PERMITS	REGISTRATION	77287
AIR NEW SOURCE PERMITS	REGISTRATION	76873
AIR NEW SOURCE PERMITS	REGISTRATION	77765
AIR NEW SOURCE PERMITS	REGISTRATION	77211
AIR NEW SOURCE PERMITS	REGISTRATION	77426
AIR NEW SOURCE PERMITS	REGISTRATION	77143
AIR NEW SOURCE PERMITS	REGISTRATION	77339
AIR NEW SOURCE PERMITS	REGISTRATION	77522
AIR NEW SOURCE PERMITS	REGISTRATION	77521
AIR NEW SOURCE PERMITS	REGISTRATION	76863
AIR NEW SOURCE PERMITS	REGISTRATION	77171
AIR NEW SOURCE PERMITS	REGISTRATION	77190
AIR NEW SOURCE PERMITS	AFS NUM	4803900041
AIR NEW SOURCE PERMITS	REGISTRATION	78008
AIR NEW SOURCE PERMITS	REGISTRATION	78257
AIR NEW SOURCE PERMITS	REGISTRATION	78248
AIR NEW SOURCE PERMITS	REGISTRATION	78285
AIR NEW SOURCE PERMITS	REGISTRATION	78286
AIR NEW SOURCE PERMITS	REGISTRATION	78471
AIR NEW SOURCE PERMITS	REGISTRATION	78482
AIR NEW SOURCE PERMITS	REGISTRATION	78570
AIR NEW SOURCE PERMITS	REGISTRATION	78680
AIR NEW SOURCE PERMITS	REGISTRATION	78668
AIR NEW SOURCE PERMITS	REGISTRATION	78331

AIR NEW SOURCE PERMITS	REGISTRATION	79348
AIR NEW SOURCE PERMITS	REGISTRATION	79383
AIR NEW SOURCE PERMITS	REGISTRATION	79131
AIR NEW SOURCE PERMITS	REGISTRATION	79130
AIR NEW SOURCE PERMITS	REGISTRATION	79202
AIR NEW SOURCE PERMITS	REGISTRATION	78439
AIR NEW SOURCE PERMITS	REGISTRATION	78897
AIR NEW SOURCE PERMITS	REGISTRATION	79920
AIR NEW SOURCE PERMITS	REGISTRATION	79806
AIR NEW SOURCE PERMITS	REGISTRATION	80380
AIR NEW SOURCE PERMITS	REGISTRATION	80372
AIR NEW SOURCE PERMITS	REGISTRATION	80161
AIR NEW SOURCE PERMITS	REGISTRATION	80624
AIR NEW SOURCE PERMITS	REGISTRATION	81207
AIR NEW SOURCE PERMITS	REGISTRATION	81302
AIR NEW SOURCE PERMITS	REGISTRATION	81271
AIR NEW SOURCE PERMITS	REGISTRATION	81267
AIR NEW SOURCE PERMITS	REGISTRATION	81301
AIR NEW SOURCE PERMITS	REGISTRATION	82007
AIR NEW SOURCE PERMITS	REGISTRATION	50904
AIR NEW SOURCE PERMITS	REGISTRATION	50941
AIR NEW SOURCE PERMITS	REGISTRATION	51074
AIR NEW SOURCE PERMITS	REGISTRATION	51354
AIR NEW SOURCE PERMITS	REGISTRATION	51426
AIR NEW SOURCE PERMITS	REGISTRATION	51547
AIR NEW SOURCE PERMITS	REGISTRATION	81882
AIR NEW SOURCE PERMITS	REGISTRATION	81988
AIR NEW SOURCE PERMITS	REGISTRATION	81724
AIR NEW SOURCE PERMITS	REGISTRATION	81582
AIR NEW SOURCE PERMITS	REGISTRATION	82027
AIR NEW SOURCE PERMITS	REGISTRATION	37290
AIR NEW SOURCE PERMITS	REGISTRATION	82393
AIR NEW SOURCE PERMITS	REGISTRATION	82279
AIR NEW SOURCE PERMITS	REGISTRATION	83726
AIR NEW SOURCE PERMITS	REGISTRATION	82190
AIR NEW SOURCE PERMITS	REGISTRATION	89262
AIR NEW SOURCE PERMITS	REGISTRATION	86036
AIR NEW SOURCE PERMITS	REGISTRATION	90102

AIR NEW SOURCE PERMITS	REGISTRATION	85153
AIR NEW SOURCE PERMITS	REGISTRATION	90434
AIR NEW SOURCE PERMITS	REGISTRATION	91437
AIR NEW SOURCE PERMITS	REGISTRATION	91311
AIR NEW SOURCE PERMITS	REGISTRATION	85369
AIR NEW SOURCE PERMITS	REGISTRATION	88488
AIR NEW SOURCE PERMITS	REGISTRATION	91422
AIR NEW SOURCE PERMITS	REGISTRATION	85867
AIR NEW SOURCE PERMITS	REGISTRATION	86879
AIR NEW SOURCE PERMITS	REGISTRATION	85864
AIR NEW SOURCE PERMITS	EPA ID	PSDTX986
AIR NEW SOURCE PERMITS	REGISTRATION	87696
AIR NEW SOURCE PERMITS	REGISTRATION	88522
AIR NEW SOURCE PERMITS	REGISTRATION	84455
AIR NEW SOURCE PERMITS	PERMIT	83789
AIR NEW SOURCE PERMITS	REGISTRATION	83992
AIR NEW SOURCE PERMITS	REGISTRATION	82636
AIR NEW SOURCE PERMITS	REGISTRATION	84964
AIR NEW SOURCE PERMITS	PERMIT	83841
AIR NEW SOURCE PERMITS	PERMIT	83699
AIR NEW SOURCE PERMITS	PERMIT	83862
AIR NEW SOURCE PERMITS	REGISTRATION	82587
AIR NEW SOURCE PERMITS	REGISTRATION	85034
AIR NEW SOURCE PERMITS	REGISTRATION	85324
AIR NEW SOURCE PERMITS	REGISTRATION	83994
AIR NEW SOURCE PERMITS	REGISTRATION	84491
AIR NEW SOURCE PERMITS	REGISTRATION	82774
AIR NEW SOURCE PERMITS	REGISTRATION	86160
AIR NEW SOURCE PERMITS	REGISTRATION	83304
AIR NEW SOURCE PERMITS	REGISTRATION	83031
AIR NEW SOURCE PERMITS	PERMIT	83698
AIR NEW SOURCE PERMITS	EPA ID	N84
AIR NEW SOURCE PERMITS	PERMIT	83839
AIR NEW SOURCE PERMITS	PERMIT	83804
AIR NEW SOURCE PERMITS	PERMIT	83788
AIR NEW SOURCE PERMITS	PERMIT	83792
AIR NEW SOURCE PERMITS	PERMIT	83846
AIR NEW SOURCE PERMITS	REGISTRATION	83678
AIR NEW SOURCE PERMITS	REGISTRATION	90039

AIR NEW SOURCE PERMITS	REGISTRATION	91171
AIR NEW SOURCE PERMITS	REGISTRATION	90540
AIR NEW SOURCE PERMITS	REGISTRATION	92220
AIR NEW SOURCE PERMITS	REGISTRATION	87548
AIR NEW SOURCE PERMITS	REGISTRATION	89544
AIR NEW SOURCE PERMITS	REGISTRATION	91493
AIR NEW SOURCE PERMITS	REGISTRATION	92938
AIR NEW SOURCE PERMITS	AFS NUM	4803900041
PETROLEUM STORAGE TANK REGISTRATION	REGISTRATION	38910
WATER LICENSING	LICENSE	0200232
WASTEWATER LICENSING	LICENSE	WQ0000007000
IHW CORRECTIVE ACTION	SOLID WASTE REGISTRATION # (SWR)	30106
AIR EMISSIONS INVENTORY	ACCOUNT NUMBER	BL0082R

Location: 2301 N BRAZOSPORT BLVD, FREEPORT, TX, 77541

TCEQ Region: REGION 12 - HOUSTON

Date Compliance History Prepared: September 08, 2010

Agency Decision Requiring Compliance History: Enforcement

Compliance Period: September 01, 2005 to September 01, 2010

TCEQ Staff Member to Contact for Additional Information Regarding this Compliance History

Name: Heather Podlipny Phone: 239 - 2603

Site Compliance History Components

1. Has the site been in existence and/or operation for the full five year compliance period? Yes
2. Has there been a (known) change in ownership/operator of the site during the compliance period? No
3. If Yes, who is the current owner/operator? N/A
4. If Yes, who was/were the prior owner(s)/operator(s)? N/A
5. When did the change(s) in owner or operator occur? N/A
6. Rating Date: 9/1/2010 Repeat Violator: YES

Components (Multimedia) for the Site :

- A. Final Enforcement Orders, court judgments, and consent decrees of the State of Texas and the federal government.

Effective Date: 04/14/2006

ADMINORDER 2005-0716-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ Flex Air Permit No. 20432, SC III-1 PERMIT

Description: Failed to prevent unauthorized emissions of 2,372.99 pounds (lbs) of volatile organic compounds (VOCs), 2,753.36 lbs of carbon monoxide (CO), and 100% opacity.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)
5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to submit an initial report within 24 hours after the discovery of an emissions event.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: Permit 834, Special Condition 1 PERMIT
 Description: Failed to prevent unauthorized emissions of 1,174 pounds lbs of VOCs.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: NSR Permit No. 5340, Special Condition 1 PERMIT
 Description: Failed to prevent unauthorized emissions of 443.94 pounds lbs of VOCs.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: TCEQ Air Permit #20996, SC #1 PERMIT
 Description: Failed to prevent unauthorized emissions of 66.64 lbs of 1,2-butylene oxide, 3,905.8 lbs of VOCs, 482.98 lbs of ethylene oxide, and 22.54 lbs of propylene oxide.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: NSR Permit 48813, Special Condition 1 PERMIT
 Description: Failed to prevent unauthorized emissions of 1,893 lbs VOCs.

Effective Date: 07/13/2007 ADMINORDER 2006-2006-AIR-E

Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Rqmt Prov: TCEQ Flex Air Permit 20432, SC Ch III-1 PERMIT
 Description: Failed to prevent unauthorized emissions.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Rqmt Prov: TCEQ Air Permit No. 7836, SC 1 PERMIT
 Description: Failed to prevent unauthorized emissions.

Effective Date: 08/31/2007 ADMINORDER 2006-2225-AIR-E

Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)
 Rqmt Prov: Permit No. 19519, MAERT PERMIT
 Description: Failed to prevent unauthorized emissions.
 Classification: Minor
 Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Description: Failed to submit an emissions event report within 24 hours after discovery of the event. Specifically, the emissions event was discovered on July 16, 2004 at 2:00 p.m., but was not reported until July 17, 2005 at 10:00 p.m.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Rqmt Prov: TCEQ Air Permit X-7386, SC 1 PERMIT
 Description: Failed to prevent unauthorized emissions.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Rqmt Prov: TCEQ Air Permit No. 19041, SC1 PERMIT
 Description: Failed to prevent unauthorized emissions.
 Classification: Minor
 Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(1)(H)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Description: Failed to include the applicable permit number in the Authorization section of the final emissions event report.

Effective Date: 04/03/2008

ADMINORDER 2007-0573-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: O-02313, SC 1.A. OP
Permit No. 37884, SC 6.A. PERMIT

Description: Failed to maintain a minimum net heating value of 200 BTU/scf on Polypropylene Flare F-600.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: O-02313, SC 8.A. OP
Permit No. 37884, SC 1 PERMIT

Description: Failed to meet the maximum allowable emission rate of 0.65 lb/hour for NOx on Polypropylene Flare F-600.

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 115, SubChapter H 115.783(5)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT DDD 60.562-2(a)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: O-02313, SC 8.A. OP
Permit No. 37884, SC 8.E. PERMIT

Description: Failed to seal an open-ended line with a second valve, blind flange, cap, or plug.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 48813, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions.

Effective Date: 06/19/2008

ADMINORDER 2007-1756-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 834, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions. Specifically, unauthorized emissions of 1,184 pounds of the highly reactive volatile organic compound ("HRVOC") ethylene were released through a 3-way diverter valve on the KO-132 knockout pot in the Polyethylene 4 Unit during an emissions event (Incident No. 96595) that occurred on August 27, 2007 and lasted one hour and 15 minutes.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 18569, SC1 PERMIT

Description: Failed to comply with the emissions limit of 0.15 pounds per hour ("lbs/hr") of carbon monoxide ("CO") and 400 parts per million volume ("ppmv") at 3.0% oxygen for the F-826 Heater, emissions point number ("EPN") B23S826.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 117, SubChapter B 117.310(c)(1)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Permit 20432 and PST-TX-994, S.C. I-1 PERMIT

Description: Failed to prevent unauthorized emissions.

Effective Date: 08/15/2008

ADMINORDER 2007-1843-IHW-E

Classification: Major

Citation: 30 TAC Chapter 335, SubChapter H 335.221(a)(11)
30 TAC Chapter 335, SubChapter H 335.221(a)(6)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(2)(ii)(A)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.103(c)(1)(v)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.104(b)(1)

Rqmt Prov: V.I.3.b.1. PERMIT

Description: Failed to meet the regulatory limit for stack gas concentration of carbon monoxide ("CO") while burning hazardous waste in Boiler F-2820 (Permit Unit 30, NOR Unit 180).

Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter H 335.221(a)(13)
30 TAC Chapter 335, SubChapter H 335.221(a)(6)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(7)(ii)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.103(g)

Rqmt Prov: V.I.3.b.2. PERMIT

Description: Failed to maintain a functioning automatic waste feed cutoff system.

Effective Date: 10/23/2008

ADMINORDER 2008-0478-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
30 TAC Chapter 101, SubChapter F 101.221(a)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(e)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: NSR Permit No. 834, SC 3 PERMIT
TCEQ Air Permit No. 834, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: TCEQ Flex Air Permit 20432, SC CIII-1 PERMIT

Description: Failed to prevent unauthorized emissions.

Effective Date: 10/23/2008

ADMINORDER 2004-1344-MLM-E

Classification: Major

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: Flexible Air Permit No. 20432/PST-TX-894 PERMIT

Description: Failed to prevent the lock-nut from falling off the positioner pin, which disconnected the feedback arm from the coupler block in the LHC-8. This resulted in the release of unauthorized emissions which exceeded permitted limits. Specifically, the total unauthorized emissions above the emissions cap from this incident were 80,525 lbs of VOCs, 4,599 lbs of benzene, and 10,050 lbs of CO.

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter B 115.121(a)(1)
30 TAC Chapter 115, SubChapter B 115.122(a)
5C THC Chapter 382, SubChapter A 382.085(a)

Description: Failed to prevent the unauthorized emission of ethylene at the Dow's Plant B Polyethylene (PE) Unit for a period of 33 hours starting on April 7, 2003. The reported value of ethylene released to the atmosphere, as a result of malfunctioning of the Train 2 safety relief valve, was 203,000 lbs.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Air Permit No. X-7386, SC 1 PERMIT

Description: Failed to comply with the permitted limit established in the Maximum Allowable Emission Rate Table (MAERT) of Air Permit No. X-7386 for ethylene oxide. Specifically, the Respondent failed to

prevent the unauthorized emission of ethylene oxide at the Dow's Hydroxyalkyl Acrylate (HHA Reactor System B6400) Unit for a period of one hour 45 minutes on March 12, 2003.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(G)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Permit 37884, MAERT PERMIT

Description: Failed to comply with the permitted limit established in the Maximum Allowable Emission Rate Table (MAERT) of Air Permit No. 37884 for propylene (C₃H₆O), carbon monoxide (CO), and nitric oxide (NO_x). Specifically, the Respondent failed to prevent the unauthorized emission of C₃H₆O, CO, and NO_x at the Dow's North American Propylene (NAPP-1) Unit during the period between January 4 and 25, 2003.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: NSR Permit #19041, Special Condition #9 PERMIT

Description: Failed to have available the records to demonstrate that samples were being continuously collected from the bottoms of stripping towers T-444 and T-445.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: Permit No. 19041, Special Condition #13 PERMIT

Description: Failed to use an approved method to establish the pounds per hour of VOCs emitted into the atmosphere from cooling towers CT-320 and CT-2320.

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: Permit #19041, Special Condition #19.B PERMIT

Description: Failed to conduct a quarterly accuracy audit for the CEMS on Boiler No. 2 FTB-402 (EPN No. OC5SV404) for the third quarter (July through September) of 2002.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(c)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(c)(2)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(f)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(d)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Permit #19041, Special Conditions 15,16 PERMIT
Permit 19041, SC 1 PERMIT

Description: Failed to meet the requirements of the VOC leak detection and repair programs. Specifically, one pump was not attempted to be repaired within five days; and two pumps, one valve, and two connectors were not repaired within 15 days.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT TT 63.1004(b)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Permit 19041, SC 1 PERMIT

Description: Failed to perform VOC leak detection monitoring of valves according to 40 CFR Part 60, Appendix A-7, Method 21, 8.3.1 during the fourth quarter of 2003. The estimated amount of VOC emissions from the 25 valves were 20.24 lbs of VOCs.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)
5C THSC Chapter 382 382.085(b)

Description: Failed to submit a complete final emissions event report.

Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter A 335.2(b)
30 TAC Chapter 335, SubChapter O 335.431
40 CFR Chapter 268, SubChapter I, PT 268, SubPT A 268.1(a)
40 CFR Chapter 268, SubChapter I, PT 268, SubPT D 268.40(a)

Rqmt Prov: HW Permit 50161 III-E 10 and V-EE PERMIT

Description: Failed to prevent the disposal of unauthorized hazardous waste into an on-site hazardous waste landfill. Specifically, instead of sending the waste to an on-site incinerator, or performing the on-site waste stabilization treatment, 355 cubic yards of non-treated waste (contaminated soil) was

placed in Cell IV of Dow's Block-51 landfill between the period of January 14, 2003 and September 23, 2003.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ Air Permit 834, Special Condition 1 PERMIT

Description: Failed to prevent unauthorized emissions of 10,085 pounds ("lbs") of the highly reactive volatile organic compound ("HRVOC") ethylene during an emissions event that occurred on May 26, 2004 and lasted 4 hours and 30 minutes. These emissions were not authorized by the permit.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)
5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failed to submit an emissions event report within 24 hours after discovery of the event. Specifically, the emissions event was discovered on May 26, 2004 at 9:30 a.m., but was not reported until May 27, 2006 at 1:59 p.m.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ Flex Air Permit #20432, SC ChIII-1 PERMIT

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(8)(A)
30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: Permit No. 834, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions and failed to prevent visible emissions with an opacity greater than 30% for any 6-minute period.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ Flex Air Permit #20432, SC #III-1 PERMIT

Description: Failed to comply with Air Permit No. 20432, Special Condition III-1, by allowing the release of unauthorized emissions at the Light Hydrocarbon 7 facility during a nonexempt emissions event which lasted from 4:35 a.m. until 9:30 a.m. on August 13, 2004. The emissions event was caused by an error made by maintenance personnel who left a valve closed on a backup hydrogen line for one of the facility's reactors.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
30 TAC Chapter 111, SubChapter A 111.111(a)(4)(A)(i)
30 TAC Chapter 116, SubChapter G 116.715(a)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Flexible Permit 20432, SC III-1 PERMIT
Permit 20432, SC 111-17 PERMIT

Description: Failed to prevent unauthorized emissions, failed to prevent visible emissions from a process gas flare for more than five minutes in any two-hour period, and failed to operate a process gas flare with a pilot flame present at all times.

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: NSR Permit #20776, Special Condition #8 PERMIT

Description: Failed to maintain pH and water flow rates for Scrubber D-27. The maximum allowable pH is 4.0 and the minimum required flow rate is 0.6 gallons per minute or 5 pounds per minute (lbs/min). On 9/24/03 at 2:10 p.m., redundant pH readings were 9.1 and 8.6 and were caused by blow-back of trimethylamine (TMA) in the line after unloading a railcar.

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: NSR Permit #20776, Special Cond. #7.G. PERMIT

Description: Failed to conduct an instrument-monitored fugitive emission inspection on a pump, Tag #EAI273155, for two quarters, fourth quarter 2003 and first quarter 2004.

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: NSR Perm. #20776, Spec. Cond. #6.E & 7.E PERMIT

Description: Failed to maintain caps and/or plugs on four open-ended lines in the B6600 Quat 188 Plant for components EAI272070 (T-100c/EPN B6610V100), EAI272990 (T-100c/EPN B6610V100), EAI273010 (D-57/EPN Unknown), and EAI272471 (P-53A/EPN B6610V53).

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: NSR Permit #20776, General Cond. #7 PERMIT

Description: Failed to retain two-year fugitive emission monitoring records for 21 components in methylene chloride service and 22 components in volatile organic compound (VOC) service.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: NSR Permit #20776, Special Cond. #10 PERMIT

Description: Failed to monitor for fugitive emissions all connectors, regardless of size, in VOC service.

A total of 649 components were not monitored.

Classification: Major

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)

5C THC Chapter 382, SubChapter A 382.085(b)

5C THSC Chapter 382 382.0518(a)

Description: Failed to obtain a permit prior to constructing and operating methylene chloride extraction Tower T-100c.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ Flexible Air Permit 20432, SC III-1 PERMIT

Description: Failed to prevent unauthorized emissions of 1,160 lbs of volatile organic compounds ("VOCs") from the Light Hydrocarbons - 7 Unit, Facility ID No. B72L7RX1, emission point number ("EPN") B60F3 and 546.9 lbs of Carbon Monoxide and 90% opacity from Facility ID No. B60L7F1 during an emissions event that occurred on April 28, 2005 and lasted 1 hour and 36 minutes.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ Air Permit 834, SC1 PERMIT

Description: Failed to prevent unauthorized emissions of 2,369 pounds ("lbs") of the HRVOC Ethylene at the Polyethylene IV Unit, Facility ID NO. B41P4RX1, emission point number ("EPN") B41RL1 during an emissions event that occurred on March 30, 2005 and lasted 15 minutes. These emissions are not authorized by the permit.

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: 19519, SC 5E PERMIT

48813, SC 5E PERMIT

6803, SC 9E PERMIT

834, SC 9E PERMIT

8567, SC 8E PERMIT

O-02215, SC 1A & SC 11 OP

Description: Failed to equip 27 open-ended lines with a cap or plug within the operating areas of B27P3FU3, B25P2FU1, B25P2FU2, B37P4FU1, B41P4FU1, and B77APFU1 between February 27, 2004 and August 29, 2004. Specifically during the deviation reporting periods of January 28, 2004 to July 27, 2004 and July 28, 2004 to September 30, 2004 there were 27 deviations reported for open-ended lines in VOC service with no second valve, blind flange, cap, or plug.

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(2)

30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: 834, SC 9I PERMIT

O-02215, SC 1A & SC 11 OP

Description: Failed to either repair or place on the delay of repair list 10 leaking components in Unit B41P4FU1 within 15 days after the leak was discovered.

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.145(2)(A)

5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: O-02215, General Terms & Conditions OP
 Description: Failed to include the hydrogen chloride leak in Unit B41P4CT1 on July 2, 2004 as a deviation in the August 24, 2004 deviation report.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: 48813, SC 1 PERMIT
 O-02215 SC 11 OP
 Description: Failed to prevent unauthorized emissions of 663 lbs of Carbon released on February 10, 2004 for approximately two minutes, which were not reported within 24 hours (reported in a deviation report submitted August 24, 2004).
 Classification: Moderate
 Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: 20432, SC 2E PERMIT
 Description: failed to equip 27 open-ended lines with a cap or plug within the operating areas of B19G1FU1, B23G2FU2, and B68ALFU1 between April 19, 2004 and April 18, 2005. Specifically, during the deviation reporting periods of April 19, 2004 to October 18, 2004 and October 19, 2004 to April 18, 2005 there were 27 deviations reported for open-ended lines in hazardous air pollutant ("HAP") and/or volatile organic compound ("VOC") service with no second valve, blind flange, cap, or plug.
 Classification: Minor
 Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: 20432, SC 3A PERMIT
 Description: Failed to conduct auditory, visual, and olfactory (AVO) checks one shift each day for Hydrogen Chloride and Chlorine leaks within the operating area of B68ALFU1 between August 14 and 18, 2004.
 Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Description: Failed to monitor five valves in highly reactive VOC ("HRVOC") service during the second quarter of 2004.
 Classification: Minor
 Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.152(c)(2)(ii)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: 20432, SC I-22C PERMIT
 Description: Failed to convert in-stack concentrations of Carbon Monoxide emissions to pounds per hour ("lbs/hr") from scrubber B19G1T210 for the 3rd and 4th quarters of 2004.
 Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Rqmt Prov: TCEQ Air Permit 7386, SC 1 PERMIT
 Description: Exceeded the maximum allowable emission rate (MAER) for volatile organic compounds (VOC) during an avoidable emissions event at the Hydroxy Alkyl Acrylates Plant on December 23, 2004. Dow failed to close a valve after maintenance which resulted in an over pressurization, blown rupture disc, and release of 1,061 pounds (lbs) of propylene oxide from the VS-1 Scrubber. The duration was one hour and 45 minutes. The MAER for VOCs is 0.20 lbs per hour.
 Classification: Moderate
 Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)(1)
 5C THSC Chapter 382 382.085(b)
 Rqmt Prov: O-01388, SC 1A OP
 Description: Failed to monitor 269 valves in Volatile Hazardous Air Pollutant ("VHAP") service in the Chemicals and Metals (1) area from February 3, 2004 to September 30, 2004, as reported during the deviation reporting period of August 3, 2004 to February 2, 2005.
 Classification: Moderate
 Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
 30 TAC Chapter 115, SubChapter D 115.352(4)

30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: O-01388, SC 1A OP

Description: Failed to equip 49 open-ended lines in the Chemicals and Metals (1) area with a second valve, blind flange, cap, or plug. Specifically, during the deviation reporting periods of February 3, 2004 to August 3, 2004 and August 3, 2004 to February 2, 2005, it was reported there were 11 open-ended lines in VHAP service on February 3, 2004, and 38 open-ended lines in VHAP service from August 17, 2004 to January 7, 2005.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.148(b)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: O-01388, SC 1A OP

Description: Failed to conduct an annual Audio, Visual, and Olfactory ("AVO") inspection of the closed vent system in VHAP service in the Chemicals and Metals (1) area, as reported during the deviation reporting period of August 3, 2004 to February 2, 2005.

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: 48478, SC 2 PERMIT

5339, SC 11 PERMIT
5661, SC 6 PERMIT

Description: Failed to adequately maintain records regarding repairs and replacements done as a result of leaks documented during AVO inspections of the Chemicals and Metals (1) areas once per shift, as reported during the deviation reporting period of August 3, 2004 to February 2, 2005.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.116(b)(1)
5C THSC Chapter 382 382.085(b)

Description: Failed to operate within permit representations. Specifically, TCEQ Air Permit No. 5661 does not authorize chlorine emissions from the J-20 HCl absorber in the Chemicals and Metals (1) area (EPN B15V20), however, during the deviation reporting period of August 3, 2004 to February 2, 2005, unauthorized chlorine emissions from the J-20 HCl absorber were reported.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT SS 63.994(b)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT YY 63.1103(d)

Rqmt Prov: 7531, SC 6 PERMIT

O-02210, STC 10 OP

Description: Failed to establish minimum liquid to gas ("L/G") ratio for the operation of the scrubber (halogen reduction device) in the polycarbonate facility in the engineering thermoplastics unit during the performance test conducted on December 12, 2002. Without the L/G ratio established, compliance with the mass emission rate requirement of less than 0.45 kilograms per hour ("kg/hr") cannot be determined.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
30 TAC Chapter 116, SubChapter B 116.115(b)(2)(C)
30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT NNNNN 63.9000(a)
5C THSC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: Permit 46431, General Condition 8 PERMIT

Permit 46431, SC 5 PERMIT

Description: Failed to comply with hydrogen chloride ("HCl") emissions limits of 0.40 pounds per hour ("lbs/hr") and 12.0 parts per million ("ppm") and Chlorine ("Cl2") emissions limits of 0.03 lbs/hr and failed to comply with the minimum destruction efficiency of 99.99% for volatile organic compounds (VOCs).

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter B 115.126(1)(B)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: NSR 22072, SC 4 PERMIT

Title V O-02212, SC 1E OP

Title V O-02212, SC 16 OP

Description: Failed to meet the flare requirements for 3 flares (EPN Nos. BSRF601, BSRFMW1T, and BSRFMNF). Specifically, Dow Chemical failed to monitor the flare pilots flames in order to maintain the continuous presence of a flame using a thermocouple or other equipment device which detects the presence of a flame.

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: NSR 22072, SC 4 PERMIT
NSR 22072, SC 5 PERMIT
Title V O-02212, SC 16 OP
Title V O-02212, SE 1E OP

Description: Failed to maintain the continuous presence of a flame on five occasions for three flares (EPN Nos. BSRFMNF, BSRF601, and BSRFMW1T).

Classification: Minor

Citation: 30 TAC Chapter 106, SubChapter K 106.262(3)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Title V O-02212, SC 17 OP

Description: Failed to submit Permit by Rule ("PBR") notification (Form PI-7) within ten days following modifications to the brine process for the aromatic storage wells (EPN Nos. BSRPSR2 and BSRPR2L) in to Lake Warder and SR-2 (benzene brine ponds).

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Permit 22072, SC 8F PERMIT
Title V Permit O-02212, SC 16 OP

Description: Failed to monitor 504 valves and 1,716 connectors in the fugitive emissions area (EPN No. BSRFUBRCK) during the third and fourth quarters of 2004, and the second quarter of 2005. The estimated amount of volatile organic compound ("VOCs") fugitive emissions during this time period of 273 days is 14.71 tons from the valves, and 2.82 tons from the connectors, for a combined total of 17.53 tons of VOCs. The permitted limit of VOCs from this EPN is 2.04 tons per year.

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.145(2)(A)
5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failed to report the deviation of failure to conduct fugitive emissions monitoring on 504 valves and 1,716 connectors in the fugitive area (EPN No. BSRFUBRCK) during the second quarter of 2005 in the deviation report dated August 5, 2005.

Classification: Minor

Citation: 30 TAC Chapter 117, SubChapter B 117.208(d)(7)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Title V O-02212, SC 1D OP

Description: Failed to check for proper operation of the engine (EPN No. BSRGE601) by recorded measurements of nitrogen oxide ("NOx") and carbon monoxide ("CO") emissions after engine maintenance was conducted on February 26, 2005.

Classification: Minor

Citation: 30 TAC Chapter 117, SubChapter B 117.216(a)(5)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Title V O-02212, SC 1D OP

Description: Failed to include the specific rule citations for units with a claimed exemption from the emission specifications of 30 TEX. ADMIN. CODE § 117.206 in the final control report submitted March 31, 2005.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: NSR Permit No. 834, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions. Specifically, unauthorized emissions of 3, 401 lbs of the HRVOC ethylene were released from an inconel rupture disc in the Polyethylene #4 Unit (Incident 73950) during an emissions event that occurred on April 4, 2006 and lasted 6 minutes. These emissions are not authorized by the permit.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Permit No. O-02215, SC 2.F. PERMIT

Description: Failed to report within 24 hours the emissions event of 663 lbs of Carbon released on February 10, 2004 for approximately two minutes. The regulated entity reported the event on a deviation report on August 24, 2004.

Effective Date: 02/08/2009

ADMINORDER 2007-1981-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: TCEQ Flex Air Permit No. 20432, SC C III PERMIT

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 834, SC 1 PERMIT

Description: Failed to prevent unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

5C THSC Chapter 382 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 6932, SC1 PERMIT

Description: Failed to prevent unauthorized emissions.

Effective Date: 06/01/2009

ADMINORDER 2008-0843-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(b)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Flexible Air Permit 20432, SC Chap III-1 PERMIT

Description: As evidenced by Findings of Fact No. 3, the Respondent failed to prevent unauthorized emissions during Incident No. 92204, in violation of Air Permit No. 20432/PSD-TX-994M1, Special Condition No. III-1, 30 TEX. ADMIN. CODE § 116.715(a), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable and excessive the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 46431, SC 1 PERMIT

Description: As evidenced by Findings of Fact No. 7, the Respondent failed to prevent unauthorized emissions during Incident No. 92991, in violation of Air Permit No. 46431, Special Condition No. 1, 30 TEX. ADMIN. CODE § 116.115(c), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable and excessive the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition No. 1 PERMIT

Description: As evidenced by Findings of Fact No. 4, the Respondent failed to prevent unauthorized emissions during Incident No. 103332, in violation of Air Permit No. 7386, Special Condition No. 1, 30 TEX. ADMIN. CODE § 116.115(c), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition 1 PERMIT

Description: As evidenced by Findings of Fact No. 5, the Respondent failed to prevent unauthorized emissions during Incident No. 103745, in violation of Air Permit No. 46431, Special Condition No. 1, 30 TEX. ADMIN. CODE § 116.115(c), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition Chapter III-1 PERMIT

Description: As evidenced by Findings of Fact No. 6, the Respondent failed to prevent unauthorized emissions during Incident No. 104544, in violation of Air Permit No. 20432/PSD-TX-994M1, Special Condition No. III-1, 30 TEX. ADMIN. CODE § 116.715(a), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition 1 PERMIT

Description: As evidenced by Findings of Fact No. 8, the Respondent failed to prevent unauthorized emissions during Incident No. 105191, in violation of Air Permit No. 834, Special Condition No. 1, 30 TEX. ADMIN. CODE § 116.115(c), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
30 TAC Chapter 101, SubChapter F 101.221(a)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition 1 PERMIT

Special Condition 10 PERMIT

Special Condition 4B PERMIT

Description: As evidenced by Findings of Fact No. 10, the Respondent failed to prevent unauthorized emissions and maintain a flare flame during Incident No. 105644, in violation of Air Permit No. 8567, Special Condition Nos. 1, 4B, and 10, 40 CODE OF FEDERAL REGULATIONS § 60.18(c)(2) and (c)(3)(ii), 30 TEX. ADMIN. CODE §§ 116.115(c), 101.20(1), and 101.221(a), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable the demonstration criteria for an affirmative defense in 30 TEX.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition No. 1 PERMIT

Description: As evidenced by Findings of Fact No. 9, the Respondent failed to prevent unauthorized emissions during Incident No. 105792, in violation of Air Permit No. 20909, Special Condition No. 1, 30 TEX. ADMIN. CODE § 116.115(c), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition No. 1 PERMIT

Description: As evidenced by Findings of Fact No. 11, the Respondent failed to prevent unauthorized emissions during Incident No. 106640, in violation of Air Permit No. 22072, Special Condition No. 1, 30 TEX. ADMIN. CODE § 116.115(c), and TEX. HEALTH & SAFETY CODE § 382.085(b). Since the emissions event was avoidable the demonstration criteria for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222 were not met.

Effective Date: 07/09/2009

ADMINORDER 2007-0923-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: TCEQ FLEX AIR PERMIT #20432, III-1 PERMIT

Description: Failed to comply with permitted emissions limits.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: TCEQ Flexible Air Permit 20432, SC III-1 PERMIT

Description: Failed to comply with permitted emissions limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: 6803, Special Condition 1 PERMIT

Description: Failed to comply with permitted emissions limits. Specifically, on December 29, 2006, Dow conducted a stack test on the 511 Heater (EPN B27S511) located in the B-2700 block of the Plant B Site. Test results showed emissions of NOX at 5.70 lbs/hr, while permitted emissions are 3.73 lbs/hr.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 7531, SC 2 PERMIT

TCEQ Air Permit No. 7531, SC1 PERMIT

Description: Failed to comply with permitted emissions limits.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
30 TAC Chapter 101, SubChapter A 101.20(3)
30 TAC Chapter 116, SubChapter G 116.715(a)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(d)
5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: Air Flex Permit 20432, SC Gen Req 4 PERMIT

Air Flex Permit 20432, SC, Chap III-1 PERMIT

Description: Failed to comply with permitted emissions limits.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)
5C THC Chapter 382, SubChapter D 382.085(b)
5C THSC Chapter 382 382.0518(a)

Description: Failure to cease unauthorized emissions. Specifically, during an emissions event on March 8, 2007, emergency vents in the Polyethylene 4 Unit, with no authorization to emit, emitted 802 lbs of ethylene and 700 lbs of carbon over a one minute period.

Effective Date: 08/31/2009

ADMINORDER 2008-1723-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
30 TAC Chapter 101, SubChapter F 101.221(a)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: TCEQ Air Permit No. 834, SC 1 PERMIT

Description: Failed to prevent avoidable emissions event.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition Chapter III - 1 PERMIT

Description: the unauthorized release of 86 lbs of acetylene, 12,491 lbs of ethylene, 2,923 lbs of ethane, 12,226 lbs of propylene, 5,859 lbs of propane, 1,088 lbs of 1,3 butadiene, 91 lbs of cis 2-butene, 29,563 lbs of CO, 4,093 lbs of NOx, 81 lbs of isobutane, 235 lbs of n-butane, 352 lbs of trans 2-butene, 1,474 lbs of benzene, 2,337 lbs of toluene, 302 lbs of hexane, 452 lbs of isobutylene, 529 lbs of isopentane,

716 lbs of n-pentane and 331 lbs of 1-butene from Elevated Flare (F1) and Ground Flare.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: SC Ch III-1 PERMIT

Description: Dow failed to prevent an avoidable emissions event. As a result unauthorized emissions of, 1.00 lbs of benzene; 1.00 lbs of 1,3-butadiene; 1,064.00 lbs of ethylene; 770.00 lbs of carbon monoxide; 107.00 lbs of nitrogen oxides and 9.00 lbs of other chemicals were released to the atmosphere through Flare - FS1.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition 1 PERMIT

Description: Failure to prevent unauthorized emissions. Specifically, 751.90 lbs of ethylene oxide was released from the Wastewater Treatment Plant THROX (B35EWS200); 3.00 lbs of ethylene oxide was released from the R-100 Reactor (EPN B35V100); and 3.00 lbs of ethylene oxide was released from the R-110 Reactor (EPN B35V110) to the atmosphere. Dow's permit did not authorize the release. Consequently, this represents a significant deviation from the permit.

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition 1 PERMIT

Description: Failure to prevent unauthorized emissions. As a result, 1,244.00 lbs of ethylene was released from the Polyethylene 4 Reactor, Train 1, Program 3 Valve, to the atmosphere. Dow's permit did not authorize the release from the Program 3 Valve. Consequently, this represents a significant deviation from the permit.

Effective Date: 11/27/2009

ADMINORDER 2008-1555-IHW-E

Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter H 335.221(a)(6)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(1)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(2)(ii)(A)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.104(b)(1)

Rqmt Prov: Permit Provision (PP) V-I-3-b and d PERMIT

Description: Failed to meet the regulatory limit for stack gas concentration of carbon monoxide ("CO") while burning hazardous waste in Boiler FTB-210 (Notice of Registration Unit 154), as documented an investigation conducted on July 29, 2008. Specifically, ten occurrences were documented during a period from March 30, 2008 through April 21, 2008, when the CO concentration exceeded 100 ppm associated with the automatic waste feed cutoff ("AWFCO") system.

Classification: Major

Citation: 30 TAC Chapter 335, SubChapter H 335.221(a)(6)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(a)

Rqmt Prov: Permit Provision (PP) V-I-3-b and d PERMIT

Description: Failed to maintain the minimum permitted liquid to gas ratio ("L/G") of the wet scrubbers, as documented during an investigation conducted on July 29, 2008. Specifically, records for Boiler FTB-603 indicated five excursions with respect to the permitted L/G minimum ratio for the scrubber system.

Effective Date: 04/11/2010

ADMINORDER 2009-1251-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Rqmt Prov: Special Condition 1 PERMIT

Special Term and Condition 16 OP

Description: Failed to maintain an emission rate below the allowable limit for propylene from the Site Functions 1 Area. TCEQ staff documented the exceedance of the permitted propylene emission limit of 4.05 pounds per hour ("lbs/hr") from the Site Functions 1 Area on June 23-24, 2008 and July 13, 2008, totaling 42.74 lbs of propylene in excess of permitted limits.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-1(a)
 5C THSC Chapter 382 382.085(b)
 Rqmt Prov: Special Term and Condition 16 OP
 Special Term and Condition 1A OP

Description: Failed to conduct LDAR on 78 components in VOC service. TCEQ staff documented that quarterly Leak Detection and Repair ("LDAR") had not been conducted on 44 connectors and seven valves in Unit A22FUST from October 16, 2003 through March 31, 2008 and 27 valves in Unit A28FUST from February 5, 2007 through October 14, 2008.

Classification: Major
 Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 5C THSC Chapter 382 382.085(b)
 Rqmt Prov: Special Condition, Chapter III-1 PERMIT

Description: Failed to maintain an emission rate below the allowable limit for propylene from the Site Functions 1 Area. TCEQ staff documented the unauthorized release of 11,521 pounds ("lbs") of carbon monoxide, 1,595 lbs of nitrogen oxides, and 12,209 lbs of volatile organic compounds ("VOCs"), including 8,859 lbs of highly reactive VOCs, exceeded permit hourly limits due to the Light Hydrocarbons-8 failure to eliminate non-condensables from the Propylene Refrigeration System causing high pressure in the C

B. Any criminal convictions of the state of Texas and the federal government.

N/A

C. Chronic excessive emissions events.

N/A

D. The approval dates of investigations. (CCEDS Inv. Track. No.)

1	09/01/2005	(403238)
2	09/12/2005	(406575)
3	09/14/2005	(431669)
4	09/22/2005	(575541)
5	09/28/2005	(402693)
6	09/28/2005	(406914)
7	09/30/2005	(402695)
8	10/05/2005	(374026)
9	10/21/2005	(575543)
10	10/26/2005	(431242)
11	10/26/2005	(432043)
12	10/26/2005	(432097)
13	10/26/2005	(432895)
14	10/26/2005	(432935)
15	10/26/2005	(432986)
16	11/15/2005	(435315)
17	11/25/2005	(575545)
18	11/30/2005	(373986)
19	11/30/2005	(435278)
20	12/23/2005	(575547)
21	12/30/2005	(433116)
22	01/10/2006	(436188)
23	01/17/2006	(376062)
24	01/17/2006	(593182)
25	01/23/2006	(575550)
26	01/24/2006	(575549)
27	01/27/2006	(436181)
28	02/03/2006	(436165)
29	02/07/2006	(436297)
30	02/09/2006	(435249)
31	02/26/2006	(575523)
32	02/27/2006	(436730)
33	02/27/2006	(453320)

34	03/02/2006	(431805)
35	03/17/2006	(340573)
36	03/23/2006	(433180)
37	03/23/2006	(436917)
38	03/24/2006	(374721)
39	03/24/2006	(575525)
40	03/28/2006	(436841)
41	03/31/2006	(436922)
42	03/31/2006	(454296)
43	04/11/2006	(454294)
44	04/17/2006	(433179)
45	04/17/2006	(436288)
46	04/17/2006	(454234)
47	04/17/2006	(459765)
48	04/19/2006	(459137)
49	04/19/2006	(575528)
50	04/26/2006	(433177)
51	05/09/2006	(459139)
52	05/11/2006	(289568)
53	05/11/2006	(459075)
54	05/11/2006	(459108)
55	05/17/2006	(461234)
56	05/17/2006	(462138)
57	05/17/2006	(463636)
58	05/17/2006	(465607)
59	05/24/2006	(466817)
60	05/25/2006	(462747)
61	05/25/2006	(462749)
62	05/25/2006	(462949)
63	05/26/2006	(575531)
64	05/31/2006	(457316)
65	06/15/2006	(481001)
66	06/22/2006	(458889)
67	06/26/2006	(575534)
68	07/14/2006	(457318)
69	07/14/2006	(480399)
70	07/14/2006	(480559)
71	07/14/2006	(480854)
72	07/14/2006	(484040)
73	07/14/2006	(485731)
74	07/14/2006	(486688)
75	07/17/2006	(462746)
76	07/17/2006	(462748)
77	07/17/2006	(482291)
78	07/18/2006	(481382)
79	07/21/2006	(457258)
80	07/21/2006	(482501)
81	07/21/2006	(575537)
82	08/07/2006	(438858)
83	08/07/2006	(466313)
84	08/08/2006	(479807)
85	08/11/2006	(247956)
86	08/11/2006	(457284)
87	08/14/2006	(483077)
88	08/14/2006	(483124)
89	08/14/2006	(483129)
90	08/15/2006	(462106)
91	08/15/2006	(489783)
92	08/15/2006	(490271)
93	08/18/2006	(338817)

94	08/18/2006	(338822)
95	08/18/2006	(465699)
96	08/18/2006	(480155)
97	08/18/2006	(483113)
98	08/22/2006	(484727)
99	08/22/2006	(490091)
100	08/23/2006	(457302)
101	08/23/2006	(457315)
102	08/23/2006	(484737)
103	08/23/2006	(509637)
104	08/24/2006	(575540)
105	08/25/2006	(484732)
106	08/25/2006	(509011)
107	08/28/2006	(483212)
108	08/28/2006	(484741)
109	08/28/2006	(490104)
110	08/28/2006	(497117)
111	08/31/2006	(457309)
112	09/01/2006	(487340)
113	09/01/2006	(487866)
114	09/01/2006	(489195)
115	09/01/2006	(489802)
116	09/01/2006	(497542)
117	09/01/2006	(508889)
118	09/01/2006	(509414)
119	09/01/2006	(509679)
120	09/01/2006	(509787)
121	09/07/2006	(510182)
122	09/07/2006	(510901)
123	09/08/2006	(489713)
124	09/08/2006	(489814)
125	09/08/2006	(490183)
126	09/08/2006	(490187)
127	09/08/2006	(510155)
128	09/18/2006	(509863)
129	09/18/2006	(575542)
130	09/29/2006	(513116)
131	10/11/2006	(512347)
132	10/12/2006	(515660)
133	10/12/2006	(515784)
134	10/25/2006	(509774)
135	10/25/2006	(516468)
136	10/30/2006	(509665)
137	10/30/2006	(512117)
138	11/03/2006	(575544)
139	11/07/2006	(516589)
140	11/07/2006	(516999)
141	11/08/2006	(515899)
142	11/10/2006	(517068)
143	11/15/2006	(518266)
144	11/21/2006	(519005)
145	11/21/2006	(575546)
146	11/28/2006	(340237)
147	11/30/2006	(519472)
148	11/30/2006	(532072)
149	12/04/2006	(518648)
150	12/04/2006	(518693)
151	12/04/2006	(518746)
152	12/04/2006	(518847)
153	12/05/2006	(518987)

154	12/05/2006	(518994)
155	12/05/2006	(519433)
156	12/07/2006	(532408)
157	12/12/2006	(532985)
158	12/13/2006	(512466)
159	12/15/2006	(512613)
160	12/18/2006	(512614)
161	12/20/2006	(512546)
162	12/20/2006	(518862)
163	12/22/2006	(575548)
164	01/03/2007	(533504)
165	01/08/2007	(533024)
166	01/08/2007	(535581)
167	01/16/2007	(535585)
168	01/17/2007	(537051)
169	01/18/2007	(512465)
170	01/19/2007	(532792)
171	01/19/2007	(532798)
172	01/19/2007	(535582)
173	01/19/2007	(535584)
174	01/19/2007	(535587)
175	01/25/2007	(535586)
176	02/14/2007	(537570)
177	02/15/2007	(532539)
178	02/16/2007	(532501)
179	02/16/2007	(538485)
180	02/20/2007	(537571)
181	02/26/2007	(575524)
182	02/27/2007	(518917)
183	02/28/2007	(540981)
184	03/22/2007	(536044)
185	03/22/2007	(538381)
186	03/22/2007	(542323)
187	03/23/2007	(538331)
188	03/23/2007	(542214)
189	03/23/2007	(543884)
190	03/23/2007	(553947)
191	03/23/2007	(554153)
192	03/23/2007	(554156)
193	03/26/2007	(554162)
194	03/26/2007	(575526)
195	03/30/2007	(489438)
196	03/30/2007	(489600)
197	04/02/2007	(532635)
198	04/09/2007	(554546)
199	04/09/2007	(554548)
200	04/12/2007	(543310)
201	04/18/2007	(514268)
202	04/19/2007	(531924)
203	04/19/2007	(531943)
204	04/19/2007	(535999)
205	04/19/2007	(575529)
206	04/24/2007	(555828)
207	04/27/2007	(532788)
208	04/30/2007	(515463)
209	05/07/2007	(511310)
210	05/07/2007	(514793)
211	05/08/2007	(511545)
212	05/08/2007	(511682)
213	05/08/2007	(511841)

214	05/08/2007	(533412)
215	05/08/2007	(557566)
216	05/08/2007	(557567)
217	05/09/2007	(555628)
218	05/10/2007	(558404)
219	05/10/2007	(558512)
220	05/11/2007	(462109)
221	05/14/2007	(398934)
222	05/14/2007	(516545)
223	05/14/2007	(516561)
224	05/14/2007	(516563)
225	05/14/2007	(559614)
226	05/14/2007	(559653)
227	05/16/2007	(680309)
228	05/17/2007	(513875)
229	05/18/2007	(554549)
230	05/21/2007	(538079)
231	05/23/2007	(560258)
232	05/24/2007	(575532)
233	05/25/2007	(560273)
234	05/25/2007	(560284)
235	05/25/2007	(560311)
236	05/25/2007	(561809)
237	05/25/2007	(561826)
238	05/25/2007	(561833)
239	05/31/2007	(541434)
240	05/31/2007	(561026)
241	05/31/2007	(561133)
242	06/01/2007	(562217)
243	06/01/2007	(562270)
244	06/08/2007	(515992)
245	06/11/2007	(555138)
246	06/18/2007	(639497)
247	06/21/2007	(575535)
248	06/22/2007	(563821)
249	06/22/2007	(563870)
250	06/25/2007	(556660)
251	06/26/2007	(556265)
252	06/26/2007	(557013)
253	07/03/2007	(565234)
254	07/09/2007	(564733)
255	07/11/2007	(532793)
256	07/16/2007	(561727)
257	07/16/2007	(563110)
258	07/18/2007	(575538)
259	07/31/2007	(564288)
260	08/06/2007	(564280)
261	08/06/2007	(568639)
262	08/06/2007	(568658)
263	08/09/2007	(563748)
264	08/09/2007	(564283)
265	08/09/2007	(570823)
266	08/10/2007	(563126)
267	08/13/2007	(571129)
268	08/13/2007	(571130)
269	08/14/2007	(568640)
270	08/14/2007	(568679)
271	08/15/2007	(570829)
272	08/15/2007	(571282)
273	08/16/2007	(543314)

274	08/16/2007	(563635)
275	08/21/2007	(601683)
276	08/28/2007	(572069)
277	08/30/2007	(568613)
278	08/31/2007	(512665)
279	08/31/2007	(543556)
280	08/31/2007	(568778)
281	09/05/2007	(571679)
282	09/06/2007	(573171)
283	09/07/2007	(571291)
284	09/07/2007	(573940)
285	09/13/2007	(639567)
286	09/20/2007	(601684)
287	09/28/2007	(564652)
288	09/28/2007	(564703)
289	09/28/2007	(565429)
290	10/01/2007	(639530)
291	10/01/2007	(639548)
292	10/01/2007	(639562)
293	10/03/2007	(543554)
294	10/03/2007	(573174)
295	10/03/2007	(574254)
296	10/04/2007	(594925)
297	10/10/2007	(566738)
298	10/10/2007	(567008)
299	10/11/2007	(567653)
300	10/12/2007	(571215)
301	10/15/2007	(567828)
302	10/15/2007	(597177)
303	10/17/2007	(601685)
304	10/18/2007	(569770)
305	10/18/2007	(569776)
306	10/18/2007	(569781)
307	10/18/2007	(569785)
308	10/18/2007	(569841)
309	10/19/2007	(594927)
310	10/23/2007	(566959)
311	10/25/2007	(594923)
312	10/25/2007	(594929)
313	10/25/2007	(597157)
314	10/26/2007	(570354)
315	10/26/2007	(573825)
316	10/26/2007	(574064)
317	10/26/2007	(597159)
318	11/02/2007	(574293)
319	11/05/2007	(595620)
320	11/05/2007	(595623)
321	11/07/2007	(573328)
322	11/08/2007	(639482)
323	11/08/2007	(639492)
324	11/08/2007	(639514)
325	11/09/2007	(596374)
326	11/15/2007	(597987)
327	11/19/2007	(619609)
328	11/21/2007	(569810)
329	11/26/2007	(567381)
330	11/26/2007	(568480)
331	11/26/2007	(570030)
332	11/26/2007	(570031)
333	11/27/2007	(570515)

334	11/27/2007	(570526)
335	11/27/2007	(599343)
336	11/27/2007	(608728)
337	11/28/2007	(568431)
338	11/30/2007	(596467)
339	12/04/2007	(596985)
340	12/07/2007	(573480)
341	12/07/2007	(597234)
342	12/12/2007	(602163)
343	12/13/2007	(573122)
344	12/18/2007	(619610)
345	12/19/2007	(599266)
346	12/19/2007	(612289)
347	12/20/2007	(598138)
348	12/21/2007	(567605)
349	01/03/2008	(613134)
350	01/09/2008	(597713)
351	01/09/2008	(597717)
352	01/09/2008	(597720)
353	01/10/2008	(595622)
354	01/10/2008	(595628)
355	01/17/2008	(595617)
356	01/17/2008	(619611)
357	01/24/2008	(614965)
358	01/28/2008	(610685)
359	01/29/2008	(615960)
360	01/30/2008	(613449)
361	01/30/2008	(613921)
362	01/31/2008	(613922)
363	02/06/2008	(616278)
364	02/06/2008	(616428)
365	02/11/2008	(615351)
366	02/11/2008	(616039)
367	02/11/2008	(616044)
368	02/11/2008	(616066)
369	02/11/2008	(616069)
370	02/11/2008	(616074)
371	02/11/2008	(617102)
372	02/13/2008	(566562)
373	02/13/2008	(610665)
374	02/15/2008	(617796)
375	02/21/2008	(672136)
376	02/27/2008	(613204)
377	02/27/2008	(613391)
378	03/03/2008	(617333)
379	03/05/2008	(637300)
380	03/06/2008	(595630)
381	03/10/2008	(617583)
382	03/10/2008	(619156)
383	03/13/2008	(614400)
384	03/13/2008	(672137)
385	03/18/2008	(615813)
386	03/18/2008	(615931)
387	03/28/2008	(617344)
388	04/03/2008	(618253)
389	04/04/2008	(638867)
390	04/04/2008	(638869)
391	04/15/2008	(510759)
392	04/16/2008	(617688)
393	04/16/2008	(672138)

394	04/21/2008	(646462)
395	04/23/2008	(653894)
396	04/30/2008	(636279)
397	05/02/2008	(571287)
398	05/02/2008	(640190)
399	05/06/2008	(637948)
400	05/15/2008	(640191)
401	05/16/2008	(638424)
402	05/16/2008	(640170)
403	05/17/2008	(657073)
404	05/20/2008	(690043)
405	05/21/2008	(640193)
406	05/23/2008	(639898)
407	05/27/2008	(726020)
408	05/27/2008	(726022)
409	05/27/2008	(726398)
410	06/02/2008	(638228)
411	06/05/2008	(682036)
412	06/10/2008	(573942)
413	06/10/2008	(646379)
414	06/13/2008	(682091)
415	06/16/2008	(690044)
416	06/25/2008	(681430)
417	06/30/2008	(669890)
418	07/01/2008	(683482)
419	07/02/2008	(618777)
420	07/03/2008	(683481)
421	07/03/2008	(684038)
422	07/07/2008	(618795)
423	07/07/2008	(641624)
424	07/07/2008	(654362)
425	07/07/2008	(681433)
426	07/09/2008	(684176)
427	07/11/2008	(684580)
428	07/18/2008	(685963)
429	07/18/2008	(686024)
430	07/18/2008	(690045)
431	07/21/2008	(687078)
432	07/23/2008	(687195)
433	07/30/2008	(686426)
434	08/04/2008	(687176)
435	08/07/2008	(680041)
436	08/07/2008	(681762)
437	08/08/2008	(688099)
438	08/11/2008	(681763)
439	08/15/2008	(710823)
440	08/20/2008	(610600)
441	08/22/2008	(636773)
442	08/26/2008	(699841)
443	08/27/2008	(636747)
444	08/27/2008	(680057)
445	08/27/2008	(687896)
446	08/28/2008	(612382)
447	08/29/2008	(687897)
448	08/29/2008	(701063)
449	08/29/2008	(701692)
450	09/10/2008	(702501)
451	09/23/2008	(710824)
452	10/02/2008	(681432)
453	10/09/2008	(699820)

454	10/09/2008	(703861)
455	10/15/2008	(710825)
456	11/03/2008	(703911)
457	11/07/2008	(701151)
458	11/10/2008	(700025)
459	11/12/2008	(638231)
460	11/18/2008	(706502)
461	11/19/2008	(727541)
462	12/05/2008	(670691)
463	12/08/2008	(688084)
464	12/08/2008	(709795)
465	12/16/2008	(750355)
466	01/15/2009	(707626)
467	01/15/2009	(727542)
468	01/20/2009	(707895)
469	01/20/2009	(707915)
470	01/29/2009	(681611)
471	01/29/2009	(722822)
472	01/30/2009	(703338)
473	01/30/2009	(708374)
474	02/03/2009	(723666)
475	02/10/2009	(726245)
476	02/13/2009	(721115)
477	02/17/2009	(726413)
478	02/18/2009	(750352)
479	02/24/2009	(705417)
480	02/27/2009	(723999)
481	03/03/2009	(726864)
482	03/03/2009	(726950)
483	03/03/2009	(726951)
484	03/03/2009	(726952)
485	03/10/2009	(724362)
486	03/11/2009	(708431)
487	03/13/2009	(750353)
488	03/16/2009	(723008)
489	03/17/2009	(684690)
490	03/17/2009	(721122)
491	03/19/2009	(702111)
492	03/19/2009	(739266)
493	03/23/2009	(738607)
494	04/06/2009	(725607)
495	04/08/2009	(703324)
496	04/08/2009	(703330)
497	04/16/2009	(737836)
498	04/16/2009	(750354)
499	04/20/2009	(724370)
500	04/20/2009	(741788)
501	04/22/2009	(742156)
502	04/23/2009	(724372)
503	04/24/2009	(724369)
504	04/24/2009	(742160)
505	04/27/2009	(742142)
506	05/05/2009	(740736)
507	05/20/2009	(768419)
508	05/26/2009	(739079)
509	05/27/2009	(741025)
510	05/28/2009	(736749)
511	06/01/2009	(741004)
512	06/05/2009	(703325)
513	06/08/2009	(747518)

514	06/08/2009	(747585)
515	06/08/2009	(747670)
516	06/08/2009	(747671)
517	06/08/2009	(747672)
518	06/08/2009	(747673)
519	06/08/2009	(747680)
520	06/08/2009	(747690)
521	06/08/2009	(747696)
522	06/08/2009	(747699)
523	06/08/2009	(747700)
524	06/08/2009	(747703)
525	06/08/2009	(748143)
526	06/08/2009	(748148)
527	06/08/2009	(748161)
528	06/08/2009	(748237)
529	06/10/2009	(721172)
530	06/10/2009	(740687)
531	06/11/2009	(768420)
532	06/15/2009	(745452)
533	06/16/2009	(721240)
534	06/17/2009	(703327)
535	06/18/2009	(749854)
536	06/25/2009	(736274)
537	06/29/2009	(742139)
538	07/01/2009	(738610)
539	07/09/2009	(761495)
540	07/16/2009	(749826)
541	07/20/2009	(742162)
542	07/22/2009	(763032)
543	07/24/2009	(747246)
544	07/24/2009	(761878)
545	07/27/2009	(738993)
546	07/27/2009	(763714)
547	07/31/2009	(804862)
548	08/04/2009	(761464)
549	08/06/2009	(724363)
550	08/06/2009	(747387)
551	08/11/2009	(740758)
552	08/11/2009	(765363)
553	08/12/2009	(761394)
554	08/12/2009	(761395)
555	08/13/2009	(721183)
556	08/17/2009	(747034)
557	08/18/2009	(737079)
558	08/18/2009	(747013)
559	08/20/2009	(804863)
560	08/25/2009	(761298)
561	08/31/2009	(767261)
562	09/03/2009	(759159)
563	09/03/2009	(760864)
564	09/04/2009	(761102)
565	09/17/2009	(776464)
566	09/22/2009	(804864)
567	09/24/2009	(777334)
568	10/06/2009	(765800)
569	10/09/2009	(766603)
570	10/12/2009	(767413)
571	10/14/2009	(779037)
572	10/15/2009	(746875)
573	10/19/2009	(804865)

574	10/23/2009	(737253)
575	10/28/2009	(746879)
576	11/02/2009	(780305)
577	11/06/2009	(780727)
578	11/18/2009	(767570)
579	11/18/2009	(804866)
580	11/19/2009	(778896)
581	11/20/2009	(778669)
582	11/30/2009	(767571)
583	12/02/2009	(778760)
584	12/03/2009	(778761)
585	12/03/2009	(778762)
586	12/09/2009	(781124)
587	12/10/2009	(784535)
588	12/10/2009	(784555)
589	12/11/2009	(784729)
590	12/14/2009	(767533)
591	12/15/2009	(784097)
592	12/15/2009	(804867)
593	12/28/2009	(786681)
594	01/06/2010	(780356)
595	01/19/2010	(804868)
596	01/25/2010	(782608)
597	01/26/2010	(783566)
598	01/27/2010	(789879)
599	02/03/2010	(788653)
600	02/03/2010	(789492)
601	02/09/2010	(789348)
602	02/11/2010	(789488)
603	02/17/2010	(789487)
604	02/17/2010	(792069)
605	02/19/2010	(789491)
606	02/22/2010	(789345)
607	02/22/2010	(804861)
608	02/23/2010	(789349)
609	02/23/2010	(789490)
610	02/24/2010	(791883)
611	03/03/2010	(784740)
612	03/09/2010	(789430)
613	03/12/2010	(791729)
614	03/17/2010	(789346)
615	03/22/2010	(830960)
616	03/23/2010	(781130)
617	03/30/2010	(767542)
618	03/31/2010	(790100)
619	03/31/2010	(795390)
620	04/02/2010	(789344)
621	04/02/2010	(789347)
622	04/02/2010	(790089)
623	04/05/2010	(790092)
624	04/08/2010	(794302)
625	04/09/2010	(790086)
626	04/12/2010	(790080)
627	04/12/2010	(790094)
628	04/15/2010	(790078)
629	04/16/2010	(830961)
630	04/19/2010	(784861)
631	04/21/2010	(790102)
632	04/21/2010	(790104)
633	04/23/2010	(760558)

634	04/26/2010	(790223)
635	05/07/2010	(792699)
636	05/07/2010	(797403)
637	05/10/2010	(798066)
638	05/12/2010	(800460)
639	05/14/2010	(795204)
640	05/17/2010	(798932)
641	05/19/2010	(799233)
642	05/20/2010	(797395)
643	05/20/2010	(830962)
644	05/26/2010	(802223)
645	05/26/2010	(824730)
646	06/07/2010	(784758)
647	06/11/2010	(799638)
648	06/11/2010	(802341)
649	06/14/2010	(824802)
650	06/16/2010	(794178)
651	06/16/2010	(801231)
652	06/16/2010	(802833)
653	06/17/2010	(798009)
654	06/17/2010	(803089)
655	06/17/2010	(824465)
656	06/17/2010	(846293)
657	06/18/2010	(801241)
658	06/18/2010	(825644)
659	06/22/2010	(802359)
660	06/24/2010	(801544)
661	06/25/2010	(799641)
662	06/25/2010	(803157)
663	06/28/2010	(794062)
664	06/28/2010	(802835)
665	07/07/2010	(828931)
666	07/09/2010	(803093)
667	07/12/2010	(828930)
668	07/14/2010	(827163)
669	07/14/2010	(841193)
670	07/15/2010	(799639)
671	07/21/2010	(794057)
672	07/21/2010	(842057)
673	07/23/2010	(803101)
674	07/28/2010	(802837)
675	08/02/2010	(830473)
676	08/04/2010	(844368)
677	08/12/2010	(803144)
678	08/12/2010	(803145)
679	08/19/2010	(824878)
680	08/20/2010	(803091)
681	08/20/2010	(826373)
682	08/24/2010	(850180)
683	08/25/2010	(850342)
684	08/26/2010	(841818)
685	08/27/2010	(767572)
686	08/31/2010	(841819)
687	09/01/2010	(857972)

E. Written notices of violations (NOV). (CCEDS Inv. Track. No.)

Date: 09/30/2005 (575543)
 Self Report? YES Classification: Moderate
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)
 TWC Chapter 26 26.121(a)
 Description: Failure to meet the limit for one or more permit parameter

Date: 10/31/2005 (575545) CN600356976
 Self Report? YES Classification: Moderate
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)
 TWC Chapter 26 26.121(a)
 Description: Failure to meet the limit for one or more permit parameter

Date: 01/17/2006 (593182) CN600356976
 Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)
 30 TAC Chapter 305, SubChapter F 305.125(17)
 Description: NON-RPT VIOS FOR MONIT PER OR PIPE

Date: 03/02/2006 (431805) CN600356976
 Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter B 115.126(1)(A)(i)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT U 63.506(d)
 Description: Failure to store required data from November 1, 2004 to November 3, 2004.
 Self Report? NO Classification: Moderate
 Citation: # 3320, General Provision 7 E PERMIT
 30 TAC Chapter 116, SubChapter B 116.115(b)(2)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
 Description: Failure to maintain a plug on an open ended line.

Date: 03/27/2006 (374721) CN600356976
 Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 101, SubChapter F 101.221(a)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)
 5C THC Chapter 382, SubChapter A 382.085(b)
 TCEQ Air Permit 22072 - SC 4 PERMIT
 Description: During Dow Inc. No. 80470 Dow sent emissions to an unlit flare.
 Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter A 382.085(b)
 TCEQ Air Permit 22072 - SC 1 PERMIT
 Description: During Dow Inc No. 92568 Dow did not determine the status of the salt dome prior to drilling.
 Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
 30 TAC Chapter 101, SubChapter F 101.221(a)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Flexible Air Permit 20432 SC III-1 & -21 PERMIT
 Description: During Dow Incident 92771 the flame of the flare was not present.
 Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Flexible Air Permit 20432 SC III-1 PERMIT
 Description: During Dow Incident 94567 (Inv 374721) a valve was inadvertently opened.
 Self Report? NO Classification: Moderate

Citation:	30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter A 382.085(b) Flexible Air Permit 20432 SC III-1 PERMIT	
Description:	Incident 51360 at Dow was an avoidable emissions event.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter A 382.085(b) Flexible Air Permit 20432 SC III-1 PERMIT	
Description:	Dow had an avoidable emissions event during Incident 94909.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) Permit 48813 - SC 1 PERMIT	
Description:	During Incidents 84700, 84701, and 93405 Dow had avoidable emissions events	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 48813 Special Condition 1 PERMIT 5C THC Chapter 382, SubChapter A 382.085(b)	
Description:	During Recordable Incident 95308, Dow had an avoidable emissions event.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 48813 SC 1 PERMIT 5C THC Chapter 382, SubChapter A 382.085(b)	
Description:	Dow had an avoidable emissions event during recordable Incident 90045.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 48813 Special Condition 1 PERMIT 5C THC Chapter 382, SubChapter A 382.085(b)	
Description:	Dow had an avoidable emissions event during recordable Incident 101031.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) 834 Special Condition 1 PERMIT	
Description:	Incident 83616 at Dow was avoidable.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) 834 Special Condition 1 PERMIT	
Description:	Dow Incident 88672 was an avoidable emissions event.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) 834 Special Condition 1 PERMIT	
Description:	Dow Incident 89747 was an avoidable emissions event.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) 834 Special Condition 1 PERMIT	
Description:	Dow Incident 93432 was an avoidable incident.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) 834 Special Condition 1 PERMIT	
Description:	Dow Incident 93975 was an avoidable emissions event.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) 834 Special Condition 1 PERMIT	
Description:	Dow Incident 95602 was an avoidable emissions event.	
Self Report?	NO	Classification: Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 5C THC Chapter 382, SubChapter A 382.085(b) 834 Special Condition 1 PERMIT	
Description:	Dow Incident 97687 was an avoidable emissions event.	
Self Report?	NO	Classification: Minor
Citation:	30 TAC Chapter 101, SubChapter A 101.20(2) 30 TAC Chapter 115, SubChapter D 115.352(4)	

30 TAC Chapter 115, SubChapter H 115.783(5)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)

Description: Failure to equip each open-ended valve or line with a cap, blind flange, plug, or second valve. Two valves at Furnace F-7 with monitoring tag Nos 193757 and 197365 were observed with open-ended lines during the on-site investigation.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 115, SubChapter H 115.783(5)
 30 TAC Chapter 116, SubChapter B 116.115(c)

Description: Failure to equip each open-ended valve or line with a cap, blind flange, plug, or second valve. An open ended line in HRVOC service at the R102/S102 bay wall area was observed during the on-site investigation.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 115, SubChapter H 115.783(5)
 30 TAC Chapter 116, SubChapter B 116.115(c)

Description: Failure to equip each open-ended valve or line with a cap, blind flange, plug, or second valve. An open ended line in HRVOC service at the R102/S102 bay wall area was observed during the on-site investigation.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(2)
 30 TAC Chapter 115, SubChapter D 115.354
 30 TAC Chapter 115, SubChapter H 115.781(b)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(a)

Description: Failure to demonstrate that each applicable HRVOC valve in the process unit was monitored in accordance with the requirements described in 30 TAC § 115.354, as directed by 30 TAC § 115.781(b).
 Failure to demonstrate that each applicable HRVOC valve in the process unit was monitored in accordance with the requirement

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354
 30 TAC Chapter 115, SubChapter H 115.781(b)

Description: Failure to demonstrate that at least ten unmarked valves in HRVOC service were complying with the monitoring requirements described in the applicable sections of 30 TAC " 115.354 and 115.781(b). Ten unmarked valves in HRVOC service were subsequently numbered in the field with monitoring program identification numbers

Date: 04/18/2006 (433179)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)
 30 TAC Chapter 101, SubChapter F 101.201(b)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter A 382.085(b)
 TCEQ Air Permit 2008, SC1 PERMIT

Description: Failure to notify and report in a timely manner following a reportable emissions event (Incident No. 64153).

Date: 04/20/2006 (459137)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 117, SubChapter B 117.206(e)(2)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Permit 46306, Special Condition 7(C) PERMIT

Description: Exceeded permitted limits of ammonia (NH3). Violation of Permit # 46306 Special Condition 7(C), 30 TAC 117.206 (e)(2), 30 TAC 116.115 (c), and 5 THC Chapter 382.085(b).

Date: 04/26/2006 (433177)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter D 382.085(b)
 TCEQ Air Permit No. 2008, SC 1 PERMIT

Description: Failure to provide a backup dempster resulting in unauthorized emississions.(
Incident No. 64154)

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(A)

Description: Dow did not report in a timely manner during Incident 64154.

Date: 06/22/2006 (458889) CN600356976

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC III-5 PERMIT
Title V O-02213, SC 16 OP

Description: Dow failed to meet the NOx emissions hourly standard of 0.1 lb/MMBtu 87 times,
and the CO emissions hourly standard of 0.034 lb/MMBtu 276 times from
Pyrolysis Furnace Nos. 1 through 7 (OC6L8H1~7) as required by NSR Permit
20432, Special Condition (SC) III-5.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC III-6 PERMIT
Title V O-02213, SC 16 OP

Description: Dow failed to meet the NOx emissions hourly standard of 0.06 lb/MMBtu 301
times, and the CO emissions hourly standard of 0.015 lb/MMBtu 47 times from
Pyrolysis Furnace Nos. 8 and 10 (OC6L8H8&10) as required by NSR Permit
20432, SC III-6.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC 1E PERMIT
Title V O-02213, SC 1A and 16 OP

Description: Dow failed to equip open-ended lines with a valve or plug on 23 occasions.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC III-1 PERMIT
Title V O-02213, SC 16 OP

Description: Dow failed to meet the permit allowables 4 times for NOx and 2 times for CO from
Gas Turbine GT-30 (B72L7GT30).

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC 4 PERMIT
Title V O-02213, SC 16 OP

Description: Dow failed to meet the specified requirement of 300 BTU/SCF for the Flare
B60L7F1 on November 15, 2004.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.354(a)(2)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: that Dow failed to record daily review of the operating parameters for 8 days as
required by 40 CFR 61.354(a)(2).

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)

5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 15 OP

Description: Dow failed to collect flare pilot monitoring data for the Flares FS-1 and FX-1000
(OC6L8F1, and OC6L8F1000) on four occasions, and failed for the Flare
B71S2F1 on three occasions.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT RRR 60.702(a)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to route off gas from the processes subject to 40 CFR 60 Subpart RRR to its primary control device Furnaces OC6L8S1 thru OC6L8S10. The off gas was routed to the Flares OC6L8F1000 and OC6L8F1 on nineteen occasions.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.6(e)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 10C OP

Description: Dow failed to follow precisely the written startup, shutdown, and malfunction plan on three occurrences.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.6(e)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 10C OP

Description: Dow failed to update the written startup, shutdown, and malfunction plan as required.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-7(a)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC III-3B PERMIT
Title V O-02213, SC 1A and 16 OP

Description: Dow failed to monitor nine valves on six monthly monitoring activities during the period of April 19, 2004 through September 15, 2004.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 3B(iii) OP

Description: Dow failed to keep records of visible emissions observations for ten furnaces, one thermal oxidizer and one decoke vent during the 3rd quarter of 2004.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter B 115.132(a)(1)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to maintain the compartment totally enclosed and have all openings sealed for the Water Separator OC6L8D27 as one leaking connector was noted between October 14, 2004 and October 19, 2004.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(2)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-6(a)(2)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC 1E PERMIT
Title V O-02213, SC 1A and 16 OP

Description: Dow failed to equip open-ended lines with a valve or plug on four occasions.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7(c)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-7(c)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20432, SC 1F PERMIT
Title V O-02213, SC 1A and 16 OP

Description: Dow failed to monitor 97 valves and 8 flanges on two quarterly monitoring activities during the period of April 19, 2004 through October 18, 2004.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.343(a)(1)(i)(A)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.347(a)(1)(i)(A)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to perform annual fugitive monitoring of components of the benzene waste management units on an annual basis.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.354(a)(2)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to inspect daily the operating parameters for benzene waste operations for 20 days to ensure proper operations.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(3)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to perform one weekly visual inspection of pumps as required.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-2(a)(2)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to perform 13 weekly visual inspections of pumps as required.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.354(3)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to perform nine weekly visual inspections of flanges as required.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 21596, SC 11E PERMIT
Title V O-02213, SC 1A and 16 OP

Description: Dow failed to equip open-ended lines with a valve or plug on 10 occasions.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.354(f)(1)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A ORDER

Description: Dow failed to perform monthly visual car-seal inspections on Benzene Waste Management Units' closed vent system in September and October of 2004.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(4)(A)(ii)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02213, SC 1A OP

Description: Dow failed to perform eight daily visual flare observations as required.

Date: 07/14/2006 (457318)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 654, SC 4 PERMIT
Title V O-02203, SC 14 OP

Description: Dow failed to install a pressure gauge or its equivalent between the rupture disk and the pressure safety valve on T-4 Tower.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 654, SC 10E PERMIT
Title V O-02203, SC 1A and 14 OP

Description: Dow failed to equip open-ended lines with plugs/caps on two occasions.

Date: 07/18/2006 (462748) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)
Special Condition 7(c) PERMIT

Description: Failure to meet permitted ammonia emission standard.

Date: 07/18/2006 (462746) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)

Description: Ammonia limit exceedence. Violation of permit #46306 SC 7, 30 TAC 116.115(c), and 5 THC Chapter 382.085(b).

Date: 07/21/2006 (457258) CN600356976

Self Report? NO Classification: Minor

Citation: 18561, SC 6E PERMIT
30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02221, STC 12 OP
O-02221, STC 1A OP

Description: Failure to cap or plug the Twelve (12) open-ended lines in VOC service in Specialty Chemicals 2 Unit.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)(4)
30 TAC Chapter 122, SubChapter C 122.222(k)(3)
5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failure to register the PBRs 106.261 and 106.262 within 10 days of increase in VOC emissions of 0.79 lbs/hr and 0.85 tons per year as a result of production of new line of products and failed to submit off-permit notification concurrently.

Self Report? NO Classification: Minor

Citation: 18561, SC 17 PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02221, STC 12 OP

Description: Failure to maintain minimum flow rate of 10 gallons per minute (gpm) of water as required by NSR permit 18561, Special Condition 17 for the SC-2 kettle scrubber (EPN B13SV3).

Date: 08/11/2006 (457284) CN600356976

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 117, SubChapter B 117.216(a)(5)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02216, SC 6C OP

Description: Dow failed to include the specific rule citation for any unit with a claimed exemption from the emission specification of §117.206 in the final NOx control report submitted on March 31, 2005.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20525, SC 15E PERMIT

NSR 46429, SC 12E PERMIT
NSR 46431, SC 13E PERMIT
Title V O-02216, SC 1A and 15 OP

Description: Dow failed to equip open-ended lines in hazardous air pollutant (HAP) with plugs/caps on fourteen occasions.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.354(3)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(3)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 46431, SC 13E PERMIT
Title V O-02216, SC 1A and 15 OP

Description: Dow failed to conduct one weekly fugitive inspection by visual, audible, and/or olfactory means.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR Permit 46431, SC 21 PERMIT
Title V Permit O-02216, SC 15 OP

Description: Dow failed to conduct daily analysis on the selective catalytic reduction (SCR) unit on four occasions.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 117, SubChapter B 117.211(a)(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02216, SC 1A OP

Description: Dow failed to conduct stack sampling on the furnace exhaust stack (EPN A36S621) within 60 days of startup of the emissions control.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR Permit 46431, SC 17 PERMIT
Title V Permit O-02216, SC 15 OP

Description: Dow failed to maintain the pH in the scrubber (EPN A36S531) at 7.5 or greater on two occasions.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.7(a)(2)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR Permit 46431, SC 12C PERMIT
Title V Permit O-02216, SC 10D and 15 OP

Description: Dow failed to conduct performance test on the thermal treatment unit (TTU) and the tail scrubber (EPN A36S531) within 180 days as required by 40 CFR 63.7(a) (2) and 63.116(c), and as required by NSR Permit 46431, SC 12C.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR Permit 46431, SC 22A PERMIT
Title V Permit O-02216, SC 15 OP

Description: Dow failed to monitor the carbon bed during unloading operation for the tank (EPN A40S741).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR Permit 2008, SC 1 PERMIT
Title V Permit O-02216, SC 15 OP

Description: NOx, CO, SO2 emissions in lb/hr from the flare (EPN B4F19A) exceeded the allowables specified in the Maximum Allowable Emission Rate Table for NSR Permit 2008 during a period from January 10, 2005 through March 13, 2005.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter A 382.085(b)
 NSR Permit 2008, SC 9 PERMIT
 Title V Permit O-02216, SC 15 OP

Description: Dow failed to maintain the minimum requirement of 300 BTU/scf for the flare (EPN B4F19A) during a period from January 10, 2005 through June 10, 2005.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter A 382.085(b)
 NSR Permit 2008, SC 14E PERMIT
 Title V Permit O-02216, SC 1A and 15 OP

Description: Dow failed to equip one open-ended line in VOC service with a cap or plug.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter B 115.112(a)(1)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Title V Permit O-02216, SC 1A and 14 OP

Description: Dow failed to maintain pilots for the flare (EPNA36MDF532), which was used as a control device for tank vents V-103 and V-534 at the time the pilots went out on September 19, 2005.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter A 382.085(b)
 Title V Permit O-02216, SC 14 OP

Description: Dow failed to keep two monthly inspection records for the degreaser (A36MDSC1).

Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(d)(2)
 5C THC Chapter 382, SubChapter A 382.085(b)
 NSR Permit 46431, SC 13F PERMIT
 Title V Permit O-02216, SC 1A and 15 OP

Description: Dow failed to monitor 107 valves during the first and second quarters of 2005.

Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(b)(2)
 5C THC Chapter 382, SubChapter A 382.085(b)
 NSR Permit 46431, SC 14A PERMIT
 Title V Permit O-02216, SC 1A and 15 OP

Description: Dow failed to monitor 324 connectors during the first and second quarters of 2005.

Date: 08/18/2006 (465699)

Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THC Chapter 382, SubChapter D 382.085(b)
 TCEA Air Permit No. 21596, SC 1 PERMIT

Description: Dow had an avoidable emissions event during Incident No. 73674.

Date: 08/19/2006 (480155) CN600356976

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 113, SubChapter C 113.130
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
 5C THC Chapter 382, SubChapter A 382.085(b)
 FOP# O-02205, Special Condition #10 OP
 NSR Permit #20774, Special Condition 10E PA

Description: Failure to cap 6 open-ended valves/lines in HAP service per 63.167(a)(1).

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
FOP# O-02205, Special Condition #11 OP
FOP# O-02205, Special Condition #1A OP
NSR Permit 20774, Special Condition #10E PA

Description: Failure to cap one open-ended valve or line in general VOC service as required by 115.352(4).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
FOP# O-02205, Special Condition #9 OP

Description: Failure to limit the outlet gas temperature of PT-110 to 95 degrees fahrenheit during venting operations.

Date: 08/22/2006 (484727) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter A 335.9(a)(2)
VII.A.1. PERMIT

Description: Failure to report the burning of Waste Stream 2196219H in Boiler B-901 (NOR 089) on the 2005 Annual Waste Summary.

Date: 08/23/2006 (457315) CN600356976

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20909, SC 5 PERMIT
Title V O-02211, SC 14 OP

Description: Dow failed to install pressure indicators for all vent streams from process vessels that are routed to an emissions control device so that the pressure indicators would indicate positive flows from the vessels to the primary thermal oxidizer (EPN B35EWS200).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 20909, SC 8 PERMIT
Title V O-02211, SC 14 OP

Description: Dow failed to operate upset diverter valves and the backup oxidizer start-up automatically when a diversion is needed from the primary thermal oxidizer (EPN B35EWS200) to the backup thermal oxidizer (EPN B34EWS201).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 117, SubChapter B 117.216(a)(5)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02211, SC 6C OP

Description: Dow failed to include the specific rule citation for any unit with a claimed exemption from the emission specification of §117.206 in the final NOx control report.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
NSR 313, SC 14 PERMIT
Title V O-02211, SC 14 OP

Description: Dow failed to record fan amperage readings once every shift.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT DD 63.697(b)(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02211, SC 1A OP

Description: Dow failed to submit the required semiannual report within the time frame allowed.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.6(e)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02211, SC 11C OP

Description: Dow failed to follow malfunction procedure as it was written during a malfunction of a flow meter.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 117, SubChapter B 117.219(d)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02211, SC 1A OP

Description: Dow failed to submit the required semiannual report within the time frame allowed.

Date: 08/23/2006 (457302)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 106, SubChapter A 106.6(b)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02218, SC 6 OP

Description: Dow failed to equip 23 open-ended lines with caps or plugs as fugitive emissions were represented and authorized through Permit by Rule (PBR) 106.262.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 106, SubChapter K 106.262(3)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter A 382.085(b)
Title V O-02218, SC 6 OP

Description: Dow failed to provide notification using Form PI-7 within ten days following the modification of the facility.

Date: 08/23/2006 (484737)

CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter F 335.152(a)(18)
40 CFR Chapter 264, SubChapter I, PT 264, SubPT BB 264.1052(e)
VI.A.21.a. PERMIT

Description: Failure to conduct annual monitoring for fugitive emissions from Pump MP-506.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter F 335.152(a)(18)
40 CFR Chapter 264, SubChapter I, PT 264, SubPT BB 264.1061(b)(2)
VI.A.21.a. PERMIT

Description: Failure to provide the notification and perform annual monitoring of valves in light liquid service.

Date: 08/28/2006 (497117)

CN600356976

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THC Chapter 382, SubChapter A 382.085(b)
FOP #O-02206, Special Condition #11 OP
FOP #O-02206, Special Condition #1A OP
NSR Permit 2773, Special Condition #12E PA

Description: Failure to cap 53 open-ended valves or lines in HAP service.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(f)(1)
5C THC Chapter 382, SubChapter D 382.085(b)
FOP #O-02006, Special Condition #1A OP
FOP #O-02206, Special Condition #11 OP
NSR Permit 2472, Special Condition #9.I PA
NSR Permit 2773, Special Condition #12.I PA

Description: Failure to perform Method 21 remonitoring to three valves in HAP service within 15 days.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(c)(1)
 FOP #O-02206, Special Condition #11 OP
 FOP #O-02206, Special Condition #1A OP
 NSR Permit #2472, Special Condition #9.I PA

Description: Failure to remonitor the P-206 pump seal, after repairs, within 15 days.
 Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(d)
 5C THC Chapter 382, SubChapter A 382.085(b)
 FOP #O-02006, Special Condition #11 OP
 FOP #O-02206, Special Condition #1A OP
 NSR Permit 2472, Special Condition #9.I PA

Description: Failure to remonitor four flanges in HAP service, after completion of repairs, within 15 days.

Date: 08/31/2006 (457309) CN600356976

Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter D 382.085(b)
 O-2710, Special Condition 3(B)(iii) OP

Description: Failure to conduct the visible emissions observations for the units in B6200, B4300 area during the compliance years 2004 and 2005.

Self Report? NO Classification: Moderate
 Citation: 20432, Special Condition I-38.c PERMIT
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter D 382.085(b)
 O-02207, Special Condition 14 OP

Description: Failure to conduct the quarterly cylinder gas audit (CGA) analysis of the continuous emissions monitoring system (CEMS) for the EPN B62CB1.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 3434, Special Condition 27.B PERMIT
 5C THC Chapter 382, SubChapter D 382.085(b)
 O-02207, Special Condition 14 OP

Description: Failure to maintain the sulfur content of the waste oils burned in the boilers below 50 ppmw.

Self Report? NO Classification: Minor
 Citation: 20432, Special Condition 1.E PERMIT
 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 3434, Special Condition 7.E PERMIT
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
 5C THC Chapter 382, SubChapter D 382.085(b)
 O-02207, Special Condition 14 OP
 O-02207, Special Condition 1A OP

Description: Failure to cap or plug the Eight (8) open-ended lines in VOC service in the O-02207 Title V permit area.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 3434, Special Condition 7.G PERMIT
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
 5C THC Chapter 382, SubChapter D 382.085(b)
 O-02207, Special Condition 14 OP
 O-02207, Special Condition 1A OP

Description: Failure to monitor nine pumps in VHAP service in the O-02207 Title V permit area.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
 30 TAC Chapter 122, SubChapter B 122.145(2)(A)

5C THC Chapter 382, SubChapter D 382.085(b)
O-2207, General Terms & Conditions OP
Description: The RE failed to report some instances of deviations in the deviation report dated November 17, 2005.

Date: 10/12/2006 (515660)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)
TCEQ Air Permit No. 48813, SC 1 PERMIT

Description: Dow failed to prevent an operator error resulting in unauthorized emissions during Incident No. 79109.

Date: 10/25/2006 (509774)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)
5C THC Chapter 382, SubChapter D 382.085(b)
TCEQ Air Permit No. 46429 MAERT PERMIT

Description: Investigation 509774 determined that Dow failed to communicate with a contractor technician properly to prevent unauthorized emissions during Incident 76828.

Date: 11/30/2006 (519472)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)
TCEQ Permit No. 48813, SC 1 PERMIT

Description: Investigation No. 519472 determined that Dow had an avoidable emissions event during Incident No. 79942.

Date: 12/13/2006 (512466)

CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 106, SubChapter K 106.261(a)(7)(B)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02212, SC 16.A. OP

Description: The Dow Chemical Company, Dow Texas Operations Freeport, failed to submit Form PI-7 on March 31, 2005, for the increase of ethylene and propylene emissions to the monitor well flare (BSRSRMW1T). This constitutes a violation of 30 Texas Administrative Code (TAC) § 106.261(a)(7)(B).

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02212, SC 16.A. OP
Permit No. 22072, SC 4 PERMIT

Description: the Dow Chemical Company ("Dow"), Dow Texas Operations Freeport, failed to maintain the minimum heat value for Monitor Well Flare no. 1 (unit I.D. BSRSRFMW1) and Brine Flare 2 (unit I.D. BSRF401).

Date: 12/18/2006 (512614)

CN600356976

Self Report? NO Classification: Minor

Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT SS 63.998(b)
5C THC Chapter 382, SubChapter D 382.085(b)

Description: Dow failed to maintain records of daily average pH data for the T-734 Scrubber System (EPN B84S734) on October 5 and 6, 2005.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 7531, SC 1 PERMIT
Title V O-02210, SC 10 OP

Description: Dow failed to meet the maximum permit allowable of 0.06 lb/hr for Cl2 from the T-734 Scrubber System (EPN B84S734) on the following dates during performance testing: 08-18-05 10:33 to 11:15 0.13 lb/hr; 08-29-05 11:23 to 12:14 0.38 lb/hr; 08-30-05 10:52 to 17:04 1.63 lb/hr; 10/12/05 9:43 to 13:23 0.1 lb/hr

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 106, SubChapter K 106.262
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02210, SC 10 OP

Description: Dow failed to register a minor process modification made in April 2005 under Permits by Rule (PBR) 106.262(a)(3) within ten days following the modification of the facility.

Date: 01/18/2007 (512465)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 117, SubChapter B 117.206(e)(1)(A)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02214, SC 15.A.(i) OP

Description: The Dow Chemical Company, Dow Texas Operations Freeport exceeded the CO limit of 400 ppmv on Boiler No. 5 (Unit ID no. B664PB5, EPN FB-45). This constitutes a violation of 30 TAC 117.206(e)(1).

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02214, SC 9.A. OP
Permit No. 46306, SC 7.C. PERMIT

Description: The Dow Chemical Company, Dow Texas Operations Freeport exceeded the ammonia limit of 10 ppmvd on boiler FB-93 (EPN: B56SB3). This constitutes a violation of Permit no. 46306, PSD-TX-986, and N-059, Special Condition (SC) 7.C.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02214, SC 9.A. OP
Permit No. 46306, SC 1 PERMIT

Description: The Dow Chemical Company, Dow Texas Operations Freeport exceeded the maximum allowable emission rate for NOx for boiler FB-92 (EPN: B56SB2) on March 3, 2006. This constitutes a violation of Permit no. 46306, PSD-TX-986, and N-059, SC 1.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02214, SC 9.A. OP
Permit No. 46306, SC 7.A. PERMIT

Description: The Dow Chemical Company, Dow Texas Operations Freeport exceeded the lb/mmBtu emission rate for NOx for boilers FB-92 (EPN: B56SB2) and FB-94 (EPN: B56SB4) on March 3, 2006. This constitutes a violation of Permit no. 46306, PSD-TX-986, and N-059, SC 7.A.

Date: 02/16/2007 (532501)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(4)(A)(ii)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02219, SC 1.A. OP

Description: Failure to record 188 daily observation of the flare (Unit I.D. B3808F1) beginning February 3, 2006, through September 30, 2006. This constitutes a violation of 30 Texas Administrative Code (TAC) § 111.111(a)(4)(A)(ii).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)

O-02219, SC 2.F. OP

Description: Failure to create a final onsite record of emissions events. This constitutes a violation of 30 TAC § 101.201(b).

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(A)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02219, General Terms and Conditions OP

Description: Failure to report all incidents of deviations as required by 30 TAC § 122.145(2)(A).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT DDD 60.562-2(a)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02219, SC 13.A. OP
Permit No. 20775, SC 7.E. PERMIT

Description: Failure to maintain secondary enclosures on the following open-ended line tag nos. EAI 128564.2, EAI 80701.2, EAI 80353, and 80701.2.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.767(1)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02219, SC 1.I.(iv) OP

Description: Failure to maintain the pressure between on the cooling water side at a minimum of 5 psig for HRVOC greater than the process fluid side for cooling tower B3831CT1.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.725(a)
5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failure to test HRVOC vents in the Research Reactor (BX250RX1).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter C 122.217(a)(2)
5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failure to submit an Application for Minor Permit Revisions prior to operating the Research Reactor (B250RX1).

Date: 02/28/2007 (542323) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)
TCEQ Flex Air Permit No. 20432, SC III-1 PERMIT

Description: Investigation No. 542323 determined that Dow had an avoidable emissions event during Incident No. 84696.

Date: 03/27/2007 (542214)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)
TCEQ Air Permit No. 770, SC 1 PERMIT

Description: Investigation No. 542214 determined that Dow Incident No. 84425 could have been avoided by good operations practices.

Date: 03/31/2007 (553947) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THC Chapter 382, SubChapter D 382.085(b)
TCEQ Air Permit No. 834, SC1 PERMIT

Description: Investigation No. 553947 determined that Dow Incident No. 85437 was caused by operator error. The incident was avoidable.

Date: 04/02/2007 (532635)

Self Report?	NO	Classification:	Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.116(b)(1) 5C THC Chapter 382, SubChapter D 382.085(b)		
Description:	Site failed to represent volatile organic compound (VOC) emissions from Catalyst Mix Tanks D-10, D-10A, D-11, D-11A, D-12, and D-12A (B77APPT10, B77APPT10A, and B77APPT11, B77APPT11A, B77APPT12, and B77APPT12A) in the permit application for NSR Permit 8567.		
Self Report?	NO	Classification:	Minor
Citation:	30 TAC Chapter 101, SubChapter F 101.201(b) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THC Chapter 382, SubChapter D 382.085(b) O-02215, SC 2F OP		
Description:	Site failed to create final records of seven emissions events no later than two weeks after the end of the emissions events.		
Self Report?	NO	Classification:	Minor
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2) 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(e) 5C THC Chapter 382, SubChapter D 382.085(b) NSR 8567, SC 6 PERMIT Title V O-02215, SC 11 OP		
Description:	Site failed to operate the flare (B78APF1) with a flame present for a total of 21 minutes on February 14, 2006.		
Self Report?	NO	Classification:	Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THC Chapter 382, SubChapter D 382.085(b) NSR 8567, SC 1 PERMIT Title V O-02215, SC 11 OP		
Description:	Site failed to maintain the hourly permitted emission limit of 0.34 lbs/hr of VOC for a tank (B78APST5).		
Self Report?	NO	Classification:	Minor
Citation:	30 TAC Chapter 115, SubChapter D 115.352(4) 30 TAC Chapter 115, SubChapter H 115.783(5) 30 TAC Chapter 116, SubChapter B 116.115(c) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THC Chapter 382, SubChapter D 382.085(b) NSR 6803, SC 9E PERMIT NSR 834, SC 9E PERMIT NSR 8567, SC 8E PERMIT Title V O-02215, SC 11 OP Title V O-02215, SC 1F(v) OP		
Description:	Site failed to equip five open-ended lines with plugs/blinds. The regulated entity also discovered to fail to equip nine open-ended lines with second valves/plugs on the non-threaded drain lines of D-10, D-11, and D-12 on May 11, 2006.		
Self Report?	NO	Classification:	Minor
Citation:	30 TAC Chapter 115, SubChapter H 115.781(c)(1) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THC Chapter 382, SubChapter D 382.085(b) Title V O-02215, SC 1F(v) OP		
Description:	Site failed to conduct weekly visual inspections of pumps, compressors, and agitators in highly reactive volatile organic compound (HRVOC) service during the week of January 15, 2006.		
Self Report?	NO	Classification:	Moderate
Citation:	30 TAC Chapter 115, SubChapter H 115.725(a)(1)(C) 30 TAC Chapter 122, SubChapter B 122.143(4) 5C THC Chapter 382, SubChapter D 382.085(b) Title V O-02215, SC 1F(ii) OP		
Description:	Site failed to operate Train 1 Make Hoppers, MH-101, MH-102 & MH-103, Check Hoppers CH-101A & CH-101B, and Spin Dryer SD-102 within the established operating limits for the selected operating parameters to establish maximum potential HRVOC hourly emission data expected during normal operation for the vent (B25P2RX101).		
Self Report?	NO	Classification:	Moderate
Citation:	30 TAC Chapter 116, SubChapter B 116.115(c)		

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 48813, SC 1 PERMIT
Title V O-02215, SC 11 OP

Description: Site failed to limit the VOC emissions from Train 2 Make Hoppers MH-201, MH-202, and MH-203 (B25P2SB201, B25P2SB202, and B25P2SB203) within the permit allowables of 1.98 lbs/hr from each hopper vent.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter H 115.725(a)(1)(C)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02215, SC 1F(i) OP

Description: Site failed to operate Make Hoppers MH-241, MH-243, MH-244 and MH-311 within the established operating limits for the selected operating parameters to establish maximum potential HRVOC hourly emission data expected during normal operation for the vent (B25P2VOGS).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(3)
30 TAC Chapter 115, SubChapter H 115.782(a)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 19519, SC 10H PERMIT
NSR 48813, SC 5H PERMIT
NSR 6803, SC 9H PERMIT
Title V O-02215, SC 11 OP

Description: Site failed to place leaker tags on six leaking valves and four leaking connectors.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 834, SC 1 PERMIT
Title V O-02215, SC 11 OP

Description: Site failed to limit the VOC emissions from Train 1 Blending Silos RB-1, RB-5, RB-9, and RB-13 (B41P4SB1, B41P4SB5, B41P4SB9, and B41P4SB13) within the permit allowables of 3.11 lbs/hr from each silo vent.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.722(d)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 834, SC 3 PERMIT
NSR 8567, SC 6 PERMIT
Title V O-02215, SC 11 OP
Title V O-02215, SC 1F(iii) OP

Description: Site failed to maintain the minimum net heating value of 300 Btu/scf for the gas being combusting at the flare (B78APF1) on two occasions for a total of two hours on June 2 and 30, 2006.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02215, SC 2 OP

Description: Site failed to determine an emissions event (Incident # 79942) occurred on August 13, 2006 is a reportable emissions event and failed to notify the commission regional office the reportable event no later than 24 hours after the discovery of the emissions event.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 6803, SC 1 PERMIT
Title V O-02215, SC 11 OP

Description: Site failed to maintain VOC emissions from the flare (B27P3F1) within the emissions allowable of 10.95 lbs/hr for one hour on September 11, 2006.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter H 115.725(a)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Title V O-02215, SC 1F(i) OP

Description: Site failed to conduct testing on the Poly 4 hold up hopper vents (B41V1 and B41V2) to establish maximum potential HRVOC hourly emission data by the compliance date of January 30, 2006.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter D 382.085(b)
 NSR 8567, SC 1 PERMIT
 Title V O-02215, SC 11 OP

Description: Site failed to maintain VOC emissions from Tanks T-10 and T-11 within the permitted allowables of 0.02 lbs/hr for each of the tanks, and 0.06 tons/yr for T-10 and 0.03 tons/yr for T-11.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
 30 TAC Chapter 122, SubChapter B 122.145(2)(A)
 5C THC Chapter 382, SubChapter D 382.085(b)
 Title V O-02215, General Conditions OP

Description: Site failed to report all instances of deviations in deviation reports.

Date: 04/13/2007 (543310) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 GFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
 5C THC Chapter 382, SubChapter D 382.085(b)
 O-02203, SC 14.A. OP
 Permit No. 4031, SC 16.E. PERMIT

Description: Failure to seal an open-ended line (OEL) in organic hazardous air pollutant service (unit ID: B13GBFU3).

Date: 04/27/2007 (532788) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter D 382.085(b)
 FOP O-02217, SC #15 OP
 TCEQ Air Permit No. 6932, SC #3A PERMIT

Description: Dow failed to prevent inadequate fuel supply to the flares.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter D 382.085(b)
 FOP O-02217, SC #15 OP
 TCEQ Air Permit No. 6932, S C #1 PERMIT

Description: Dow failed to control the release of unauthorized VOCs.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THC Chapter 382, SubChapter D 382.085(b)
 FOP O-02217, SC 15 OP
 TCEQ Air Permit No. 19720 SC 3 PERMIT

Description: Dow exceeded their annual permitted throughput loading rate.

Date: 06/30/2007 (575538) CN600356976

Self Report? YES Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)
 TWC Chapter 26 26.121(a)

Description: Failure to meet the limit for one or more permit parameter

Date: 07/11/2007 (532793)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
Permit # O-02311, General Terms & Cond. OP
Permit # O-02311, Special Condition #10 OP
Permit #20776, Special Condition #5 PERMIT

Description: Failure to prevent the solvent recovery tank system pressure from exceeding 10 psig.

Date: 07/27/2007 (563635)

CN600356976

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter A 335.15(3)(A)
Provision IV.A PERMIT

Description: Failure to notify acceptance of unmanifested wastes within 15 days from the date the wastes were accepted.

Date: 08/06/2007 (568640)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(C)
5C THC Chapter 382, SubChapter A 382.085(b)
General Terms and Conditions OP

Description: Failure to submit a deviation report by the submittal due date.

Date: 08/14/2007 (568679)

CN600356976

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)

30 TAC Chapter 122, SubChapter B 122.145(2)(C)
5C THC Chapter 382, SubChapter D 382.085(b)
General Terms and Conditions OP

Description: Failure to submit semiannual deviation report within 30 days of end of deviation reporting period.

Date: 08/31/2007 (512665)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THC Chapter 382, SubChapter D 382.085(b)
FOP Permit No. O-02206, STC 11 OP
NSR Permit No. 2472 SC 9E PERMIT
NSR Permit No. 2773 SC 12 E PERMIT

Description: Failure to plug 35 open-ended lines.

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1366(b)(1)(ii)
5C THC Chapter 382, SubChapter D 382.085(b)
FOP No. O-02206 STC 10 OP
FOP No. O-02206 STC 1D OP

Description: failure to record solvent flow and pH for the units A32TO560, A32STHROX, A32CPST06C&D, and A32CSST284 during February 20, 2006 at 3:03 p.m. through February 21, 2006 till 7:35 a.m.

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
FOP O-02206 STC 11 OP
NSR Permit No. 770 SC 11 PERMIT

Description: failed to complete annual refresher training for the year 2005.

Self Report? NO

Classification: Minor

Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(b)(2)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(b)(3)(i)

Description: failure monitor 29 connectors initially and annually as required from January 16, 2005 through July 15, 2006.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
FOP O-02206 STC 11 OP

Description: failure to record firebox temperature of incinerators A32CPSTO6D and A32CPSTO6C and failed to detect pilot flame for flare A32CSST284 for one hour between April 25, 2006 at 9:00 a.m. through April 26, 2006 at 10:00 a.m. while compute files were backed-up.

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
FOP O-02206 STC 11 OP
NSR Permit No. R-770 SC 17 B(2) PERMIT

Description: failure to maintain minimum Liquid / Gas (L/G) ratio for the Huntsman's ammonia scrubber 36 times during July 16, 2005 through January 15, 2006.

Date: 08/31/2007 (543556)

CN600356976

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(A)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-2208, STC 3(A)(II) OP

Description: Failure to conduct visible emission observations for unit ID B19S2, each quarter from April 4, 2004 through September 30, 2005.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR Permit No. 20432 SC 2E PERMIT
O-02208 STC 1(F) OP

Description: Failure to plug 12 open-ended lines during October 19, 2005 through September 27, 2006.
This is an alleged violation of 40 CFR 63.167(a)(1) and 30 TAC 115.352(4).

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.722(d)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR Permit No. 20232 SC 4 PERMIT
O-02208 STC 17 OP

Description: Failure to maintain minimum BTU of 300 Btu/scf for the flares B23G1FS865, B70ALF1, and B70ALF801 during April 19, 2006 through October 17, 2006 and November 5, 2005 through April 18, 2006.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.725(d)(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02208 STC 1M OP

Description: Failure to analyze grab samples when the on-line analyzer data unavailable for 15 instances from June 13, 2006 through August 13, 2006 for the unit B23G2F865 and for two instances from February 1, 2006 through June 27, 2006 for the unit B70AKF1.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR Permit No. 20432 SC 1-12A PERMIT
O-0228 STC 17 OP

Description: failure to install a rupture disc upstream of PSV in HAP service. This is an alleged violation of NSR Permit No. 20432 SC I-12A

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT A 61.14(b)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.356(j)(7)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02208 STC 9G OP
Description: failure to maintain monitoring data for the flare, B23G2F865 from July 4, 2006 through July 5, 2006.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02208 STC 1F OP
Description: failure to monitor a pump during September 1, 2006 through October 18, 2006. This is an alleged violation of 40 CFR 63.163(b)(1).

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR Permit 20432 SC 2F PERMIT
O-02208 STC 17 OP
Description: failure to replace rupture disc at the earliest convenience during January 31, 2006 through March 29, 2006.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.349(a)(1)(II)
5C THC Chapter 382, SubChapter D 382.085(b)
O-02208 STC 11 OP
Description: failed to install car seal on the ten (10) bypass valves on closed vent system during December 13, 2005 through December 14, 2005.

Date: 10/03/2007 (543554)

CN600356976

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 20432; SC I-9.C., SC I-9.D., SC I-9.E. PERMIT
Title V O-02207; SC 14.A. OP
Description: failed to maintain water flow rates to scrubbers with a minimum rate as indicated in the permit

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.116(a)(1)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02207; SC 14.A. OP
Description: failed to maintain water flow to the Scrubber, EPN B64VS3, with a minimum rate of 30 gallons per minute on November 27, 2005.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 20432; SC I-38.C. PERMIT
Title V O-02207; SC 14.A. OP
Description: failed to perform quarterly cylinder gas audits (CGAs) on the continuous emissions monitoring system (CEMS) for Epoxy 2 Carbon Bed, EPN B62CB1 from April 1, 2005 through June 30, 2006.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02207; SC 3.B.(iii) OP
Description: failed to perform annual observations of the stationary vents, EPN B62E2RX1 and B43E3RX1 from January 16, 2004 to April 18, 2006, and failed to keep records of annual observations of the stationary vent, EPN B52V001 from April 18, 2004 to October 18, 2006

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter G 116.715(a)

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 20432; SC I-37.C. PERMIT
Title V O-02207; SC 14.A. OP

Description: failed to convert volatile organic compounds (VOC) concentrations to pounds per hour from April 1, 2005 to July 31, 2006 for Epoxy 2 Carbon Bed, EPN B62CB1.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter G 116.715(a)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 20432; SC 2E PERMIT
Title V O-02207; SC 1.A., 14.A. OP

Description: failed to equip open-ended lines in hazardous air pollutant (HAP) and in VOC service with a cap or plug.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 117, SubChapter B 117.345(d)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02207; SC 1.A. OP

Description: failed to submit a semi-annual NOx CEMS report for Boilers B-901, B-902, and B-903, EPN OC3U3B901, EPN OC3U3B902, and EPN OC3U3B903, within the established deadline.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.10(e)(3)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT W 63.528(a)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02207; SC 1.A. OP
Title V O-02207; SC 8.G. OP

Description: failed to submit a semi-annual report for the Epoxy Products (1) Unit, within the established deadline.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)

30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(c)(1)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 3434; SC 6.F. PERMIT
Title V O-02207; SC 1.A., 14.A. OP

Description: failed to re-monitor of a fugitive leaker within 15 days of the detection of the leak.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(A)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02207: General Conditions OP

Description: failed to report all instances of deviations in the deviation report dated November 18, 2005

Date: 10/23/2007 (566959) CN600356976

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THC Chapter 382, SubChapter D 382.085(b)
NSR 20909; SC 7. PERMIT
Title V O-02211; SC 14. OP

Description: Site failed to maintain a positive flow from the vent header system to the thermal oxidizer (EPN B35EWS200) on November 14 and 15, 2006.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 68, SubChapter C, PT 68, SubPT D 68.69(c)
5C THC Chapter 382, SubChapter D 382.085(b)
Title V O-02211; SC 20 OP

Description: Site failed to certify the operating procedures required by 40 CFR 68.69(c) pertaining to risk management processes to assure that they are current and accurate.

Date: 01/09/2008 (595622)

CN600356976

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THSC Chapter 382 382.085(b)
FOP 2212, SC # 16 OP
FOP 2212, SC # 1A OP
NSR # 22072 SC # 4 PERMIT

Description: Failure to maintain minimum flare heating values of 300 Btu/scf for flares
BSRFMNF and BSRF401

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP 2212, SC #16 OP
NSR # 22072, SC # 1 PERMIT

Description: Failure to maintain maximum allowable VOC emissions of 0.94 lb/hr during the
times the BSRFMNF flare was below 300 Btu/scf on July 24, 2006 from
1500-1600, and from August 11, 2006 at 1900 to August 14, 2006 at 0700.

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 117, SubChapter B 117.219(f)(2)(C)
5C THSC Chapter 382 382.085(b)

Description: Failure to record permanent records of the daily NOx emissions and fuel usage
(or exhaust stack flow) from January 1, 2007 to March 28, 2007 for EPN
BSRHDHTR.

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP 2212, SC # 17 OP
NSR # 22072, SC # 10A PERMIT

Description: Failure to consistently conduct audio, visual, & olfactory (AVO) inspections for
chlorine leaks within the operating area every four hours (19 times) from January
1, 2007 to July 6, 2007.

Date: 01/09/2008 (595628)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THSC Chapter 382 382.085(b)
NSR #770, SC26E PERMIT
O-02206, STC 11 OP
O-02206, STC 1A OP

Description: Failed to seal 10 open-ended valves or lines with a cap, blind flange, plug or a
second valve.

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.169(a)
5C THSC Chapter 382 382.085(b)
NSR#770, SC26F PERMIT
O-02206, SC12 OP
O-02206, SC1A OP

Description: Failed to monitor nine fugitive components.

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter B 115.116(a)(3)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1366(b)(2)(i)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1366(b)(2)(ii)
5C THSC Chapter 382 382.085(b)

O-02206, STC1A OP

Description: Failed to record two periodic monitoring records.

Date: 01/28/2008 (610685)

CN600356976

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
37884, SC 3 (C) PERMIT
5C THSC Chapter 382 382.085(b)
O-02313, SC 9 OP

Description: Failure to stay below the maximum operating limit for NOx on flare FV600.

Date: 01/29/2008 (615960)

Self Report? NO

Classification: Moderate

Citation: 20774 PA
30 TAC Chapter 116, SubChapter B 116.115(c)

Description: Failure to inspect relief valves as required by permit No. 20774.

Date: 02/13/2008 (610665)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
NSR Permit 20776, Special Condition 5 PERMIT
O-02311, Special Terms and Conditions 10 OP

Description: Failure to operate at a minimum pressure of 2 psig and a maximum pressure of 10 psig on Unit B6610QUV53.

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
NSR Permit 20776, Special Condition 8 PERMIT
O-02311 Special Terms and Conditions 10 OP

Description: Failure to maintain the minimum flow rate of 0.6 gallon per minute on the Acid Scrubber System (D-27).

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
NSR Permit 20776, Special Condition 7I PERMIT
O-02311, Special Terms and Conditions 10 OP

Description: Failure to monitor one component out of 3814 fugitive components for three monitoring periods.

Date: 02/28/2008 (637300)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 290, SubChapter D 290.45(d)(2)(B)(ii)

Description: Failure to provide a ground storage capacity which is equal to 50% of the maximum daily demand.

Date: 03/06/2008 (595630)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.725(d)(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 1(L)(iii) OP

Description: Failure to collect grab samples when the on-line analyzer (OC6L8F1000) data was unavailable (2 instances) from November 1, 2006 at 0833 to November 30, 2006 at 0955.

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 1, SubChapter C, PT 61, SubPT V 61.242-6(a)(1)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
 5C THSC Chapter 382 382.085(b)
 FOP O-02213, SC 1(A) OP
 FOP O-02213, SC 1(D) OP
 FOP O-02213, SC 16 OP
 NSR 20432, SC 1(E) PERMIT

Description: Failure to seal fifty (50) open-ended lines containing volatile organic compounds for B72L2FU1 and OC6L8FU01 from May 16, 2006 at 1500 to August 3, 2006 at 1159 and from November 29, 2006 at 1200 to March 21, 2007 at 1150.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
 5C THSC Chapter 382 382.085(b)
 FOP O-02213, SC 1(A) OP
 FOP O-02213, SC 1(D) OP
 FOP O-02213, SC 16 OP
 NSR 20432 (GMA) SC 1(F) PERMIT

Description: Failure to monitor 61 newly installed valves as required from October 15, 2006 at 0000 to April 18, 2007 at 2359 for B72L2FU1.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(11)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 FOP O-02213, SC 16 OP
 NSR 20432 (GMA), SC 1(E) PERMIT

Description: Failure to monitor 512 newly installed connectors as required from October 15, 2006 at 0000 to April 18, 2007 at 2359 for B72L2FU1.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
 5C THSC Chapter 382 382.085(b)
 FOP O-02213, SC 1(A) OP
 FOP O-02213, SC 1(D) OP
 FOP O-02213, SC 16 OP
 NSR 20432 (GMA), SC 1(G) PERMIT

Description: Failure to monitor 2 newly installed pumps as required from October 15, 2006 at 0000 to April 18, 2007 at 2359 for B72L2FU1.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
 5C THSC Chapter 382 382.085(b)
 FOP O-02213, SC 1(A) OP
 FOP O-02213, SC 1(D) OP
 FOP O-02213, SC 16 OP
 NSR 21596, SC 13 PERMIT

Description: Failure to monitor one fugitive component (pump EAI266096 in light liquid service) from November 1, 2006 at 0000 to April 18, 2007 at 2350 for A17FU2.

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 FOP O-02213, SC 16 OP
 NSR 20432, Ch. III, SC III-24(G)(1)(b) PERMIT

Description: Failure to complete analysis of cracked gas sulfur content which was collected but not analyzed by the end of the 1st quarter, from April 1, 2007 at 0000 to April 18, 2007 at 2359.

Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 116, SubChapter B 116.110(a)

30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 16 OP

Description: Failure to submit a permit-by-rule for HRVOC analyzer vents B72L7FU1, OC6L8FU01, A17EAFU2, B31S1FU1, and B71S2FU1) from January 30, 2006 at 0000 to October 18, 2006 at 2350 and from October 19, 2006 at 0000 to April 18, 2007.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 16 OP
NSR 20432, Ch. IV, SC IV-10(D) PERMIT
NSR 21596, SC 15(C) PERMIT

Description: Failure to reduce the individual average NOx and CO concentrations to units of the applicable permit allowable emission rates at the required frequency as stated in the permit from April 19, 2004 at 0000 to April 4, 2007 at 2359 for B31HMOD1B and 71S123/A17S551.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 16 OP
NSR 20432 (GMA), SC 4 PERMIT

Description: Failure to prevent five (5) occurrences of excess the flare tip exit velocity for flare waste gas from May 03, 2006 at 0200 to May 11, 2006 at 2100 (2 occurrences) and from November 22, 2006 at 0800 to February 2, 2007 at 1500 (3 occurrences) for flare OC6L8F1000.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)(2)(F)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 16 OP
NSR 20432, Ch. III, SC III-1 PERMIT

Description: Failure to prevent Maximum Allowable Emissions Rate Table (MAERT) occurrences due to excess the flare tip exit velocity for flare waste gas on February 4, 2007 for flare OC6L8F1000. Total VOC emissions were 267.6 lbs/hr (126.0 lbs/hr maximum allowed per the interim CAP effective from December 31, 2005 to July 1, 2008).

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 1(A) OP
FOP O-02213, SC 16 OP
NSR 21596, SC 8 PERMIT

Description: Failure to maintain minimum flare Btu/scf value at or above 300 on August 6, 2006 from 1300-1400 for A17EAF11.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT NNN 60.662(a)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 16 OP
NSR 21596, SC 3 PERMIT

Description: Failure to maintain minimum firebox temperature at or above 663 degrees Celsius on May 21, 2006 from 1300 to 2100 for A17EAH551.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213, SC 16 OP
NSR 21596, GC 8 PERMIT
NSR 21596, SC 1 PERMIT

Description: Failure to prevent Maximum Allowable Emission Rate Table (MAERT) exceedance for A17S551 due to low firebox temperature below 663 degrees Celsius on May

21, 2006 from 1300 to 2100 for A17EAH551.
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02213 SC 2F OP
Description: Failure to make a final record of a recordable event within 14 days (2 occurrences) for the loss of 2 lbs of VOC from A17EAF11 and the 3 lbs of VOC from A17EAF11.

Date: 03/10/2008 (619156) CN600356976
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
30 TAC Chapter 101, SubChapter F 101.221(a)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
TCEQ Air Permit No. 21596, SC 3 PERMIT
TCEQ Air Permit No. 21596, SC 8 PERMIT
Description: Dow failed to maintain the net heating value of the flare for one hour during an emissions event (Incident 101569) that occurred on December 19, 2007 and lasted 15 hours and 17 minutes.

Date: 06/30/2008 (690045) CN600356976
Self Report? YES Classification: Moderate
Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)
30 TAC Chapter 305, SubChapter F 305.125(1)
Description: Failure to meet the limit for one or more permit parameter

Date: 07/02/2008 (618777) CN600356976
Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 115, SubChapter H 115.783(5)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 1, SubChapter C, PT 61, SubPT V 61.242-6(a)(1)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-1(d)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-1(c)
40 CFR Part 60, Subpart VV 60.482-1(c)
5C THSC Chapter 382 382.085(b)
SC 15 OP
SC 2 E PERMIT
Description: Failure to install plugs for open ended lines during the annual compliance certification period 10/19/06 through 10/18/07.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145
5C THSC Chapter 382 382.085(b)
SC 15 OP
SC I-9 (B), (C), & (D) PERMIT
Description: Failure to maintain inlet water flow to the adsorber, process vents and storage tanks.

Date: 08/11/2008 (681763) CN600356976
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02204, General Terms & Conditions OP
FOP O-02204, Special Term & Condition 10 OP
Description: Failure to operate the liquid/gas ratio of the scrubber at the prescribed levels.
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 115, SubChapter D 115.352(2)
30 TAC Chapter 115, SubChapter H 115.781(b)

30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02204, Special Term & Condition 11 OP
FOP O-02204, Special Term & Condition 1A OP
Permit 19041, Special Condition 20F PERMIT

Description: Failure to perform Method 21 monitoring to one valve in VOC service on a quarterly basis.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.6(e)(3)(iii)
5C THSC Chapter 382 382.085(b)
FOP O-02204, Special Term & Condition 1A OP

Description: Failure to properly and completely record corrective actions in response to an SSM event.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-02204, Special Term & Condition 11 OP
Permit 19041, Special Condition 2A PERMIT

Description: Failure to operate one safety valve in conjunction with a rupture disc.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(f)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(d)
5C THSC Chapter 382 382.085(b)
FOP O-02204, Special Term & Condition 11 OP
FOP O-02204, Special Term & Condition 1A OP
Permit 19041, Special Condition 20I PERMIT
Permit 48715, Special Condition 8I PERMIT

Description: Failure to perform remonitoring of seven leaking LDAR components, after repairs were made, within 15 days of the date the leak was found.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(d)(2)
5C THSC Chapter 382 382.085(b)
FOP O-02204, Special Term & Condition 11 OP
FOP O-02204, Special Term & Condition 1A OP
Permit 941, Special Condition 5E PERMIT

Description: Failure to perform quarterly LDAR monitoring to 338 components from February 25, 2005 through January 31, 2008.

Date: 08/20/2008 (610600) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter H 115.726(c)(2)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP 2219, Spec. Cond 1I OP

Description: Failure to record pressure readings on a pressure safety valve (PSV).

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.356(2)(F)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
NSR Permit No. 20775, Spec. Cond 3E PERMIT

Description: Failure to record leaks from AVO observations.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 106, SubChapter K 106.261(a)(6)
30 TAC Chapter 116, SubChapter B 116.110(a)(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Spec. Cond. 14 OP

Description: Late submittal of a Permit by Rule (PBR).

Date: 08/27/2008 (680057)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(C)
5C THSC Chapter 382 382.085(b)
O-02220 General Terms and Conditions OP

Description: Failure to submit the semi-annual deviation report dated August 28, 2007 within thirty days of the end of the reporting period.

Self Report? NO

Classification: Moderate

Citation: 1472 Special Condition 7(A) PERMIT
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THSC Chapter 382 382.085(b)
O-02220 Special Terms and Conditions 1A OP
O-02220 Special Terms and Conditions 7 OP

Description: Failure to maintain a minimum net heating value of 300 BTU/scf for the gas being combusted at the flare (A26VEF1) on two occasions from September 15 to 16, 2007 and November 11 through 28, 2007.

Date: 09/30/2008 (710825)

CN600356976

Self Report? YES

Classification: Moderate

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)
30 TAC Chapter 305, SubChapter F 305.125(1)

Description: Failure to meet the limit for one or more permit parameter

Date: 11/07/2008 (701151)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.211(c)

Description: Failure to submit a Final Report for Incident No. 109697 within 14 days of the end of a startup activity

Date: 12/31/2008 (727542)

CN600356976

Self Report? YES

Classification: Moderate

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)
30 TAC Chapter 305, SubChapter F 305.125(1)

Description: Failure to meet the limit for one or more permit parameter

Date: 01/29/2009 (703338)

CN600356976

Self Report? NO

Classification: Moderate

Citation: Federal Operating Permit 02214 SC 10 OP
New Source Review (NSR) 46306 SC 7B PERMIT

Description: Failure to prevent Carbon Monoxide emissions from Boiler EPN B56PSB3.

Date: 01/29/2009 (681611)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)
Permit 7531 SC #1 PERMIT

Description: Failure to maintain emissions of chlorine from F-732 Throx unit below the permit allowable.

Date: 02/24/2009 (705417)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 116, SubChapter B 116.115(b)
30 TAC Chapter 122, SubChapter B 122.143(4)
5340 Special Condition 13F PERMIT
5C THSC Chapter 382 382.085(b)
FOP O-01388 ST&C 17 OP
FOP O-01388, ST&C 1A OP

Description: Failure to monitor five leak detection and repair (LDAR) components, from January 1, 2007 through February 13, 2008.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.120(a)(5)
5C THSC Chapter 382 382.085(b)
FOP O-01388 ST&C 1A OP

Description: Failure to submit a 30 day notification to the Administrator prior to refilling Tank NV-11.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(b)
30 TAC Chapter 122, SubChapter B 122.143(4)
5340, Special Condition 11C PERMIT
5C THSC Chapter 382 382.085(b)
FOP O-01388, ST&C 17 OP

Description: Failure to maintain the caustic flow to the scrubber, from 0745 through 0900 hours on December 13, 2008, at or above the minimum of 600 lbs/hr.

Date: 02/27/2009 (723999) CN600356976

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)
Special Condition 1 PERMIT

Description: Dow failed to prevent unauthorized emissions. Dow had an avoidable emissions event caused by failure to follow good design practices. Dow failed to install compatible pilot mixing chambers on flare FS-11, which caused the flare to loose the pilot flame during a rain event.

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 101, SubChapter A 101.20(1)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
5C THSC Chapter 382 382.085(b)
Special Condition 8 PERMIT

Description: Dow failed to prevent unauthorized emissions. Dow failed to keep the flare FS-11 lit when emissions were being routed to it.

Date: 03/17/2009 (721122)

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.10(e)(3)
5C THSC Chapter 382 382.085(b)
Special Condition 1D OP

Description: Failure to submit the semi annual report required under 40 CFR 63, Subpart MMM for the site within the required timeframe. (Category C3)

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 12 OP
Special Condition 1A OP
Special Condition 27 PERMIT

Description: Failure to monitor tag nos. EAI904489, EAI904491, EAI904494 and EAI904498 annually for fugitive leaks. (Category C1)

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THSC Chapter 382 382.085(b)
Spcaill Condition 11 OP
Special Condition 1A OP
Special Condition 26E PERMIT

Description: Failure to seal five open-ended lines containing VOCs and HAPs in units A32CPFUPIC and A32CSFUSYM. (Category C10)

Date: 03/31/2009 (750354)

Self Report? YES

Classification: Moderate

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)
30 TAC Chapter 305, SubChapter F 305.125(1)

Description: Failure to meet the limit for one or more permit parameter

Date: 04/08/2009 (703324)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
GP 7(E) PERMIT
GP 7(F) PERMIT
GP 7(G) PERMIT
ST&C 11 PERMIT

Description: Failure to conduct fugitive monitoring on eight (8) components on the K-11 reactor UNIT ID B5010K11 (CATEGORY C1 violation)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC 3E PERMIT
ST&C 11 PERMIT

Description: Failure to conduct fugitive monitoring on one (1) connector on the D-37 Storage Tank UNIT ID B5006ST37, one (1) connector on the D-38 Storage Tank UNIT ID B5006ST38, and one (1) connector on the D-703 Reactor/Agitator UNIT ID B5006D703 (Category C1 violation)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC 3E PERMIT
ST&C 11 PERMIT

Description: Failure to seal one open ended line containing volatile organic compounds (CATEGORY C10 violation)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC 10G PERMIT
ST&C 12 PERMIT

Description: Failure to conduct fugitive monitoring on one (1) component on the Vent Header for Product Vents UNIT ID B5016RX341 (CATEGORY C1 violation).

Date: 04/10/2009 (703330)

CN600356976

Self Report? NO

Classification: Minor

Citation: 20432, SGR 1E PERMIT
30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Failure to plug/cap all open ended lines (Category C10).

Self Report? NO

Classification: Minor

Citation: 20432, SGR 4 PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(1)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Visible emissions from the Tank Farm Flare.

Self Report? NO

Classification: Minor

Citation: 20432, SGR 4 PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Pilot flame outage on three occasions.
Self Report? NO Classification: Minor
Citation: 20432, SGR 4 PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Part 60, Subpart A 60.18(c)(4)(i)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Exceeded maximum allowable flare tip velocity.
Self Report? NO Classification: Minor
Citation: 21596, SC 11F PERMIT
30 TAC Chapter 115, SubChapter D 115.354(2)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
O-02213, SC 1A OP

Description: Failed to conduct LDAR monitoring on a valve and eight connectors in VOC service.
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 115, SubChapter D 115.352(2)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
O-02213, SC 1A OP

Description: Failed to retest a repaired leaking component.
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 117, SubChapter B 117.310(c)(1)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
O-02213, SC 1A OP

Description: Exceeded 24 hour rolling average carbon monoxide 400 ppm limit.
Self Report? NO Classification: Minor
Citation: 21596, SC 8 PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Part 60, Subpart A 60.18(c)(4)(i)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Failed to maintain flare inlet heat content at or above 300 BTU/scf.
Self Report? NO Classification: Minor
Citation: 20432, SGR 2E PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(3)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Failure to conduct weekly Audiovisual-olfactory (AVO) monitoring of pump seal and connector in VOC/HAP service.
Self Report? NO Classification: Minor
Citation: 21596, SC 3 PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.7(c)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Failed to submit 40 CFR 60, Subpart NNN report on time
Self Report? NO Classification: Minor
Citation: 20432, SC IV-2 PERMIT
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.7(c)
5C THSC Chapter 382 382.085(b)
O-02213, SC 13 OP

Description: Failed to include CEMS/PEMS downtime report in the site report.
Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
O-02213, SC 20 OP

Description: Failed to comply with the risk management program specified in Federal
Operation Permit O-02213, Special Terms and Condition 20.

Date: 06/10/2009 (721172)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter C 115.213(b)(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP

Description: Failed to update the site wide VOC Loading Control Plan within 30 days as
required after a Thermal Oxidizer (TOX) was added to the VOC loading rack

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-6(a)(1)
5C THSC Chapter 382 382.085(b)
Special Condition No. 13 OP
Special Condition No. 3E PERMIT

Description: Failed to operate the process unit with no open-ended lines

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition No. 14 OP
Special Condition No. 3F PERMIT

Description: Failed to conduct quarterly monitoring of three valves in the B3831 Unit for
fugitive emissions

Date: 06/16/2009 (721240)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(1)(A)
5C THSC Chapter 382 382.085(b)
NSR SC 18A PERMIT
NSR SC 4A PERMIT
NSR SC 5A PERMIT
O-02215 General Terms and Conditions OP
O-02215 Special Terms and Conditions 11 OP

Description: Failure to maintain net heating value for the flares B45F1, B27F2, and B27F1.
(Category B18)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(1)(A)
5C THSC Chapter 382 382.085(b)
NSR SC 7 PERMIT
O-02215 General Terms and Conditions OP
O-02215 Special Terms and Conditions 11 OP

Description: Failure to conduct monthly cooling tower return water VOC testing for the
months of February through June 2008. (Category B1)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(3)
30 TAC Chapter 116, SubChapter B 116.115(c)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-1(a)
5C THSC Chapter 382 382.085(b)
NSR SC 11E PERMIT
O-02215 Special Terms and Conditions 1A OP

Description: Failed to monitor 488 connectors at the Poly3 (B27P3FU1) unit during 1/28/2003
through 3/31/2008. (Category B1)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)
NSR SC 11F PERMIT
O-02215 Special Terms and Conditions 1A OP
Description: Failed to monitor 77 valves at the Poly3 (B27P3FU1) unit during 1/28/2003 through 3/31/2008. (Category B1)

Date: 06/17/2009 (703327) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP SC 17 OP
SC 13(A)(2) PERMIT
SC 5(F) PERMIT

Description: Failure to monitor 450 fugitive components (Category B1).

Self Report? NO Classification: Minor

Citation: 22072, SC 5(H) PERMIT
2212, FOP SC 17 OP
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Description: Failure to complete repairs on one fugitive component (Category B1).

Date: 07/01/2009 (738610)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 12F PERMIT
Special Term and Condition 16 OP

Description: Failure to promptly retest a repaired component. (CATEGORY C1 VIOLATION)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 5 PERMIT
Special Term and Condition 16 OP

Description: Failure to stay below the annual ethylbenzene throughput limit at the marine loading dock. (CATEGORY B13 VIOLATION)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 4 PERMIT
Special Term and Condition 16 OP

Description: Failure to keep the outlet temperature on the refrigeration unit MU7001 below 4 degrees Celsius. (CATEGORY B18 VIOLATION)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.880
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEEE 63.2378(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT SS 63.996(c)(1)
5C THSC Chapter 382 382.085(b)
Special Term and Condition 1A OP
Special Term and Condition 1E OP

Description: Failure to operate the pressure swing adsorber within the daily operating parameters. (CATEGORY B18 VIOLATION)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.7(a)(1)
5C THSC Chapter 382 382.085(b)
Special Term and Condition 9A OP

Description: Failure to submit notification for new tank construction within 30 days of starting the project. (CATEGORY C3 VIOLATION)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(a)(2)
 5C THSC Chapter 382 382.085(b)
 Special Terms and Conditions 1E OP

Description: Failure to conduct daily CEMS audits on EPN B33INS1. (CATEGORY C3 violation)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 Special Condition 24.B.2 PERMIT
 Special Terms and Conditions 14 OP

Description: Failure to conduct cylinder gas audits for the CEMS on EPN B8S180 for the period of 02/07/2007 through 12/31/2008. (CATEGORY B3 violation)

Self Report? NO

Classification: Minor

Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT SS 63.994(c)(1)(ii)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT SS 63.996(c)(5)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT SS 63.998(b)(1)(i)
 Special Terms and Conditions 1.G OP

Description: Failure to maintain monitoring data for the liquid to gas (L/G) ratio on EPN B34S1400. (CATEGORY C3 violation)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 Special Condition 27 PERMIT
 Special Condition 28 PERMIT
 Special Terms and Condition 14 OP

Description: Failure to maintain MSS records relating to EPN B8FU180 during maintenance, startup and shutdown activities. (CATEGORY B3 violation)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 Special Condition 7 PERMIT
 Special Terms and Condition 14 OP

Description: Failure to maintain positive gas flow to EPN B35EWS200. (CATEGORY C4 violation)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-6(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
 5C THSC Chapter 382 382.085(b)
 Special Condition 17.E PERMIT
 Special Terms and Condition 14 OP
 Special Terms and Condition 1A OP

Description: Failure to maintain lines resulting in open ended lines. (CATEGORY C10 violation)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
 40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-7(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
 Condition X.B.2.g PERMIT
 Special Condition 17.F PERMIT
 Special Condition 6.F PERMIT
 Special Terms and Condition 14 OP
 Special Terms and Condition 1A OP

Description: Failure to monitor valves for the Leak Detection and Repair program. (CATEGORY B1 violation)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(D)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-8(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.165(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

5C THSC Chapter 382 382.085(b)
Special Terms and Conditions 1(A) OP
Description: Failure to monitor connectors and pressure relief valves for the Leak Detection and Repair program. (CATEGORY B1 violation)

Date: 08/13/2009 (721183)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 11A OP
Special Condition 8 OP

Description: Failure to stay below the required pH level on the Acid Vent Scrubber (D-27) during volatile organic compound (VOC) venting operation. B19 (g) (1)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 11A OP
Special Condition 6F OP
Special Condition 7F OP

Description: Failure to record 3 quarters of monthly monitoring of 14 components. B19 (g) (4)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(A)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP

Description: Failure to submit all deviations in the deviation report dated September 1, 2007 through February 29, 2008. B3

Date: 08/18/2009 (747034)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEEE 63.2346(c)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(c)
5C THSC Chapter 382 382.085(b)
Special Condition 10 PERMIT
Special Condition 7E PERMIT
Special Condition 7F PERMIT
Special Condition 8 PERMIT
Special Term and Condition 1A OP
Special Term and Condition 7 OP

Description: Failure to monitor fugitive components. (CATEGORY B1 VIOLATION)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 4 PERMIT
Special Term and Condition 7 OP

Description: Failure to install upstream rupture disks on relief valves. (CATEGORY B18 VIOLATION)

Date: 08/18/2009 (737079)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
SC 16A OP
SC 7 PERMIT

Description: Dow failed to conduct weekly testing of the carbon canister.

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)

SC 16A OP
SC 16E PERMIT
SC 1A OP

Description: Dow failed to seal one open ended line. (C10 violation)
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)(1)(B)
30 TAC Chapter 122, SubChapter B 122.143(4)
SC 2F OP

Description: Failure to record four emission events.
Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
SC 16A OP
SC 18 PERMIT

Description: Dow failed to meet the 100 ppm CO hourly rolling average. (Category B19 (g) (1) violation)
Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
SC 15 PERMIT

Description: Dow failed to meet the hourly average temperature. (CATEGORY B19 (g)(1))
Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
SC 16A OP
SC 20 PERMIT

Description: Dow failed to maintain the caustic concentration. (CATEGORY B19 (g)(1) violation).
Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
SC 1 PERMIT
SC 16A OP

Description: Dow failed to control CO emission from a furnace. (CATEGORY B19 (g)(1) violation)

Date: 08/19/2009 (747013)

CN600356976

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(1)
5C THSC Chapter 382 382.085(b)
SC 1A OP

Description: Failure to seal two open ended lines (OELs) or 0.04% out of 4714 potential OELs from June 12, 2008 through September 22, 2008 in Unit ID B23G2FU2 and B70FU1. These lines were in volatile organic compound (VOC) service.
Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter H 115.722(d)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(3)(ii)
5C THSC Chapter 382 382.085(b)
SC 1A OP

Description: failed to maintain the Btu value of the vent to the flare (Unit Id B70ALF801) on 12/10/2007, 9/19/2008 and 9/24/2008. The incident on 12/19/2007 resulted in unauthorized emissions of 3 lbs VOC; and the incident on 9/19/2008 and 9/24/2008 resulted in unauthorized emissions of 2 lbs of HRVOC and 6 lbs VOC due to loss of flare pilot.
Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-7(a)
5C THSC Chapter 382 382.085(b)
SC 1A OP

Description: Failure to monitor monthly 0.02% of 28,529 fugitives components (Unit ID B19G1FU1, B19G1FU5, B19G1FU6, B19G1FU7, B19G1FU9, B15G1FU2, B23G2FU2, and B23G2FU8) in the affected area from April 18, 2004 through October 18, 2008.

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC 18 OP
SC 2F PERMIT

Description: Failure to monitor quarterly 3 valves in VOC service from December 14, 2006 through December 12, 2007.

Self Report? NO Classification: Moderate
Citation: 1A OP
30 TAC Chapter 116, SubChapter G 116.716(b)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)

Description: failed to maintain emission limit for the flare (Unit ID B23F865). An unauthorized emission of 0.09 ton of propylene and 0.76 ton VOC (not including propylene) were released from October 19, 2007 through December 31, 2007.

Date: 08/26/2009 (761298)

Self Report? NO Classification: Minor
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
46306 SC.17(A) PERMIT
5C THSC Chapter 382 382.085(b)

Description: Failure to conduct annual RATAs as required by Permit #46306.

Date: 08/31/2009 (767261)

CN600356976

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 335, SubChapter H 335.221(a)(5)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(d)(1)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(d)(2)
Provision II.A.1., II.C.d. PERMIT

Description: Unauthorized waste streams

Date: 09/03/2009 (759159)

CN600356976

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 335, SubChapter F 335.152(a)(18)
40 CFR Chapter 264, SubChapter I, PT 264, SubPT BB 264.1061(b)(2)
VI.A.21.a. PERMIT

Description: Failure to provide the notification and perform annual monitoring of valves in light liquid service.

Date: 10/23/2009 (737253)

CN600356976

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)
5C THSC Chapter 382 382.085(b)
FOP O-2207, SC 15 ORDER
FOP O-2207, SC 1A ORDER
NSR 20432, SC 2F PERMIT
NSR 20432, SC 2G PERMIT
NSR 3434, SC 6F PERMIT
NSR 3434, SC 6G PERMIT

Description: Failure to monitor fugitive components from April 18, 2004 - April 18, 2008.
(CATEGORY B19g1 violation)

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-2207, SC 15 ORDER
NSR 20432, SC 2E PERMIT

Description: Failed to seal open-ended lines containing volatile organic compounds.
(CATEGORY C10 violation)

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-2207, SC 15 ORDER
NSR 28363, SC 12 PERMIT
NSR 28363, SC 8 PERMIT

Description: Failure to operate the Thermal Oxidizer at 99.9% destruction efficiency.
(CATEGORY B19g1 violation)

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP O-2207, SC 15 ORDER
NSR 28363, SC 15E PERMIT

Description: Failure to submit the final sampling report within forty-five (45) days after
sampling was completed. (CATEGORY C3 violation)

Date: 11/20/2009 (778896)

Self Report? NO Classification: Moderate
Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
5C THSC Chapter 382 382.085(b)
Permit #43603, S.C. 17(a) PERMIT

Description: Boiler 91 (EPN:B56SB1) did not pass Relative Accuracy requirements for the
NOx analyzer.

Date: 12/02/2009 (778760)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(c)

Description: Dow failed to submit a Final Report in Steers within 14 days of the end of the
emissions event.

Date: 12/11/2009 (781124)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
5C THSC Chapter 382 382.085(b)
NSR 770 OP

Description: Failure to conduct fugitive monitoring on valves.

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(A)
5C THSC Chapter 382 382.085(b)

Description: Failure to timely report deviations within their respective reporting period.

Date: 03/24/2010 (781130)

CN600356976

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC 6A PERMIT
ST & C 17 PERMIT
ST & C 1A PERMIT

Description: Failure to monitor one fugitive emission connector in VOC service between May
28, 2008 and June 23, 2009. (Category C1 VIOLATION)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.782(b)(2)
5C THSC Chapter 382 382.085(b)
ST & C 17 OP

Description: Failure to perform a timely first attempt repair of a fugitive component (EPN
BSRFUSTV). (Category C1 VIOLATION)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter H 115.781(b)(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-7(a)
 5C THSC Chapter 382 382.085(b)
 SC 5F PERMIT
 ST & C 17 OP
 ST&C 1A OP

Description: Failure to monitor 211 valves in their LDAR program in units BSRSRFUSTV, BSRSRFUDOW AND BSRSRFUBRK, from July 7, 2008 through September 30, 2008. (Category C1 violation)

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter H 115.781(b)(3)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 SC 6A PERMIT
 ST&C 17 OP
 ST&C 1A OP

Description: Failure to monitor 865 connectors in the fugitive monitoring program in units BSRSRFUSTV, BSRSRFUDOW AND BSRSRFUBRK, from July 7, 2008 through September 30, 2008. (CATEGORY C1 VIOLATION)

Self Report? NO Classification: Minor
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(D)
 5C THSC Chapter 382 382.085(b)
 ST&C 17 OP
 ST&C 1A OP

Description: Failure to monitor 2 pressure relief valves in units BSRSRFUSTV, BSRSRFUDOW AND BSRSRFUBRK, from July 7, 2008 through September 30, 2008. (Category C1 violation)

Self Report? NO Classification: Minor
 Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT ZZZZ 63.6600(a)
 5C THSC Chapter 382 382.085(b)
 ST&C 13C OP
 ST&C 17 OP
 ST&C 1A OP

Description: Failure to maintain the pressure drop across the catalyst in unit BSRGE14 within the allowable limits. (Category C1 VIOLATION)

Date: 04/05/2010 (789344) CN600356976
 Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 101, SubChapter F 101.201(a)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 5C THSC Chapter 382 382.085(b)
 Special Condition 1 PERMIT

Description: Dow failed to prevent unauthorized emissions. Dow failed to submit an Initial Notification in Steers within 24 hours of the discovery of the emissions event (Incident No. 133636).

Date: 04/20/2010 (784861) CN600356976
 Self Report? NO Classification: Moderate
 Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
 30 TAC Chapter 115, SubChapter H 115.781(b)
 30 TAC Chapter 116, SubChapter B 116.115(c)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT DDD 60.562-2(a)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7(c)(1)(ii)
 5C THSC Chapter 382 382.085(b)
 FOP O-02219 STC 1A OP
 NSR 20775 SC 3(F) PERMIT
 NSR 20775 STC 1A PERMIT

Description: failure to monitor LDAR components on a quarterly basis (Category C1 Violation)

Date: 04/28/2010 (790223)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC(1) PERMIT
ST&C(16) OP

Description: Failure to prevent MAERT exceedance for EPN B44S100 and A36MDH621 (Category B19(g)(1) violation).

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
ST&C(3)(A)(iv)(1) OP

Description: Failure to conduct opacity observations during the third quarter of 2008 (Category B1 violation).

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC(8) PERMIT
ST&C(16) OP

Description: Failure to maintain a hourly average firebox temperature on the TOX unit (EPN B44S200) above the permitted minimum limit of 840 degrees Celsius (Category B19(g)(1) violation).

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)(2)

5C THSC Chapter 382 382.085(b)
SC16(E) PERMIT
ST&C(1)(A) OP
ST&C(16) OP

Description: Failure to prevent open-ended lines (Category C10 violation).

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
SC(11) PERMIT
ST&C(16) OP

Description: Failure to maintain the maximum hourly vent flow rate to the Thermal Treatment Unit (TTU) in accordance with permitted limits (Category B19(g)(1) violation).

Date: 05/07/2010 (792699)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.211(c)
5C THSC Chapter 382 382.085(b)

Description: Dow failed to report within 14 days of the end of an air shutdown.

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.211(b)(1)(E)
5C THSC Chapter 382 382.085(b)

Description: Dow failed to include the FIN or common name of the portable flare in the final report.

Date: 05/12/2010 (795204)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)
Effluent Limits & Monit. Reqmnt. No. 1. OP

Description: Failure to maintain compliance with the permit effluent limits for total suspended solids at outfall 202.

Date: 06/10/2010 (784758)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.725(d)(4)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 1F OP

Description: Failure to collect samples manually during extended HRVOC data collection system outage for units B27F1 flare and B45F1 flare on July 30 & 31 (Category B1 Violation).

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 11 OP
Special Condition 1A OP
Special Condition 7E PERMIT

Description: Failure to equip three open-ended lines with a cap, blind flange, plug or a second valve to seal the line so that no leak occurs on May 15, 2009 to July 12, 2009. Immediate steps were taken to cap the open ended lines (Category C10 Violation).

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 10 PERMIT
Special Condition 11 OP
Special Condition 12 PERMIT
Special Condition 14 PERMIT

Description: Failure to monitor fugitive components in VOC service annually for connectors unit B41P4FU1 on from January 28, 2003 to March 31, 2009. This constitutes a violation of NSR Permit 834, SC14 (Category B1 Violation).

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter H 115.725(a)(2)(D)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 1F OP

Description: Failure to comply with the established HRVOC operating parameter limits for units B41SP2 blender, B41V2A/B check hopper and B41SB8 blender when the production rate of on Train 2 was exceeded by 593 lbs for one hour on January 14, 2009. This constitutes a violation of 30 TAC 115.725(a)(2)(D) (Category B1 Violation).

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 1A OP

Description: Failure to monitor fugitive components in VOC service quarterly for 2 pressure relief valves in unit B77APFU1 from January 28, 2003 to March 31, 2009 (Category B1 Violation).

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 11 OP
Special Condition 1A OP
Special Condition 7F PERMIT
Special Condition 8F PERMIT

Description: Failure to monitor fugitive components in VOC service quarterly for 36 valves in unit B77APFU1 from January 28, 2003 to March 31, 2009. This constitutes a violation of NSR Permit 8567, SC7F and 30 TAC 115.354(2)(C), (Category B1 Violation).

Date: 06/17/2010 (794178)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
5C THSC Chapter 382 382.085(b)
SC(5) PERMIT
ST&C (1)(A) OP
ST&C (16) OP

Description: Failure to maintain a continuous pilot flame (Category C4).

Date: 06/17/2010 (798009)

CN600356976

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(d)(2)
5C THSC Chapter 382 382.085(b)
ST&C(1)(A) OP

Description: Failure to conduct quarterly monitoring (Category B1 violation)

Date: 06/18/2010 (803089)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(C)
5C THSC Chapter 382 382.085(b)

Description: Failure to submit the deviation report dated November 17, 2009, within the required 30 day time period.

Date: 06/28/2010 (794062)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
FOP 03005 Special Term and Condition 8 OP
NSR Permit 75751 SC7 PERMIT
NSR Permit 75751 SC9A PERMIT

Description: Failure to conduct quarterly monitoring for 168 connectors out of 329 components. Category B1

Date: 07/22/2010 (794057)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(A)
5C THSC Chapter 382 382.085(b)
FOP O-02208 General Terms and Conditions OP

Description: Failure to report all deviations in the first semi-annual deviation report dated October 19, 2008-March 31, 2009. Category B3

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.146(2)
5C THSC Chapter 382 382.085(b)
FOP O-02208 General Terms and Conditions OP

Description: Failure to submit the annual compliance certification for Federal Operating Permit (FOP) O-02208 no later than 30 days at the end of the certification period. Category B3

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(C)
5C THSC Chapter 382 382.085(b)
FOP O-02208 OP

Description: Failure to submit the second semi-annual deviation report for Federal Operating Permit (FOP) O-022081 no later than 30 days at the end of the reporting period. Category B3

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(D)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-4(a)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.165(a)
 5C THSC Chapter 382 382.085(b)
 FOP O-02208 SC 18A OP
 FOP O-02208 SC 1A OP
 NSR 20432 GC 2F PERMIT
 NSR 20432 SC I-3 (C) PERMIT
 NSR 20432 SC I-5 PERMIT

Description: Failure to monitor the relief valves on process vents (B19FU6). Category B19 (g) (1)

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter H 115.725(d)(4)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 5C THSC Chapter 382 382.085(b)
 FOP O-02208 SC 1M (iii) OP

Description: Failure to collect grab samples on flares B70ALF1, B70ALF801, and B23G2F865. Category B19 (g) (1)

Self Report? NO Classification: Minor

Citation: 30 TAC Chapter 115, SubChapter D 115.356(5)
 30 TAC Chapter 115, SubChapter H 115.786(g)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.486(a)(1)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.181(a)
 5C THSC Chapter 382 382.085(b)
 FOP O-02208 SC 18A OP
 FOP O-02208 SC 1A OP
 NSR 20432 GC 1J PERMIT
 NSR 20432 GC 2K PERMIT
 NSR 20432 GC 3C PERMIT
 NSR 20432 SC I-3C PERMIT
 NSR 20432 SC I-5 PERMIT

Description: Failure to submit required documentation. Category C3

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter H 115.722(d)
 30 TAC Chapter 116, SubChapter G 116.715(a)
 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)
 40 CFR Chapter 60, SubChapter C, PT 60, SubPT QQQ 60.702(b)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.11(b)(5)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.113(a)(1)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.119(e)(1)
 40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.139(c)(3)
 5C THSC Chapter 382 382.085(b)
 FOP O-02208 SC 18A OP
 FOP O-02208 SC 1A OP
 NSR 20432 GC 4 PERMIT
 NSR 20432 SC I-16A PERMIT
 NSR 20432 SC I-16B PERMIT

Description: Failure to maintain a lit pilot on flare B70ALF801. Category B19 (g) (1)

Date: 08/12/2010 (803145) CN600356976

Self Report? NO Classification: Moderate

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
 40 CFR Chapter 68, SubChapter C, PT 68, SubPT G 68.168
 5C THSC Chapter 382 382.085(b)
 FOP ST&C 16 OP

Description: Failed to submit the five (5) year Risk Management Plan (RMP) accident history reports within the required six (6) month period from May 16, 2007 to June 26, 2009. [Category B3 violation]

Date: 08/24/2010 (803091)

CN600356976

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
5C THSC Chapter 382 382.085(b)
Special Term and Condition 5 OP

Description: Failure to conduct monthly fugitive emission monitoring for a pump during the months of November 2009 and December 2009. (Category C1 violation)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Condition 19I PERMIT
Special Term and Condition 9 OP

Description: Failure to conduct annual fugitive emission monitoring for a valve for 2008 and 2009. (Category C1 violation)

Date: 08/25/2010 (841818)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter H 335.221(a)(15)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.104(b)
PROVISION V.I.7.c. PERMIT

Description: Failure to perform a quarterly calibration error test during the second quarter (April 1 - June 30) of 2009.

Date: 08/30/2010 (767572)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(C)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP

Description: Failure to submit the deviation report within the time frame (B3)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.132(e)(2)
30 TAC Chapter 122, SubChapter B 122.132(e)(3)
5C THSC Chapter 382 382.085(b)

Description: Failure to include NSPS Subpart D information in the permit application (C3)

Self Report? NO

Classification: Minor

Citation: 30 TAC Chapter 122, SubChapter B 122.143(4)
30 TAC Chapter 122, SubChapter B 122.145(2)(A)
5C THSC Chapter 382 382.085(b)
General Terms and Conditions OP

Description: Failure to include a deviation in the deviation report (C3)

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 116, SubChapter B 116.115(c)
30 TAC Chapter 122, SubChapter B 122.143(4)
5C THSC Chapter 382 382.085(b)
Special Conditions 1 and 7A PERMIT
Special Term and Condition 12A OP

Description: Failure to limit NOx emissions from Boiler FB-92 (B18)

Date: 08/31/2010 (841819)

CN600356976

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter C 335.69(a)
40 CFR Chapter 262, SubChapter I, PT 262, SubPT C 262.34(a)

Description: Failure to have a permit or interim status to store hazardous waste on-site for more than 90 days.

Self Report? NO

Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter C 335.69(a)(1)
40 CFR Chapter 265, SubChapter I, PT 265, SubPT I 265.174

Description: Failure to have records indicating inspections were conducted for on-site hazardous waste containers.

F. Environmental audits.

Notice of Intent Date: 12/17/2004 (347242)

Disclosure Date: 11/23/2005

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(A)
30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(b)(8)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-7
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.349(a)(1)(i)

Rqmt Prov: PERMIT NSR Permit 20432

PERMIT NSR Permit 22072

Description: Failure to monitor Valves, Connectors, Pressure Relief Valves, Pumps, Compressors, Agitator and Instrumentation Systems in the Salt Dome Operation, LHC-7 and LHC8.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include components which missed monitoring in emissions inventory calculations.

Notice of Intent Date: 04/20/2005 (380855)

Disclosure Date: 10/28/2005

Viol. Classification: Moderate

Citation: 40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1057
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(b)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(b)(3)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(c)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(e)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(d)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(b)

Rqmt Prov: PERMIT NSR Permit 2473

Description: Failed to monitor all components under a prescribed Leak Detection and Repair Program.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failed to include missed monitored components in emissions inventory.

Notice of Intent Date: 08/16/2005 (434104)

Disclosure Date: 02/22/2006

Viol. Classification: Moderate

Rqmt Prov: PERMIT NSR permit 37884

Description: Failure to monitor 369 Valves, 1156 Connectors and 31 Pressure Relief Valves in the OC4 Polypropylene Unit.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10(b)
40 CFR Chapter 372, SubChapter J, PT 372, SubPT B 372.30

Description: Failed to report emission calculations of components that were not monitored under a prescribed LDAR program

Notice of Intent Date: 09/16/2005 (436340)

Disclosure Date: 11/28/2005

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Description: Failure to monitor components within an LDAR program.

Notice of Intent Date: 10/26/2005 (465631)

Disclosure Date: 04/27/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(b)(3)
30 TAC Chapter 115, SubChapter H 115.781(b)(8)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)

Rqmt Prov: PERMIT 19519

PERMIT 48813

PERMIT 6803

Description: Failure to monitor Valves, Connectors, Pressure Relief Valves in B25 Polyethylene 2 and failure to monitor Valves, Connectors, Pressure Relief Valves, Agitator and Pumps in B27 Polyethylene 3.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include components which missed monitoring (B25 Polyethylene 2 and B27 Polyethylene 3) in the emissions inventory calculations.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

Description: Failure to close open ended lines.

Disclosure Date: 10/25/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(b)(3)
30 TAC Chapter 115, SubChapter H 115.781(b)(8)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)

Rqmt Prov: PERMIT 19519

PERMIT 48813

PERMIT 6803

Description: Failure to monitor Valves, Connectors, Pressure Relief Valves in B25 Polyethylene 2 and failure to monitor Valves, Connectors, Pressure Relief Valves, Agitator and Pumps in B27 Polyethylene 3.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include components which missed monitoring (B25 Polyethylene 2 and B27 Polyethylene 3) in the emissions inventory calculations.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

Description: Failure to close open ended lines.

Notice of Intent Date: 10/31/2005 (597298)

Disclosure Date: 05/01/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.349(a)(1)(i)

Rqmt Prov: PERMIT NSR 20432

Description: Failure to monitor components under a prescribed LDAR program

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components on EIQ.

Notice of Intent Date: 01/06/2006 (452904)

Disclosure Date: 05/12/2006

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)

Description: RQ emissions event records missing information.

Viol. Classification: Moderate

Rqmt Prov: PERMIT NSR Permit 22070

Description: Failure to maintain monthly emissions records for all storage tanks and loading operations.

Viol. Classification: Minor

Citation: 40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.246(h)(1)

Description: Failure to maintain documentation for the design criteria of the seal system, the barrier fluid system or both for dual mechanical seal pumps in benzene service.

Viol. Classification: Minor

Citation: 40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-1(d)

Description: Failure to label lines for Pygas.

Notice of Intent Date: 02/06/2006 (458261)

Disclosure Date: 08/04/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(D)

30 TAC Chapter 115, SubChapter H 115.781(b)

30 TAC Chapter 115, SubChapter H 115.789(1)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-4

40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-7

40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-4

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.169(a)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)(1)

Description: Failure to monitor valves, connectors and pressure relief valves under a prescribed Leak Detection and Repair Program.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to submit emissions inventories for missed component monitoring.

Notice of Intent Date: 02/27/2006 (459089)

Disclosure Date: 08/24/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter H 115.781(b)

30 TAC Chapter 115, SubChapter H 115.781(f)

30 TAC Chapter 115, SubChapter H 115.789(1)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)(1)

Rqmt Prov: PERMIT NSR Permit 5339

Description: Failure to monitor 146 Valves and 499 Connectors in the B15 Trichloroethanes Unit.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.1

Description: Failure to include components which missed monitoring in emissions inventory calculations.

Notice of Intent Date: 03/29/2006 (464367)

Disclosure Date: 08/30/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)

30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter D 115.354(2)(D)

Rqmt Prov: PERMIT NSR permit 2606

Description: Failure to monitor components

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in EIQ submittals

Notice of Intent Date: 03/29/2006 (464509)

Disclosure Date: 10/02/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter H 115.781(f)

30 TAC Chapter 115, SubChapter H 115.782(b)

30 TAC Chapter 115, SubChapter H 115.789(1)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)

Description: Failure to monitor 146 valves and 398 connectors.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in emissions calculations reporting.

Notice of Intent Date: 03/29/2006 (464513)

Disclosure Date: 08/30/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.160(c)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)(1)

Rqmt Prov: PERMIT NSR Permit 5340

Description: Failed to monitor 341 Valves and 1018 Connectors in the A18 Chlorinated Methane Unit.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include components which missed monitoring in the emissions inventory calculations.

Notice of Intent Date: 03/29/2006 (466306)

Disclosure Date: 09/28/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter H 115.781(b)

30 TAC Chapter 115, SubChapter H 115.781(f)

30 TAC Chapter 115, SubChapter H 115.789(1)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(b)(1)

Rqmt Prov: PERMIT NSR Permit 8567

Description: Failure to monitor 261 Valves and 715 Connectors in the B77 Adhesive Polymers Plant.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failed to include components that missed monitoring in emissions inventory calculations.

Notice of Intent Date: 03/29/2006 (466317)

Disclosure Date: 09/28/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)

Rqmt Prov: PERMIT NSR Permit 834

Description: Failure to monitor 828 Valves, 3981 Connectors, 4 Pumps, and 6 Relief Valves in the B41 Polyethylene Plant.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

Description: Failure to close 80 open ended lines in B41 Polyethylene Plant.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in emissions inventory calculations.

Notice of Intent Date: 04/21/2006 (465958)

Disclosure Date: 10/22/2006

Viol. Classification: Moderate

Citation: 40 CFR Chapter 60, SubChapter C, PT 60, SubPT VV 60.482-2
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-2
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(2)(i)

Rqmt Prov: PERMIT NSR Flex Permit 20432

Description: Failure to monitor 633 Valves, 5175 Connectors, 4 Relief Devices and 38 Pumps in the B71 Styrene Plant.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include components which missed monitoring in emissions inventory calculations.

Notice of Intent Date: 04/25/2006 (480426)

Disclosure Date: 10/22/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter H 115.781(b)
40 CFR Chapter 264, SubChapter I, PT 264, SubPT BB 264.1052
40 CFR Chapter 264, SubChapter I, PT 264, SubPT BB 264.1058
40 CFR Chapter 264, SubChapter I, PT 264, SubPT BB 264.1062(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.173
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(b)(1)

Rqmt Prov: PERMIT NSR Flex Permit 20525

PERMIT NSR Flex Permit 46429

PERMIT NSR Permit 8567

Description: Failure to monitor Valves, Connectors and Agitators in B44 Voranol Plant, failure to monitor Valves and Connectors in B46 SPC Plant and failure to monitor Valves and Connectors in B46 Blending Plant.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)

Rqmt Prov: PERMIT NSR Flex Permit 20525

PERMIT NSR Flex Permit 46429

Description: Failure to include 2 Pumps and 14 Relief Valves in the LDAR Program in B44 Voranol Plant, failure to include 3 Pumps in the LDAR Program in B46 SPC Plant.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include components which missed monitoring into Emissions Inventory calculations.

Notice of Intent Date: 05/12/2006 (465966)

Disclosure Date: 11/15/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1052
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1057(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.173
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Rqmt Prov: PERMIT NSR Flex permit 20432

Description: Failure to monitor 108 Valves, 392 Connectors and 3 Pumps in the B43 Epoxy 3. Failure to monitor 898 Valves, 3018 Connectors, 12 Pressure Relief Valves, 10 Pumps and 1 Agitator in the B62 Epoxy 2.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in emissions inventory calculations.

Viol. Classification: Minor

Citation: 1 THC Chapter 1 1.001(a)

Rqmt Prov: PERMIT Title V permit O-02207

Description: Failure to included missed monitored components in previous Title V Deviation Reports.

Notice of Intent Date: 06/13/2006 (484536)

Disclosure Date: 05/14/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)

Rqmt Prov: PERMIT NSR permit 20432

Description: Failure to monitor components

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components on EIQ reports

Notice of Intent Date: 06/20/2006 (486601)

Disclosure Date: 12/21/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 106, SubChapter K 106.261
30 TAC Chapter 106, SubChapter K 106.262
30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(b)(3)
30 TAC Chapter 115, SubChapter H 115.781(b)(8)
30 TAC Chapter 115, SubChapter H 115.789(1)

Rqmt Prov: PERMIT NSR permit 20775

Description: Failure to monitor components

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components on EIQ submittals

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V Operating Permit O-02219

Description: Failure to include missed monitored components on Title V deviation report

Notice of Intent Date: 06/26/2006 (488476)

Disclosure Date: 12/27/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(2)(i)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(b)(1)

Rqmt Prov: PERMIT NSR 19041

Description: Failure to monitor 3126 valves, 10975 connectors, 8 relief devices, 12 pumps.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in emission calculations reporting.

Viol. Classification: Moderate

Rqmt Prov: PERMIT O-2204

Description: Failure to include missed monitored components in previous Title V deviation reports.

Notice of Intent Date: 08/15/2006 (511065)

Disclosure Date: 11/15/2006

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1052
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1057(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Description: Failure to monitor 402 Valves, 1425 Connectors, 8 Relief Devices and 2 Pumps in the B64 HydroxyAlkylAcrylate Plant.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in the emissions inventory calculations.

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V permit O-02207

Description: Failure to include missed monitored components in previous Title V deviation reports.

Notice of Intent Date: 08/28/2006 (514018)

No DOV Associated

Notice of Intent Date: 10/24/2006 (461404)

Disclosure Date: 04/25/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.169(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Description: Failure to monitor valves, connectors, relief devices and pumps.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include emissions of missed monitored components in emission calculation reporting.
Viol. Classification: Moderate
Citation: 1 THC Chapter 1 1.001(a)
Rqmt Prov: PERMIT Title V Permit O-2207
Description: Failure to include missed monitored components in Title V deviation reports.

Notice of Intent Date: 12/13/2006 (536545)
Disclosure Date: 06/13/2007
Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
Rqmt Prov: PERMIT Permit 20777
Description: Failure to monitor components.
Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include missed monitored components in EIQ submittals.
Viol. Classification: Minor
Rqmt Prov: PERMIT Title V Operating Permit O-02218
Description: Failure to include missed monitored components in the Title V deviation report.

Notice of Intent Date: 12/13/2006 (536549)
Disclosure Date: 06/13/2007
Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
Rqmt Prov: PERMIT Title V Operating Permit O-02221
Description: Failure to monitor components
Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include missed monitored components in EIQ.
Viol. Classification: Minor
Citation: 1 THC Chapter 1 1.001(a)
Rqmt Prov: PERMIT Title V O-02221
Description: Failure to include missed monitored components in Title V deviation report

Notice of Intent Date: 12/27/2006 (537891)
Disclosure Date: 06/26/2007
Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)
Rqmt Prov: PERMIT NSR permit 4031
Description: Failure to monitor components
Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include components in EIQ report submittals
Viol. Classification: Minor
Citation: 1 THC Chapter 1 1.001(a)
Rqmt Prov: PERMIT Title V Operating Permit O-02203
Description: Failure to include missed monitored components on Title V deviation report

Notice of Intent Date: 01/09/2007 (541786)

Disclosure Date: 07/11/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)

Rqmt Prov: PERMIT NSR Permit 20432

Description: Failure to monitor components under a prescribed LDAR program.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10(a)

Description: Failure to include missed monitored components in Emissions Inventory

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V O-02207

Description: Failure to include missed monitored components in Title V deviation reports.

Notice of Intent Date: 01/12/2007 (554256)

No DOV Associated

Notice of Intent Date: 01/19/2007 (541798)

Disclosure Date: 07/12/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(b)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)

Rqmt Prov: PERMIT NSR permit 48715

Description: Failure to, under a prescribed LDAR program, monitor 462 valves, 2873 connectors, 1 pump, 5 relief valves.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in EIQs.

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V O-02204

Description: Failure to include missed monitored components in Title V deviation report.

Notice of Intent Date: 01/19/2007 (541800)

Disclosure Date: 07/13/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(2)(i)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Rqmt Prov: PERMIT NSR 3320

Description: Failure to monitor components under a prescribe LDAR program.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in EIQ.

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V O-02209

Description: Failure to include missed monitored components on Title V deviation report.

Notice of Intent Date: 01/25/2007 (541805)
Disclosure Date: 07/30/2007
Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
Description: Failure to monitor components.
Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include missed monitored components in EIQ.
Viol. Classification: Minor
Rqmt Prov: PERMIT Title V O-02211
Description: Failure to include missed monitored components on Title V deviation report.

Notice of Intent Date: 01/25/2007 (541810)
Disclosure Date: 07/25/2007
Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.352(1)(A)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
30 TAC Chapter 115, SubChapter H 115.781(f)
30 TAC Chapter 115, SubChapter H 115.789(1)
Description: Failure to monitor components under a prescribed LDAR program.
Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include missed monitored components in EIQ.
Viol. Classification: Minor
Rqmt Prov: PERMIT Title V O-02311
Description: Failure to include missed monitored components on Title V deviation report.

Notice of Intent Date: 02/13/2007 (542642)
Disclosure Date: 07/30/2007
Viol. Classification: Moderate
Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1362(c)(6)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(c)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(e)
Description: Failure to monitor components under a prescribe LDAR program.
Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include missed monitored components EIQ.
Viol. Classification: Minor
Rqmt Prov: PERMIT Title V O-02205
Description: Failure to include missed monitored components on Title V deviation report.

Notice of Intent Date: 02/12/2007 (542650)
Disclosure Date: 07/14/2007
Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.169(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)
Rqmt Prov: PERMIT NSR 2008
Description: Failure to monitor components under a prescribed LDAR program.
Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Description: Failure to include missed monitored components in Emissions Inventory.

Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10
Rqmt Prov: PERMIT O-02216

Description: Failure to include missed monitored components in Title V deviation report.

Notice of Intent Date: 02/26/2007 (554272)
Disclosure Date: 08/23/2007

Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)

30 TAC Chapter 115, SubChapter D 115.354(2)(C)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Rqmt Prov: PERMIT NSR 4031

Description: Failure to monitor all valves, connectors, pumps, relief valves under a prescribed leak detection and repair program.

Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to report missed monitored components in emissions calculations.

Viol. Classification: Minor
Rqmt Prov: PERMIT O-02203

Description: Failure to include missed monitored components on Title V deviation report.

Notice of Intent Date: 02/26/2007 (554275)
Disclosure Date: 08/24/2007

Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in emissions calculations.

Viol. Classification: Minor
Citation: 2E THSC Chapter 101, SubChapter B 101.001
Rqmt Prov: PERMIT O-02204

Description: Failure to include missed monitored components on a Title V deviation report.

Notice of Intent Date: 02/26/2007 (554300)
Disclosure Date: 08/23/2007

Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1026(b)(2)(iii)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1035
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Rqmt Prov: PERMIT NSR 18561

Description: Failure to monitor all valves, connectors and a pump under a prescribed Leak Detection and Repair program.

Viol. Classification: Minor
Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to report missed monitored components in emissions calculations.

Viol. Classification: Minor
Rqmt Prov: PERMIT O-02203

Description: Failure to include missed monitored components on Title V deviation reports.

Notice of Intent Date: 04/02/2007 (557536)
Disclosure Date: 10/11/2007

Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter D 115.352(1)(A)
30 TAC Chapter 115, SubChapter D 115.352(1)(B)

30 TAC Chapter 115, SubChapter D 115.354(2)(C)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1026(b)(2)(iii)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1035
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEEE 63.2346

Rqmt Prov: PERMIT NSR Permit 18950
PERMIT NSR Permit 19720
PERMIT NSR Permit 19792
PERMIT NSR Permit 22070
PERMIT NSR Permit 22071
PERMIT NSR Permit 48892

Description: Failure to monitor several components in the Marine and Terminal Operations.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in EIQ.

Viol. Classification: Minor

Citation: 1 THC Chapter 1 1.001(a)

Rqmt Prov: PERMIT Title V Permit O-02217

Description: Failure to include missed monitored components on Title V Deviation Report.

Notice of Intent Date: 04/02/2007 (557539)

Disclosure Date: 07/25/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.352(1)(A)
30 TAC Chapter 115, SubChapter D 115.354(2)(B)
30 TAC Chapter 115, SubChapter D 115.354(2)(C)
30 TAC Chapter 115, SubChapter D 115.354(2)(D)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(2)(i)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)
40 CFR Part 63, Subpart H 63.173
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Rqmt Prov: PERMIT NSR 7531

Description: Failure to monitor all valves, connectors, relief valves, pumps and agitator.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to report missed monitored components in emissions calculations.

Viol. Classification: Minor

Rqmt Prov: PERMIT O-02210

Description: Failure to include missed monitored components in Title V deviation report.

Notice of Intent Date: 04/02/2007 (557547)

Disclosure Date: 10/11/2007

Viol. Classification: Moderate

Citation: 1 THC Chapter 1 1.001(a)
30 TAC Chapter 115, SubChapter B 115.132(a)
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1057(c)

Description: Failure to monitor components in B-52 Epoxy.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in EIQ.

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V Operating Permit O-02207

Description: Failure to include missed monitored components in Title V report.

Notice of Intent Date: 04/18/2007 (558622)

No DOV Associated

Notice of Intent Date: 04/16/2007 (558628)

Disclosure Date: 11/04/2007

Viol. Classification: Moderate

Citation: 40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1057(c)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1035(b)

Rqmt Prov: PERMIT NSR 1472

Description: Failure to monitor specific components.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components on emissions inventory report.

Viol. Classification: Minor

Rqmt Prov: PERMIT O-2220

Description: Failure to include missed monitored components on emissions inventory report.

Notice of Intent Date: 04/19/2007 (558643)

No DOV Associated

Notice of Intent Date: 04/19/2007 (558652)

Disclosure Date: 04/24/2008

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1027(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT UU 63.1035(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(b)(3)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(e)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)

Description: Failure to monitor 49 valves, 186 connectors and 1 pump under a prescribed LDAR program.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to report missed monitored components in emissions calculations.

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V Permit O-02211

Description: Failure to include missed monitored components in Title V deviation report.

Notice of Intent Date: 04/20/2007 (558658)

Disclosure Date: 11/16/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)

30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter D 115.354(2)(D)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.163(b)(2)(i)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.169(a)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.174(a)(1)

Description: Failure to monitor specific components.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to include missed monitored components in emissions inventory report.

Viol. Classification: Minor

Rqmt Prov: PERMIT O-2213

Description: Failure to include missed monitored components on Title V deviation report.

Notice of Intent Date: 04/18/2007 (558712)

Disclosure Date: 04/24/2008

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)
40 CFR Chapter 264, SubChapter I, PT 264, SubPT BB 264.1062(b)(3)
40 CFR Part 60, Subpart VV 60.482-8
40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.243-2(b)(3)
40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.349(a)(1)(i)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(e)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)

Description: Failure to monitor 110 valves and 567 connectors under a prescribed LDAR program.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to report emission calculations for missed monitored components.

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V Permit O-02211

Description: Failure to include missed monitored components in Title V deviation reports.

Notice of Intent Date: 04/20/2007 (558725)

Disclosure Date: 11/16/2007

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(B)

30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter D 115.354(2)(D)

30 TAC Chapter 115, SubChapter H 115.781(b)

30 TAC Chapter 115, SubChapter H 115.781(b)(8)

30 TAC Chapter 115, SubChapter H 115.781(f)

Description: Failure to monitor specific components under a prescribed Leak Detection and Repair Program.

Viol. Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to report emission calculations for missed monitored components.

Viol. Classification: Minor

Rqmt Prov: PERMIT O-2213

Description: Failure to include missed monitored components in Title V deviation report.

Notice of Intent Date: 04/18/2007 (558733)

Disclosure Date: 04/24/2008

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

40 CFR Part 60, Subpart VV 60.482-8

40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.349(a)(1)(i)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.168(b)

Rqmt Prov: PERMIT NSR 46428

Description: Failure to monitor 42 valves and 291 connectors under a prescribed LDAR program.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.10

Description: Failure to report emissions calculations for missed monitored components.

Viol. Classification: Minor

Rqmt Prov: PERMIT Title V Permit O-02211

Description: Failure to include missed monitored components in Title V deviation report.

Notice of Intent Date: 05/14/2007 (564251)

No DOV Associated

Notice of Intent Date: 10/02/2007 (598845)

No DOV Associated

Notice of Intent Date: 10/25/2007 (600864)

No DOV Associated

Notice of Intent Date: 10/25/2007 (600866)

No DOV Associated

Notice of Intent Date: 04/29/2008 (681813)

No DOV Associated

Notice of Intent Date: 07/02/2008 (114194)

No DOV Associated

Notice of Intent Date: 09/02/2008 (706228)

Disclosure Date: 04/03/2009

Viol. Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125

Rqmt Prov: PERMIT RCRA Permit HW-50161-001

Description: Failure to maintain sufficient documentation demonstrating that personnel responsible for ensuring compliance with the RCRA permit are familiar with the location and content of the RCRA permit.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 264, SubChapter I, PT 264, SubPT C 264.37(a)

40 CFR Chapter 264, SubChapter I, PT 264, SubPT C 264.37(b)

Description: Failure to maintain sufficient documentation that confirms arrangements with local authorities (police and hospital) is in place as appropriate for the type of waste handled at the Dow facility in Freeport, Texas.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125

Rqmt Prov: PERMIT RCRA Permit 50161-001

Description: Failure to maintain sufficient documentation that annual certification of wastes meeting Land Disposal Requirements are kept on record at the Dow facility in Freeport, Texas.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125

Rqmt Prov: PERMIT RCRA Permit 50161-001

Description: Failure to use the sampling and analytical methods in permit 50161-001 during initial pre-shipment analysis of incoming bulk, liquid wastes at the B-33 Kiln.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 265, SubChapter I, PT 265, SubPT I 265.177(c)

Description: Failure to properly store hazardous waste. Specifically, storage containers holding a hazardous waste that may be incompatible with waste or other materials stored nearby, in other containers, are not separated from other materials or protected from them by means of a dike, berm, wal, or other device.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125

Rqmt Prov: PERMIT RCRA Permit 50161-001

Description: Failure to maintain sufficient documentation that compressive strength testing is performed to demonstrate successful stabilization prior whenever stabilization of hazardous waste is based solely on a pozzolanic reaction.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125

Rqmt Prov: PERMIT RCRA Permit 50161-001

Description: Failure to maintain sufficient documentation that compressive strength testing was performed to demonstrate successful stabilization of waste prior to landfilling.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 266, SubChapter I, PT 266, SubPT O 268.3

Rqmt Prov: PERMIT RCRA Permit 50161-001

Description: Failure to properly manage waste streams subject to Land Disposal Restrictions. Specifically, waste streams may have been treated using a potentially ineffective treatment method.

Viol. Classification: Moderate
Citation: 30 TAC Chapter 305, SubChapter F 305.125
Rqmt Prov: PERMIT RCRA Permit 50161-001

Description: Failure to maintain sufficient documentation that initial shipments and random fingerprint analysis on subsequent shipments of offsite bulk and containerized wastes, destined for the B-51 Hazardous Waste Landfill are subjected to a fingerprint analysis to verify that the Waste Profile associated with the waste is correct.

Viol. Classification: Moderate
Citation: 30 TAC Chapter 305, SubChapter F 305.125
Rqmt Prov: PERMIT RCRA Permit 50161-001

Description: Failure to maintain sufficient documentation that incinerator residue contaminated with F024/K022 (scrubber water filter cake) waste number 5034503H on the Notice of Registration (Dow Waste Profile Number 119111-000) were adequately analyzed after stabilization and prior to landfilling.

Notice of Intent Date: 10/24/2008 (707543)
Disclosure Date: 11/10/2009

Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter B 115.121(a)(2)
30 TAC Chapter 115, SubChapter B 115.122(a)(2)
30 TAC Chapter 115, SubChapter B 115.125
30 TAC Chapter 115, SubChapter B 115.126
30 TAC Chapter 115, SubChapter B 115.126(1)(C)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT F 63.102(a)(1)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.113(a)(2)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.116(c)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.118(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.152(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.152(c)

Description: Failure to classify caustic scrubbers as HON control devices and perform tests or monitor HON control devices for purposes of HON MACT or Reg V Vent Gas Control requirements.

Viol. Classification: Minor
Citation: 30 TAC Chapter 115, SubChapter B 115.116

Description: Failure to amend the NSR Air permit to authorize process vents to be intermittently redirected from the THROX to the T-2910/T-2912 caustic scrubbers under normal operating conditions since 1999.

Viol. Classification: Moderate
Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT F 63.103(c)

Description: Failure to keep available bypass records for any SSM diversions of DK-2822 from F-2820 boiler/T-2830 halogen scrubber to the caustic scrubbers, T2910/T-2912.

Viol. Classification: Minor
Citation: 40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.11(d)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.7(a)(1)
40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.7(a)(3)

Description: Failure to submit update to Title V for NSPS RRR and NSPS NNN applicability related to reactors R-2301 and R-2302 and distillation units RT-2303 and T-2403, respectively.

Viol. Classification: Moderate
Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.129
40 CFR Chapter 63, SubChapter C, PT 63, SubPT G 63.152(b)(1)

Description: Failure to submit either original HON Subpart Notification of Compliance Status (NOCS) or supplemental NOCS for the Group 2 TDI tank truck (B4TDILR1) and railcar (B4TDILR2) transfer operations.

Viol. Classification: Moderate
Citation: 40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.1(b)(3)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.10(b)(3)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT FFFF 63.2515(b)

Description: Failure to document negative applicability with 40 CFR 63 Subpart FFFF, Miscellaneous Organic NESHAP (MON).

Viol. Classification: Moderate
Citation: 30 TAC Chapter 115, SubChapter B 115.116

Description: Failure to maintain adequate records for MSS activities and emissions that are noted in Special Condition No. 21 of NSR Air permit.

Viol. Classification: Moderate
Citation: 30 TAC Chapter 106, SubChapter K 106.263

Description: Failure to amend TCEQ NSR Air Permit No. 2008 to authorize maintenance, startup, shutdown emissions routed from the emissions vacuum system to the T-2914 scrubber.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter F 101.201(b)(2)

Description: Failure to maintain adequate operating procedures and recordkeeping for emission events that emit less than Reportable Quantity (RQ).

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354(2)(C)

30 TAC Chapter 115, SubChapter D 115.354(3)

Description: Failure to operate forced and induced draft blowers to maintain proper mitigation building pressure while the phosgene service units are in operation.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter B 115.116

Description: Failure to abide by Condition 4 of the AMOC 2000-01 which requires the Flange Leak Detection System (FLDS) to be vented to the THROX system or to submit a request to revise the AMOC to allow diversion to the T-2910/T-2912 scrubbers when the THROX system is unavailable or down.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter B 115.116

Description: Failure to implement management systems to ensure all instrumentation is calibrated to the required frequency.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 262, SubChapter I, PT 262, SubPT C 262.34

Description: Failure to classify the D-10 vessel as a RCRA Hazardous Waste vessel.

Notice of Intent Date: 11/06/2008 (722259)

No DOV Associated

Notice of Intent Date: 11/20/2008 (707260)

No DOV Associated

Notice of Intent Date: 11/18/2008 (722258)

No DOV Associated

Notice of Intent Date: 11/25/2008 (721910)

No DOV Associated

Notice of Intent Date: 01/22/2009 (739319)

No DOV Associated

Notice of Intent Date: 03/17/2009 (742452)

Disclosure Date: 03/22/2010

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620

40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(10)

40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(8)(i)(A)

40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(8)(i)(B)

30 TAC Chapter 335, SubChapter H 335.221(a)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.10(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(a)(6)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to extract required one-minute average (OMA) and hourly rolling average (HRA) operating data, including constituent feed rates.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(6)
30 TAC Chapter 305, SubChapter F 305.127(2)
30 TAC Chapter 335, SubChapter H 335.221(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(c)(3)(B)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(c)(3)(C)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(a)(6)(ii)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(b)(5)(ii)

Description: Failure to maintain programming: did not properly trigger automatic waste feed cut off (AWFCO), did not convert OMA readings from carbon monoxide CEMS system to 10,000 ppmv when 3,000 PPMV is exceeded, did not properly calculate of the hourly rolling averages when instrument failure is detected, and did not initiate an AWFCO when the span of a continuous monitoring system (CMS) (except CEMS) was exceeded and when there is a CMS malfunction.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(10)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(8)(iv)
30 TAC Chapter 305, SubChapter F 305.127
30 TAC Chapter 305, SubChapter F 305.127(2)
30 TAC Chapter 335, SubChapter H 335.221(a)

Description: Failure to document compliance with the RCRA permit requirement for annual feed rate limits, and weekly AWFCO alarm testing.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(10)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(8)(i)(A)
40 CFR Chapter 266, SubChapter I, PT 266, SubPT H 266.102(e)(8)(i)(B)
30 TAC Chapter 335, SubChapter H 335.221
30 TAC Chapter 335, SubChapter H 335.221(a)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.10(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(a)(6)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(b)(5)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to change HRA values for operating parameters for extended periods to show accurate data.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(c)(2)(iii)

Description: Failure to identify an oxygen correction in the Startup, Shutdown, and Malfunction (SSM) Plan for the HWC MACT.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to determine and document the maximum amount of constituents that could enter the Thermal Oxidizer via the various non-waste sources and programmed this information so that this contribution is accounted for in the feed rate determinations.

Viol. Classification: Moderate

Citation: 4F TWC Chapter 63, SubChapter A 63.109

Description: Failure to use One Minute Averages (OMAs) instead of Minute Rolling Averages (MRAs) to determine Hourly Rolling Averages (HRAs) for at least the following parameters- HCl Production, Ejector Venturi Feed Pressure, Demister pH, and D-30 Blowdown.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620
40 CFR Chapter 264, SubChapter I, PT 264, SubPT O 264.347(d)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.10(b)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(b)(5)
40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to extract OMA and HRA operating data for the After Burner Chamber (ABC) temperature and Scrubber Tower pump amperage.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620
40 CFR Chapter 63, SubChapter C, PT 63, SubPT A 63.10(b)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1209(b)(5)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to update HRA values for various operating parameters for extended periods of time.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620

40 CFR Chapter 264, SubChapter I, PT 264, SubPT O 264.345(e)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(c)(3)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to monitor the flow meter's performance.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1203(a)(3)

Description: Failure to properly convert OMA readings from the carbon monoxide CEMS system to 10000 ppmv when the 3000 ppmv span is exceeded.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 264, SubChapter I, PT 264, SubPT O 264.347(d)

30 TAC Chapter 305, SubChapter F 305.127(2)

Description: Failure to verify compliance with RCRA permits requirements for annual feed rate limits.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 270, SubChapter I, PT 270, SubPT C 270.30(l)(1)

Description: Failure to modify the RCRA permit to correct the discrepancies concerning the arrangement and size of the vent spargers in the Afterburner Chamber.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to include feed rates of constituents in the process vents, tank vents and supplemental fuels identified in Table V.I.3 of the permit and HWC MACT Table 2 Documentation of Compliance for this unit.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter B 115.116

Description: Failure to include quantities of solid waste from the pack-line in the Total Hazardous Waste calculations.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(c)

Description: Failure to review and update the Operation and Maintenance Plan in 2007.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1206(c)

Description: Failure to disclose summary information associated with 10 malfunction events in 60 days in the January 2009 HWC MACT periodic report.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 113, SubChapter C 113.620

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEE 63.1211(c)

Description: Failure to calibrate flow meter.

Notice of Intent Date: 03/24/2009 (742462)

No DOV Associated

Notice of Intent Date: 03/30/2009 (742456)

No DOV Associated

Notice of Intent Date: 04/13/2009 (744897)

No DOV Associated

Notice of Intent Date: 05/04/2009 (746990)

No DOV Associated

Notice of Intent Date: 05/13/2009 (746992)

No DOV Associated

Notice of Intent Date: 05/22/2009 (764971)

No DOV Associated

Notice of Intent Date: 05/28/2009 (759316)

No DOV Associated

Notice of Intent Date: 06/08/2009 (760155)

No DOV Associated

Notice of Intent Date: 06/12/2009 (762770)

No DOV Associated

Notice of Intent Date: 06/17/2009 (761059)

No DOV Associated

Notice of Intent Date: 06/29/2009 (761341)

No DOV Associated

Notice of Intent Date: 07/02/2009 (762286)

No DOV Associated

Notice of Intent Date: 07/02/2009 (762304)

No DOV Associated

Notice of Intent Date: 07/13/2009 (763446)

No DOV Associated

Notice of Intent Date: 07/17/2009 (764099)

Disclosure Date: 10/01/2009

Viol. Classification: Moderate

Citation: 40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1057(a)

Description: Failure to include the lab waste dumpster, DTA-1, in the current fugitive monitoring program.

Notice of Intent Date: 07/16/2009 (764103)

Disclosure Date: 10/01/2009

Viol. Classification: Moderate

Citation: 40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1057(a)
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1061
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1062
40 CFR Chapter 265, SubChapter I, PT 265, SubPT BB 265.1063(b)

Description: Failure to include the lab waste dumpster, DTA-1, in the current fugitive monitoring program.

Notice of Intent Date: 07/23/2009 (764096)

No DOV Associated

Notice of Intent Date: 07/22/2009 (764098)

No DOV Associated

Notice of Intent Date: 07/28/2009 (764976)

Disclosure Date: 08/02/2010

Viol. Classification: Moderate

Citation: 40 CFR Chapter 136, SubChapter D, PT 136.136.1

Rqmt Prov: PERMIT TPDES Permit No. WQ0000007000

Description: Failure to reflect the current analytical personnel that could perform regulated analyses to support the site Texas Pollutant Discharge Elimination System Permit.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 262, SubChapter I, PT 262, SubPT B 262.20(a)(1)

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to keep correct and required information for waste manifests.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 264, SubChapter I, PT 264, SubPT E 264.72(d)(1)

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to locate manifest to determine the disposition of four rejected waste drums.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 262, SubChapter I, PT 262, SubPT C 262.34

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to dispose waste containers that were past the permitted accumulation date.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter C 335.67

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to adequately label containers.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 106, SubChapter T 106.452

Description: Failure to document how emissions from a grit blaster located in the landfill maintenance area are authorized.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 264, SubChapter I, PT 264, SubPT I 264.175

Description: Failure to store a pallet of 4 drums of closed, labeled ferric sulfate residue wastes in proper location.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter A 335.6(c)

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to properly label and store a drum of methylene chloride.

Viol. Classification: Moderate

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to label a partially full drum of clean sawdust located within a satellite container storage area.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 264, SubChapter I, PT 264, SubPT D 264.54(d)

Description: Failure to update personnel list in the Waste Water Treatment Plant RCRA Contingency Plan.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 265, SubChapter I, PT 265, SubPT C 265.35

Description: Failure to store hazardous waste containers with the required storage space between containers to facilitate required inspections.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 264, SubChapter I, PT 264, SubPT I 264.173

40 CFR Chapter 264, SubChapter I, PT 264, SubPT I 264.175

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to store four drums of hazardous waste in designated storage area. One of four hazardous drums was uncovered.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 262, SubChapter I, PT 262, SubPT C 262.34(a)

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to label waste trailer in the <90 day container storage area with accumulation start date.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 335, SubChapter A 335.6(c)

Rqmt Prov: PERMIT HW 50161-001 Permit

Description: Failure to list container storage areas in the facility's notice of registration.

Viol. Classification: Moderate

Rqmt Prov: PERMIT HW 50601-001 Permit

Description: Failure to properly store waste containers in satellite accumulation area.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 264, SubChapter I, PT 264, SubPT C 264.15(d)

Description: Failure to communicate expectation of legible signature on all compliance documents to all Environmental Operations personnel.

Viol. Classification: Moderate

Citation: 30 TAC Chapter 115, SubChapter D 115.354

40 CFR Chapter 61, SubChapter C, PT 61, SubPT V 61.242-1(a)

40 CFR Chapter 61, SubChapter C, PT 61, SubPT FF 61.349(a)(1)(i)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT MMM 63.1363(a)

40 CFR Part 63, Subpart H 63.163

40 CFR Part 63, Subpart H 63.164

40 CFR Part 63, Subpart H 63.165

40 CFR Part 63, Subpart H 63.166

40 CFR Part 63, Subpart H 63.167

40 CFR Part 63, Subpart H 63.168

40 CFR Part 63, Subpart H 63.169

40 CFR Part 63, Subpart H 63.170

40 CFR Part 63, Subpart H 63.171

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.172

40 CFR Part 63, Subpart H 63.173

40 CFR Part 63, Subpart H 63.174

40 CFR Chapter 63, SubChapter C, PT 63, SubPT EEEE 63.2346(c)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT FFFF 63.2480(a)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT DD 63.691(b)

Rqmt Prov: PERMIT HW #50161-001 X.B.2.g.

PERMIT NSR permit #46428 SC#6

Description: Failure to meet leak detection requirements for 181 valves, 910 connectors, 5 pumps, 15 pressure relief devices and 7 agitators throughout the B33, B34, B35 process areas.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 122, SubChapter D, PT 122, SubPT B 122.26

Rqmt Prov: PERMIT TPDES Permit No. WQ0000007000

Description: Failure to conduct 10 of 13 weekly visual inspections on the correct day as required by the Storm Water Pollution Prevention Plan for Chlorine 7 project.

Viol. Classification: Moderate

Citation: 40 CFR Chapter 122, SubChapter D, PT 122, SubPT B 122.26

Rqmt Prov: PERMIT TPDES permit No. WQ0000007000

Description: Failure to update the erosion controls drawing in the Storm Water Pollution Prevention Plan for the Chlorine 7 project and the revision sheet with amended Drainage Ditch Plan.

Notice of Intent Date: 07/30/2009 (765501)

No DOV Associated

Notice of Intent Date: 08/21/2009 (762243)

No DOV Associated

Notice of Intent Date: 08/26/2009 (776290)

No DOV Associated

Notice of Intent Date: 09/01/2009 (776285)

Disclosure Date: 09/18/2009

Viol. Classification: Moderate

Citation: 30 TAC Chapter 111, SubChapter A 111.111(a)(1)(C)

Rqmt Prov: PERMIT Operating Permit O-02204

Description: Failure to document visible emission observations of stationary source OCSU5GE500 (FIN) since the Title V permit was issued on February 28, 2005.

Notice of Intent Date: 09/08/2009 (776284)

No DOV Associated

Notice of Intent Date: 09/14/2009 (777729)

Disclosure Date: 05/12/2010

Viol. Classification: Moderate

Rqmt Prov: PERMIT Special Condition No. 3

Description: Failure to perform or document visible emission observations of the following stationary sources:
A12SIGE12; B1SIGE13; B12SIGE12; B2SIGE280; OC7SIGE704.

Notice of Intent Date: 10/02/2009 (779123)

No DOV Associated

Notice of Intent Date: 10/07/2009 (782753)

No DOV Associated

Notice of Intent Date: 10/07/2009 (782760)

No DOV Associated

Notice of Intent Date: 10/14/2009 (782930)

No DOV Associated

Notice of Intent Date: 10/27/2009 (748465)

No DOV Associated

Notice of Intent Date: 11/10/2009 (794164)
No DOV Associated

Notice of Intent Date: 11/13/2009 (794815)
No DOV Associated

Notice of Intent Date: 11/20/2009 (794361)
No DOV Associated

Notice of Intent Date: 11/24/2009 (794384)
No DOV Associated

Notice of Intent Date: 12/04/2009 (787544)
No DOV Associated

Notice of Intent Date: 01/14/2010 (794380)
No DOV Associated

Notice of Intent Date: 01/18/2010 (794383)
No DOV Associated

Notice of Intent Date: 02/05/2010 (797639)
No DOV Associated

Notice of Intent Date: 02/16/2010 (797641)
No DOV Associated

Notice of Intent Date: 02/18/2010 (797644)
No DOV Associated

Notice of Intent Date: 02/19/2010 (797657)
No DOV Associated

Notice of Intent Date: 02/19/2010 (797662)
No DOV Associated

Notice of Intent Date: 03/01/2010 (798594)
No DOV Associated

Notice of Intent Date: 03/12/2010 (798597)
No DOV Associated

Notice of Intent Date: 03/09/2010 (798600)
No DOV Associated

Notice of Intent Date: 03/08/2010 (798627)
No DOV Associated

Notice of Intent Date: 03/12/2010 (798632)
No DOV Associated

Notice of Intent Date: 03/15/2010 (798500)
No DOV Associated

Notice of Intent Date: 03/25/2010 (800777)
No DOV Associated

Notice of Intent Date: 03/26/2010 (800833)
No DOV Associated

Notice of Intent Date: 03/31/2010 (800749)
No DOV Associated

Notice of Intent Date: 04/05/2010 (800702)
No DOV Associated

Notice of Intent Date: 04/16/2010 (800774)
No DOV Associated

Notice of Intent Date: 04/15/2010 (800792)
No DOV Associated

Notice of Intent Date: 04/19/2010 (800794)
No DOV Associated

Notice of Intent Date: 05/01/2010 (826930)
No DOV Associated

Notice of Intent Date: 04/26/2010 (826936)
No DOV Associated

Notice of Intent Date: 04/26/2010 (826940)
No DOV Associated

Notice of Intent Date: 05/03/2010 (826921)
No DOV Associated

Notice of Intent Date: 05/04/2010 (826948)
No DOV Associated

Notice of Intent Date: 05/26/2010 (826923)
No DOV Associated

Notice of Intent Date: 06/01/2010 (826916)
No DOV Associated

Notice of Intent Date: 06/03/2010 (846000)
No DOV Associated

Notice of Intent Date: 06/10/2010 (827965)
No DOV Associated

Notice of Intent Date: 06/24/2010 (841010)

No DOV Associated

Notice of Intent Date: 07/12/2010 (841127)

No DOV Associated

Notice of Intent Date: 07/23/2010 (843903)

No DOV Associated

Notice of Intent Date: 07/28/2010 (848864)

No DOV Associated

Notice of Intent Date: 07/29/2010 (848881)

No DOV Associated

Notice of Intent Date: 08/04/2010 (849288)

No DOV Associated

Notice of Intent Date: 08/04/2010 (849315)

No DOV Associated

G. Type of environmental management systems (EMSs).

N/A

H. Voluntary on-site compliance assessment dates.

N/A

I. Participation in a voluntary pollution reduction program.

N/A

J. Early compliance.

N/A

Sites Outside of Texas

N/A

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



IN THE MATTER OF AN
ENFORCEMENT ACTION
CONCERNING
THE DOW CHEMICAL COMPANY
RN100225945

§ BEFORE THE
§
§ TEXAS COMMISSION ON
§
§ ENVIRONMENTAL QUALITY

AGREED ORDER
DOCKET NO. 2010-1450-AIR-E

I. JURISDICTION AND STIPULATIONS

At its _____ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding The Dow Chemical Company ("the Respondent") under the authority of TEX. HEALTH & SAFETY CODE ch. 382 and TEX. WATER CODE ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent appear before the Commission and together stipulate that:

1. The Respondent owns and operates a power generation plant at 2301 North Brazosport Boulevard in Freeport, Brazoria County, Texas (the "Plant").
2. The Plant consists of one or more sources as defined in TEX. HEALTH & SAFETY CODE § 382.003(12).
3. The Commission and the Respondent agree that the Commission has jurisdiction to enter this Agreed Order, and that the Respondent is subject to the Commission's jurisdiction.
4. The Respondent received notice of the violations alleged in Section II ("Allegations") on or about November 3, 2010.
5. The occurrence of any violation is in dispute and the entry of this Agreed Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.

6. An administrative penalty in the amount of Ninety-Six Thousand Nine Hundred Seventy-Five Dollars (\$96,975) is assessed by the Commission in settlement of the violations alleged in Section II ("Allegations"). The Respondent has paid Thirty-Eight Thousand Seven Hundred Ninety Dollars (\$38,790) of the administrative penalty and Nineteen Thousand Three Hundred Ninety-Five Dollars (\$19,395) is deferred contingent upon the Respondent's timely and satisfactory compliance with all the terms of this Agreed Order. The deferred amount will be waived upon full compliance with the terms of this Agreed Order. If the Respondent fails to timely and satisfactorily comply with all requirements of this Agreed Order, the Executive Director may require the Respondent to pay all or part of the deferred penalty. Thirty-Eight Thousand Seven Hundred Ninety Dollars (\$38,790) shall be conditionally offset by the Respondent's completion of a Supplemental Environmental Project ("SEP").
7. Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
8. The Executive Director of the TCEQ and the Respondent have agreed on a settlement of the matters alleged in this enforcement action, subject to the approval of the Commission.
9. The Executive Director recognizes that, by September 30, 2010, the Respondent implemented an electronic system for environmental health and safety management to review upcoming permit renewal deadlines so permit renewals will not be overlooked in the future.
10. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
11. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
12. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable.

II. ALLEGATIONS

As owner and operator of the Plant, the Respondent is alleged to have:

1. Failed to submit an application for renewal prior to the expiration of a permit and continued to operate without authorization after the permit expired, in violation of 30 TEX. ADMIN. CODE § 116.110(a) and TEX. HEALTH & SAFETY CODE §§ 382.0518(a) and 382.085(b), as documented during an investigation conducted on September 1, 2010. Specifically, the Respondent failed to renew Standard Permit Registration No. 43417 for the wet compression equipment before the permit expiration date of February 16, 2010.

2. Failed to submit an application for renewal prior to expiration of a permit and continued to operate without authorization after the permit expired, in violation of 30 TEX. ADMIN. CODE § 116.110(a) and TEX. HEALTH & SAFETY CODE §§ 382.0518(a) and 382.085(b), as documented during an investigation conducted on September 1, 2010. Specifically, the Respondent failed to renew New Source Review ("NSR") Permit No. 9046 for the Power 6 Westinghouse Gas Turbines before the permit expiration date of July 21, 2010.

III. DENIALS

The Respondent generally denies each allegation in Section II ("Allegations").

IV. ORDERING PROVISIONS

1. It is, therefore, ordered by the TCEQ that the Respondent pay an administrative penalty as set forth in Section I, Paragraph 6 above. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations which are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: The Dow Chemical Company, Docket No. 2010-1450-AIR-E" to:

Financial Administration Division, Revenues Section
Attention: Cashier's Office, MC 214
Texas Commission on Environmental Quality
P.O. Box 13088
Austin, Texas 78711-3088
2. The Respondent shall implement and complete a SEP in accordance with TEX. WATER CODE § 7.067. As set forth in Section I, Paragraph 6 above, Thirty-Eight Thousand Seven Hundred Ninety Dollars (\$38,790) of the assessed administrative penalty shall be offset with the condition that the Respondent implement the SEP defined in Attachment A, incorporated herein by reference. The Respondent's obligation to pay the conditionally offset portion of the administrative penalty assessed shall be discharged upon final completion of all provisions of the SEP agreement.
3. It is further ordered that the Respondent shall undertake the following technical requirements:
 - a. Immediately upon the effective date of this Agreed Order, until such time authorization to operate is obtained, comply with the provisions in expired Standard Permit Registration No. 43417 and NSR Permit No. 9046;
 - b. Within 15 days after the effective date of this Agreed Order, submit an administratively complete permit application for the wet compression equipment and the Power 6 Westinghouse Gas Turbines in accordance with 30 TEX. ADMIN. CODE § 116.110(a) to:

Air Permits Division, MC 162
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

- c. Respond completely and adequately, as determined by the TCEQ, to all requests for information concerning the permit application within 30 days after the date of such requests, or by any other deadline specified in writing; and
- d. Within 180 days after the effective date of this Agreed Order, submit written certification that authorization to operate a source of air emissions has been obtained or that operation has ceased until such time that appropriate authorization is obtained. The certifications shall include detailed supporting documentation including receipts and/or other records to demonstrate compliance, be notarized by a State of Texas Notary Public, and include the following certification language:

"I certify under penalty of law that I have personally examined and am familiar with the information submitted and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing violations."

The certification shall be submitted to:

Order Compliance Team
Enforcement Division, MC 149A
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

with a copy to:

Air Section, Manager
Houston Regional Office
Texas Commission on Environmental Quality
5425 Polk Avenue, Suite H
Houston, Texas 77023-1486

- 4. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Plant operations referenced in this Agreed Order.
- 5. If the Respondent fails to comply with any of the Ordering Provisions in this Agreed Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Agreed Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent


shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.

6. The Executive Director may grant an extension of any deadline in this Agreed Order or in any plan, report, or other document submitted pursuant to this Agreed Order, upon a written and substantiated showing of good cause. All requests for extensions by the Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.
7. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
8. This Agreed Order may be executed in separate and multiple counterparts, which together shall constitute a single instrument. Any page of this Agreed Order may be copied, scanned, digitized, converted to electronic portable document format ("pdf"), or otherwise reproduced and may be transmitted by digital or electronic transmission, including but not limited to facsimile transmission and electronic mail. Any signature affixed to this Agreed Order shall constitute an original signature for all purposes and may be used, filed, substituted, or issued for any purpose for which an original signature could be used. The term "signature" shall include manual signatures and true and accurate reproductions of manual signatures created, executed, endorsed, adopted, or authorized by the person or persons to whom the signatures are attributable. Signatures may be copied or reproduced digitally, electronically, by photocopying, engraving, imprinting, lithographing, electronic mail, facsimile transmission, stamping, or any other means or process which the Executive Director deems acceptable. In this paragraph exclusively, the terms "electronic transmission", "owner", "person", "writing", and "written" shall have the meanings assigned to them under TEX. BUS. ORG. CODE § 1.002.
9. Under 30 TEX. ADMIN. CODE § 70.10(b), the effective date is the date of hand-delivery of the Order to the Respondent, or three days after the date on which the Commission mails notice of the Order to the Respondent, whichever is earlier. The Chief Clerk shall provide a copy of this Agreed Order to each of the parties.

SIGNATURE PAGE

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

For the Commission


For the Executive Director

Date

2/17/2011

I, the undersigned, have read and understand the attached Agreed Order. I am authorized to agree to the attached Agreed Order on behalf of the entity indicated below my signature, and I do agree to the terms and conditions specified therein. I further acknowledge that the TCEQ, in accepting payment for the penalty amount, is materially relying on such representation.

I also understand that failure to comply with the Ordering Provisions, if any, in this order and/or failure to timely pay the penalty amount, may result in:

- A negative impact on compliance history;
- Greater scrutiny of any permit applications submitted;
- Referral of this case to the Attorney General's Office for contempt, injunctive relief, additional penalties, and/or attorney fees, or to a collection agency;
- Increased penalties in any future enforcement actions;
- Automatic referral to the Attorney General's Office of any future enforcement actions; and
- TCEQ seeking other relief as authorized by law.

In addition, any falsification of any compliance documents may result in criminal prosecution.



Signature

1-11-11

Date

Fran Falcon

Name (Printed or typed)
Authorized Representative of
The Dow Chemical Company

EH&S Leveraged Delivery Leader

Title

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenues Section at the address in Section IV, Paragraph 1 of this Agreed Order.

Attachment A
Docket Number: 2010-1450-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent: The Dow Chemical Company

Penalty Amount: Seventy-Seven Thousand Five Hundred Eighty Dollars (\$77,580)

SEP Offset Amount: Thirty-Eight Thousand Seven Hundred Ninety Dollars (\$38,790)

Type of SEP: Pre-approved

Third-Party Recipient: Brazoria County – *Brazoria County Vehicle and Equipment Program*

Location of SEP: Brazoria County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative Penalty Amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Offset Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

a. Project

The Respondent shall contribute the SEP Offset Amount to the Third-Party Recipient named above. The contribution will be used by **Brazoria County** for the *Brazoria County Vehicle and Equipment Program* as set forth in an agreement between the Third-Party Recipient and the TCEQ. The Third-Party Recipient shall use SEP Funds to: 1) retire current diesel powered or gasoline-powered vehicles and equipment and replace those vehicles and equipment with alternative-fueled or low-emission vehicles or equipment; 2) convert current vehicles and equipment to alternative-fueled vehicles or equipment; or 3) retrofit current gasoline-powered and diesel-powered vehicles and equipment to decrease emissions from those sources. *SEP Funds may only be used for: 1) the incremental costs of purchase of alternative-fueled or lower emission vehicles or equipment or retrofit of existing vehicles or equipment; 2) the incremental cost of purchase of alternative fuels versus regular gasoline or diesel fuels; or 3) other direct expenses authorized in advance and in writing by TCEQ.*

Retirement of Vehicles. The Third-Party Recipient shall submit proof that any purchase of new vehicles or equipment using SEP Funds meets current EPA low-emission standards. The Third-Party Recipient shall ensure that equipment and vehicles being retired are operational and that vehicles have current registration stickers. The retired vehicles and equipment must not be resold for any use except scrap value. The engine and exhaust system, including the catalytic

converter, must be destroyed. The Third-Party Recipient shall submit proof of registration, decommissioning, and scrappage by an authorized vehicle dismantler for all retired vehicles and equipment.

Retrofits and Conversions. The Third-Party Recipient shall submit proof that all conversions or retrofits meet current EPA low-emission standards. Retrofitting, in this context, means installing devices to reduce exhaust emissions that are verified or certified by the U.S. Environmental Protection Agency ("EPA") or the California Air Resources Board ("CARB") as proven retrofit technologies. All replacement engines must be certified or verified by the EPA or CARB.

When purchasing alternative-fueled vehicles or equipment, The Third-Party Recipient shall purchase only those types of equipment that use fuels that are available for purchase within 15 miles of its fleet operation area. Alternative-fueled technologies may include propane or electric-powered lawn mowers, propane-powered light duty vehicles and heavy equipment, propane-powered generators, and other technologies or alternative fuels as described below. The Third-Party Recipient may utilize any of the following fuel technologies if the fuel is available for purchase within 15 miles of its fleet operation area:

Alternative Fuels: Use of alternatives fuels is limited to this list of fuels which are defined as alternative fuels by the Energy Policy Act of 1992 and are currently, or have been, commercially available for vehicles: Biodiesel (if used in an area not designated as ozone non-attainment or near non-attainment), electricity, ethanol, hydrogen, methanol, natural gas and propane. Other fuels that are currently under development may be approved for use at the discretion of the TCEQ staff.

b. Environmental Benefit

Replacement of gasoline and diesel powered lawn mowers, heavy equipment, and vehicles with lower-emission items will reduce air pollution emissions of particulate matter (PM), volatile organic carbon (VOC) compounds, nitrogen oxides (NOx), and other pollutants associated with the combustion of fuel that would have been generated by the older replaced item. Use of alternative fuels combined with energy efficiency modifications results in a direct reduction in the amount of emissions that contribute to air pollution in this state.

The Respondent certifies that it has no prior commitment to make this contribution and that it is being done solely in an effort to settle this enforcement action.

c. Minimum Expenditure

The Respondent shall contribute at least the SEP Offset Amount to the Third-Party Recipient and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Offset Amount to the Third-Party Recipient. The Respondent shall mail a copy of the Agreed Order with the contribution to:

Brazoria County Parks Department
313 W. Mulberry
Angleton, Texas 77155

3. Records and Reporting

Concurrent with the payment of the SEP Offset Amount, the Respondent shall provide the TCEQ SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Offset Amount to the Third-Party Recipient. The Respondent shall mail a copy of the check and transmittal letter to:

Litigation Division
Attention: SEP Coordinator, MC 175
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this SEP in any way, including full expenditure of the SEP Offset Amount and submittal of the required reporting described in Section 3 above, the Executive Director may require immediate payment of all or part of the SEP Offset Amount.

In the event of incomplete performance, the Respondent shall include on the check the docket number of this Agreed Order and a note that it is for reimbursement of a SEP. The Respondent shall make the payment for the amount due to "Texas Commission on Environmental Quality" and mail it to:

Litigation Division
Attention: SEP Coordinator, MC 175
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent must include a clear statement that the project was performed as part of the settlement of an enforcement action brought by the TCEQ. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP Offset Amount identified in this Agreed Order has not been, and shall not be, included as a SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.